

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21003588/Gtf3e2
	8 SHENTON WAY TOWERSINGAPOR	_		Date:	01/04/2021
	ATTN : YU DOMINI	IC YISHAN		Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 3426K	Veh. Inspected	d t	SMU 6843E
	Policy No.	VFX/P2419138	Coverage (\$)		0.00
	Claim No.	S1M035PR	Excess (\$)		0.00
	Assign From	YU DOMINIC YISHAN	Assign Date		19/03/2021
2.	Vehicle Particulars & Condition				
	Make & Model	RENAULT GRAND SCENIC IV	c.c		1461
	Engine No.	HIDDEN	Year of Reg.		2020
	Chassis No.	VF1RFA00X63926181	Colour		BLUE
	Odometer	32916 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/55 R20	MICHELIN		6 mm
	L/H Front Tyre	195/55 R20	MICHELIN		6 mm
	R/H Rear Tyre	195/55 R20	MICHELIN		6 mm
	L/H Rear Tyre	195/55 R20	MICHELIN		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
5.	General Information				
	Accident Date	16/03/2021	Inspect Date /	Time	19/03/2021 (05:35 PM)
	Survey held at	AUTO CITY PTE LTD			
	32 KAKI BUKIT CRESCENT SINGAPORE 416262				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				

Report Ref No. CS3/ASM21003588/Gtf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor