

108/11/13 wef
ASS. REC. BY: JASUL

REF:

CS/A1621003590/R1183

4996

ASSIGNMENT

COPIRY: 2022/MAR

From: Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: FBB3982L

at Workshop m/s HUA CHIN

of SP, BUKIT BARU ST 23 #02-02

Insured: ALH

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 2K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBB3982L Yr Regn: 2007 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: YAMAHA T135 c.c. 135

Colour: MULTI A/C: Insured / Std / NI / NA

Sp. Reading: 36706 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 54P718051

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/19-17

R: 80/19-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXXIS

Front Rear

R/Bal. 3 mm R/Bal. 3 mm

L/Bal. mm L/Bal. mm

D.O.A. 13/03/21 D.O.I. 19/03/21

Survey held at HUA CHIN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair limit - 500

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

___ \$ + RS, ___ \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))



SINGAPORE POLICE FORCE



T/20210316/7021

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20210316/7021

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/03/2021 16:06	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: MOHAMMAD FADZLI BIN WAHID			Address: 113 BEDOK NORTH STREET 2 #04-274 SINGAPORE 460113		
ID Type / ID No.: NRIC NO / S8722499F			Contact No.: Home/Office: Mobile: 89290219		
Nationality: SINGAPORE CITIZEN			Email: FADZLIWAHID26@GMAIL.COM		
Sex: Male	Age: 33	Date of Birth: 26/07/1987	Type of Informant: Rider		
Race: Malay			Language: English		Institution / School Name:
Occupation: Painter			Driving Licence Information: Class: 2B Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 13/03/2021 08:30	Type of Location: Straight Road
Location: BEDOK SOUTH AVENUE 3				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 50 Km/h	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Moving Vehicle Against - Others				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of
FBB3982L	Motorcycle	YAMAHA	T135	White		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBB3982L	NTUC Income Insurance Co-Operative Limited	5115160056-01	30/12/2020	29/12/2021



**SINGAPORE
POLICE FORCE**



T/20210316/7021

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20210316/7021

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	MOHAMMAD FADZLI BIN WAHID	ID No.	S8722499F
Related Vehicle	FBB3982L (Motorcycle)	Contact No.	89290219
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry	Class: 2B Date of Expiry: NIL
Date	13/03/2021	Date	16/03/2021
No. of Days granted Medical Leave	64	Degree of	Serious

Brief Details.

On the 13/3/2021, I was riding my motorcycle Fbb3982L on the extreme left lane at Bedok south ave 3 proceeding towards Bedok Mall. As I was traveling on the left turn only lane. All of a sudden a motocar No. SML3519J who was on going straight lane beside my lane abruptly without giving me any way or signal cuts into my lane when I had the right of way collided onto my motorcycle causing me to fall down & suffer serious injuries. I was then taken to Changi general hospital & was given 64 days MC



**SINGAPORE
POLICE FORCE**



T/20210316/7021

3 of 3

Report No. T/20210316/7021

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
PHUA TIAK YEE
Contact No.: 65472077

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
16/03/2021 16:06

Classification Of Case:

Date: 09/11/21
Click to OneMotoring
Acquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC
Owner ID: 499F

Vehicle No.: FBB3982L
Vehicle to be Exported: No
Intended Deregistration Date: 22 Mar 2021
Vehicle Make: YAMAHA
Vehicle Model: T135
Primary Colour: White
Manufacturing Year: 2007
Engine No.: 5YP718051
Chassis No.: 5YP718051
Maximum Power Output: -
Open Market Value: \$1,725.00
Original Registration Date: 23 Mar 2007
First Registration Date: 23 Mar 2007
Transfer Count: 4
Actual ARF Paid: \$259.00

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

COE Expiry Date: 22 Mar 2022
COE Category: D - Motorcycle
COE Period(Years): 5
PQP Paid: \$3,128.00
COE Rebate Amount: \$1,460.00
Total Rebate Amount: \$1,460.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Mar 2021

OK