

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.



ACCIDENT STATEMENT

Date Of Report	16/04/2019 15:31
Date Of Accident	13/04/2019 00:30
Exact Location Of Accident	ALONG RIVER VALLEY RD NEAR TO CLARK QUAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS9962X
Insured/Policyholder	
Name Of Registered Owner	LENG CHUEN LING
NRIC No	S8008284C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-86301588
Alternative Phone No	OFFICE-86301588

Vehicle Particulars

Manufacturer	KIA
Model	-

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken REPORTING ONLY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z18VP05020207
Cover Note Number	

Driver

Name of Driver	TOH HUI LONG
NRIC No	S8513330F
Date Of Birth	02/05/1985
Occupation	INDOOR
Date Of Driving Pass	20/01/2017
Driving Experience	2 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86301588
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	-
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - BOYFRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer attached report.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC5284G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJT3611T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

Along River Valley Road Near To Clark Quay


Vehicle A: SSS 9962X		Lane 1
Vehicle B: BLC 5384G		
Vehicle C: SST 3611T		


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On the stated date and time, vehicle A was traveling along River Valley Road on lane 1 and did not manage to brake in time. It collided onto vehicle B

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/04/2019 10:25
Date Of Accident	13/04/2019 00:30
Exact Location Of Accident	ALONG RIVER VALLEY ROAD NEAR TO CLARK QUAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC5284G
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	ASCEND COM PTE LTD
Co Reg No	199802692H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93887275

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	19MT102359-R01
Cover Note Number	

Driver

Name of Driver	POH HOCK HENG JACKSON
NRIC No	S8426532B
Date Of Birth	23/09/1984
Occupation	INDOOR
Date Of Driving Pass	01/09/2008
Driving Experience	10 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93887275
Fax Number	
Contact Number	
Email Address	NOEMAIL

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage


No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

Along River Valley Road Near To Clark Quay

Vehicle A: SLK 5284G
Vehicle B: SSS 9962K
Vehicle C: GST 3611T



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Ref Police Report - T/20170413/2169

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

CITY AUTO PTE LTD

Blk 8 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 575643
Tel: 6453 4234 Fax: 6453 7944
(Claims Section)



SINGAPORE POLICE FORCE



T/20190413/2169

1 of 4

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

Report No. T/20190413/2169

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/04/2019 23:13		Vide Report No.:		Station Diary No.: 155	
Informant's Particulars					
Name of Informant: POH HOCK HENG, JACKSON			Address: APT BLK 672C YISHUN AVENUE 4 #12-568 SINGAPORE 763672		
ID Type / ID No.: NRIC NO / S8426532B			Contact No.: Home/Office: Mobile: 93887275		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 34	Date of Birth: 23/09/1984	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: PROJECT MANAGER			Driving Licence Information: Class: 2B,2A,3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 13/04/2019 00:35	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 RIVER VALLEY ROAD ALONG RIVER VALLEY ROAD NEAR TO CLARKE QUAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJS9962X	Car	KIA	FORTE	Maroon	Slightly Damaged	1
SJT3611T	Car	TOYOTA	VIOS	Blue	Slightly Damaged	1
SLC5284G	Car	HONDA	VEZEL	Black	Slightly Damaged	4

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date



**SINGAPORE
POLICE FORCE**



T/20190413/2169

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

3 of 4

Report No. T/20190413/2169

CONTINUATION OF REPORT

Brief Details.

On 13/04/2019 at about 12.28am, while I was driving along River Valley Road on Lane 1, all of a sudden the car in front of me (SJT3611T) applied his brakes. I managed to brake on time and did not hit the car in front of me. About 3-5 seconds later, the car behind me (SJS9962X) hit the rear of my vehicle. Due to the collision, my car jerked to the front causing my car to hit onto the rear of the front vehicle.

My vehicle sustained dents and scratches on the frontal and rear area. No ambulance and police were at scene. No vehicle was towed. The 2 vehicles that were involved in the accident had exchanged particulars with me for insurance claim purposes. I am lodging this report for insurance claim purposes only.



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To: Ascend Com Pte Ltd
C/o: 160 Sin Ming Drive #05-16
Sin Ming AutoCity (S) 575722

Date of report: 28.05.2019
Date of request: 16.04.2019
Date of inspection: 16.04.2019
Date of accident: 13.04.2019
Claim type: Third Party Claim

Report No: AAS/2019/189

Particulars of affected vehicle:

Registration no: SLC5284G
Make/Model: Honda Vezel (A)
Year of registration: 2015/16
Colour: Metallic Black

Odometer: 113422 km
Engine Capacity: 1496 cc
Engine no: L15B4028001
Chassis no: RU11108000

Condition of tires:

Front Left: 4mm
Make: Dunlop
Rear Left: 5mm
Make: Dunlop

Front Right: 4mm
Make: Dunlop
Rear Right: 5mm
Make: Dunlop

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: In order
Footbrake	: In order
Steering	: In order
Apparent engine modification	: Nil

The Assignment

The inspection was conducted at M/s. Toh Motor Enterprise
160 Sin Ming Drive #05-16
Sin Ming AutoCity (S) 575722

(Subsequent inspection was conducted)

Assessment

Repairer's estimate:	\$ 18,390.00
Revised estimate:	\$ 14,389.92
Recommended reserve:	\$ 11,500.00 (Lump sum)

Estimated normal duration of repairs : 14 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: SLC5284G

Report No: AAS/2019/189

W/O PREJUDICE

Point of impact

At the front and rear portion.

General description of damages

The front bumper, front bumper lower spoiler, front grille, tailgate, tailgate lamps, tail lamps, rear bumpers, rear end panel, floor panel, rear chassis members, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Toh Motor Enterprise as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$14,389.92

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$11,500.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 14 working days.

I have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 178 photographs.

Your Faithfully
Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SLC5284G

Report No: AAS/2019/189

Appraisement Schedule

S/N	Parts Description	Qty	Condition		Repairer's Est	Revised Est
1	Front bumper	1	Dented		\$ 559.80	\$ 559.80
2	Front bumper lower grille	1	Serviceable		\$ 260.00	-
3	Front bumper lower spoiler	1	Dented/Grazed		\$ 481.00	\$ 481.00
4	Front bumper fog lamp LH/RH	2	Serviceable	\$ 285.85	\$ 571.70	-
5	Front bumper fog lamp grille LH/RH	2	LH Cracked	\$ 89.60	\$ 179.20	\$ 89.60
6	Front bumper retainer LH/RH	2	Cracked	\$ 41.70	\$ 83.40	\$ 83.40
7	Front bumper support LH/RH	2	Cracked	\$ 45.70	\$ 91.40	\$ 91.40
8	Front bumper reinforcement	1	Necessary		\$ 361.50	\$ 361.50
9	Front grille	1	Cracked		\$ 542.20	\$ 542.20
10	Front grille outer moulding	1	Serviceable		\$ 385.00	-
11	Front grille side chrome LH/RH	2	Not Necessary	\$ 108.00	\$ 216.00	-
12	Front grille emblem	1	Not Necessary		\$ 58.80	-
13	Front grille support	1	Not Necessary		\$ 139.50	-
14	Tailgate	1	Dented		\$ 1,370.00	\$ 1,370.00
15	Tailgate glass moulding (top)	1	Necessary		\$ 58.00	\$ 58.00
16	Tailgate glass moulding (lower)	1	Necessary		\$ 58.00	\$ 58.00
17	Tailgate outer garnish	1	Cracked		\$ 560.00	\$ 560.00
18	Tailgate emblem	1	Necessary		\$ 38.00	\$ 38.00
19	Tailgate nameplate 'Vezel	1	Necessary		\$ 55.00	\$ 55.00
20	Tailgate lamp LH/RH	2	Grazed/Cracked	\$ 321.00	\$ 642.00	\$ 642.00
21	Tailgate lock	1	Distorted/Jammed		\$ 181.00	\$ 181.00
22	Tailgate striker	1	Distorted		\$ 42.00	\$ 42.00
23	Tailgate lifter LH/RH	2	Serviceable	\$ 190.00	\$ 380.00	-
24	Tailgate inner trim	1	Cracked		\$ 541.00	\$ 541.00
25	Tailgate weather-strip	1	Necessary		\$ 178.00	\$ 178.00
26	Tailgate buzzer	1	Cracked		\$ 93.00	\$ 93.00
27	Tail lamp LH/RH	2	Cracked	\$ 653.00	\$ 1,306.00	\$ 1,306.00
28	Rear bumper	1	Dented		\$ 820.00	\$ 820.00
29	Rear bumper side LH/RH	2	Dented/RH Repair	\$ 272.00	\$ 544.00	\$ 272.00
30	Rear bumper reflector LH/RH	2	Grazed/Cracked	\$ 71.00	\$ 142.00	\$ 142.00
31	Rear bumper retainer LH/RH	2	Cracked	\$ 55.00	\$ 110.00	\$ 110.00
32	Rear bumper undercover	1	Deformed		\$ 260.00	\$ 260.00
33	Rear fender inner trim LH/RH	2	Deformed/Cracked	\$ 640.00	\$ 1,280.00	\$ 1,280.00
34	Rear fender arch moulding LH/RH	2	Cracked	\$ 178.00	\$ 356.00	\$ 356.00
35	Rear end panel	1	Dented		\$ 650.00	\$ 650.00
36	Rear end panel trim	1	Deformed		\$ 92.00	\$ 92.00
37	Floor panel	1	Dented/Distorted		\$ 1,130.00	\$ 1,130.00
38	Floor panel cover	1	Serviceable		\$ 290.00	-
39	Tow hook	1	Necessary		\$ 207.00	\$ 207.00



ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0418 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SLC5284G

Report No: AAS/2019/189

Total:	\$ 15,312.50	\$ 12,649.90
-20%	\$ 3,062.50	\$ 2,529.98
List total:	\$ 12,250.00	\$ 10,119.92

1	Front bumper clips	1set	Necessary	\$ 50.00	\$ 30.00
2	Tailgate glass sealant	1	Necessary	\$ 60.00	\$ 40.00
3	Reverse camera	1set	Serviceable	\$ 380.00	-
4	Rear bumper clips	1set	Necessary	\$ 50.00	\$ 30.00
5	Reverse sensor	1set	Cracked/Dislodged	\$ 280.00	\$ 250.00
6	Joint sealant	2	Necessary	\$ 60.00	\$ 80.00

Special nett total:	\$ 940.00	\$ 430.00
---------------------	-----------	-----------

Parts Total:	\$ 13,190.00	\$ 10,549.92
--------------	--------------	--------------

S/N	Labour Description	Repairer's Est	Revised Est
1	To check front lightings & wirings.	\$ 50.00	\$ 30.00
2	To remove and renew front damaged parts. Re-align all affected area.	\$ 400.00	\$ 250.00
3	To putty and respray all front damaged parts. Touch up all affected area.	\$ 300.00	\$ 200.00
4	To check rear lightings & wirings.	\$ 50.00	\$ 30.00
5	To transfer tailgate glass.	\$ 200.00	\$ 180.00
6	To transfer tailgate fittings.	\$ 120.00	\$ 80.00
7	To transfer reverse camera.	\$ 100.00	\$ 60.00
8	To renew reverse sensor.	\$ 80.00	\$ 50.00
9	Rust proofing on rear affected panels..	\$ 100.00	\$ 60.00
10	To remove and renew rear damaged parts. Re-align all affected area.	\$ 1,800.00	\$ 1,500.00
11	To putty and respray all rear damaged parts. Touch up all affected area.	\$ 2,000.00	\$ 1,400.00

Labour Total:	\$ 5,200.00	\$ 3,840.00
---------------	-------------	-------------

Grand Total:	\$ 18,390.00	\$ 14,389.92
--------------	--------------	--------------

The final adjusted lump sum amount is \$11,500.00

Under normal circumstances, the repair should be completed within a reasonable period of 14 working days.

178 Photographs were taken at the time of inspection.

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.