

ACC. REC. BY:

Steve

REF:

AIG

CS/AIG21003673/Etd3

ASSIGNMENT

SMY31730

Yr Regn:

26/2/21

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

7210020407

Policy No.

Claims No. 6875039258SG

Sum Insured:

Excess:


0

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Sum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Attrage

c.c

1193

Colour:

Grey

A/C:

Insured / Std / NI / N

Sp. Reading

559

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

MMOSTA JAMH 002993

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brakes: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size:

F:

185 / 55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

4

mm

Rear

R/Bal.

4

mm

U/Bal.

4

mm

U/Bal.

4

mm

D.O.A.

21/3/21

D.O.I.

22/3/21

Survey held at

Cycle & Carriage

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-71K

Confirm final figure @ \$12,228.71 before GST

red:3045.84:19%

File Time, File Pass to?



: Prel. Report



: Final Report

File Time, File Return to?

Days Of Repair: 17

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (%)



: Weekend (\$

Formal:

12,228.71

imp Sum / L.E. / %