

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 13.03.2021

Time: 12:48:13

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305458099
REGN NO : SHA 903U
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4A)
DATE OF REGN : 14.01.2020
DATE/TIME IN : 12.03.2021 16:40
ACCIDENT DATE : 12.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2712-G	COVER REAR BUMPER	1 L	499.90	25.00	374.92	x repair
0002 04-01-0302-2288-G	REINFORCEMENT SUB-ASSY RE	1 L	318.80	25.00	239.10	?
0003 04-01-0302-2267-G	BUMPER PIECE	10 L	22.00	25.00	16.50	MC
0004 04-01-0302-2713-G	GUARD REAR BUMPER CENTER	1 L	552.60	25.00	414.45	re
0005 04-01-0302-2286-G	COVER REAR BUMPER-TOW HOO	1 L	82.70	25.00	62.02	re
0006 04-01-0302-2723-G	REFLECTOR ASSY RH	1 L	55.00	25.00	41.25	?
0007 09-01-0302-2005-A	REVERSE SENSOR ASSY	1 N	135.70	2.50-	135.70	X
0008 04-01-0302-1150-A	BUMPER PROTECTOR MAT	1 N	50.00	0.25	50.00	X
0009 04-01-0302-2270-G	PLATE-BACK DOOR NAME (HYBRID)	1 L	52.40	25.00	39.30	X
0010 04-01-0302-3909-G	PANEL SUB-ASSY QUARTER RH	1 L	836.70	25.00	627.52	X

SUB-TOTAL : 2,000.76

JOB NATURE

0000 20-05 RENEW ADVERTISEMENT STICKER-

50.00

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305458099
 REGN NO : SHA 903U
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID
 DATE OF REGN : 14.01.2020
 DATE/TIME IN : 12.03.2021 16:4
 ACCIDENT DATE : 12.03.2021

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 L	PANEL BEATING	900.00		350		
0002 23-502	SPRAYPAINT ON AFFECTED AREA	550.00		250		
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00		X		
0004 20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR	120.00		X		
0005 L	REMOVE/REFIX REVERSE SENSOR	120.00		40		
SUB-TOTAL :						1,790.00
TOTAL :						3,790.76

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

2 Days.
 8/P
 before / After paint photos
 Guo Qiang
 15/3/21

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: