COMFO	RTDELGRO
ENGINEE	RING
ComfortDelGro	Engineering Pte Ltd
59 Loyang Drive	e Singapore 508969
Fax: 6546 8156	
Fax ·	

Our d Date	Job Re	f No : 305459854 : 25/03/21	ENGINEERING ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969			
FINA	LIZAT	ION FORM	Fax: 6546	• •		
То	: :	LKK	Fax :			
Attn	:	TAUFIKH				
Vehic	cle Reg	9 No. : SHC8400R	Date of Accident :_	21.03.21		
The	survey	and estimates of the repairs of the above-	mentioned vehicle are as	follows:-		
1.	The	repair job shall bill to: TOKIO N	MARINE	SJP1301Y		
2.	The f	inalized amount shall be:				
	(a)	Spare Parts after List discount				
	(b)	Labour Charges				
		Total for Part-By-Part Repair Cost		89		
	(c.)	Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less Final Lumpsum Repair cost	:: <u>20%</u>	\$1,500.00 \$1,500.00		
3.	Estim	ated normal period for repairs:	2working days.			
4.		hall treat the above amount as Correct and 7 working days	and Confirmed if there is	no reply from you		
5.	Thanl	k you for your assistance.	We confirm the estimates and finalized amount			
	Signa		Signature :7	taufikh TAUFIKH		
	Tel	62148398	V	6/4/21		
	Fax	65468156	*** d			

For Official Use Only

ltem	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
Rental Rate P/Day		YES		
2. Loss of Income Paid	2025	N		
3. Survey Fees		(41)		
4. LTA Search Fee	\$7.49 /\$2.00			
Medical Fees (on behalf of driver, if applicable)			_	
6 Overrun				

Remarks	*			
	-			