

VEHICLE DAMAGE INSPECTION REPORT

Our File No: S8188-1503T-TJ
Date: 25/07/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MX001745		
Claimant Vehicle No :	SLD8228U	Insured Vehicle No :	SKJ3251P		
Date of Loss:	13/03/2018	Nature of Claim:	TP	Claim No:	M1801403

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD8228U	Engine No:	27186030636200
Make & Model:	AUDI A6, 2.0 TFSI MU (A)	Chassis No:	WDD2120482A758307
Reg. Date:	27/11/2011 (Man. Year: 2011)	Odometer:	99225 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Goodyear 4 mm	Rear Left Side:	Goodyear 4 mm
Front Right Side:	Goodyear 4 mm	Rear Right Side:	Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	40.00	-40.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	20.00	-20.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	60.00	-60.00	

INSPECTION

Date of Assignment:	15/03/2018		
Date Inspected:	19/03/2018, 20/03/2018, 21/03/2018	Inspected At:	Wahyu Automotive Body Work (Sin Ming) 176 Sin Ming Drive, #05-09 Singapore 575721
Estimated Period of Repair:	0.5 days		

Adjuster: Melvin Lum

Manager: Melvin Lum

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jul 2018)
Parts:	143	AUDI A6 2.0 TFSI MU (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Koays Accident Reconstruction Pte Ltd/SLD8228U/25/07/2018 02:30	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Accident Parts (see attached)		-	*40.00 F
F=Franchise part.						
Total Parts (S\$)					0.00	40.00

Koays Accident Reconstruction Pte Ltd/SLD8228U/25/07/2018 02:30. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Labour & Materials	New	-	20.00
Gross Labour Cost (S\$)			0.00	20.00

Koays Accident Reconstruction Pte Ltd/SLD8228U/25/07/2018 02:30. Not valid without Reference section.

< END OF ESTIMATES >