

12/02/2020

REF: CS3/AIG21003687/f3

Special Instruction:

ASS. REC. BY:

ASSIGNMENT (Office)

SURVBY

Merimen

From (Person): DIVYASHNI

of AIG

Date/Time: 22/03/2021@2.33PM

Estimated Cost: Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBE 1029L

Insured: SMW 595A

at Workshop m/s ALPHA CAR SERVICE

Tel: 6509 8258

of 1 Kaki Bukit Ave 6 # 01-59

Policy No: Claim No: 8877543150SG003

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 07/01/2021

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time 3.26pm@22/03/2021

Person Contacted: CAI LING

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	GBE 1029L-CC4/LPC16006947/Khb3q2 DOA : 06/04/2016
	SMW 595A-X