

REC. BY: Steve

ALIA CS/AIG21003688/ETF3N2


ASSIGNMENT

Yr Regn: 21/3/19

From: _____ Date: _____
 Estimated Cost: _____
 TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. 1900062756
 Claims No. 8035187959SG
 Sum Insured: _____ Excess: 0
 (Client's Record)
 Make of Veh: _____

Veh No: SMJ 7982M
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mitsubishi Attrage c.c. 1793
 Colour: Red A/C: Insured / Std / Nil / N
 Sp. Reading: 54320 T/Radio: Insured / Std / Nil / N
 Eng/No: _____
 C/No: MMIBSTAB3AKH991149
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/55R15
 R: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 SIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Cum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front R/Bal. 5 mm
 L/Bal. 5 mm
 D.O.A. 22/3/21
 Survey held at cycle & Carriage
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>MV-58K</u>
	Confirm final figure at \$15286.94, 14days before gst
	RED: 3366.66: 18%

File/Time, File, Pass to? Prel. Report
 Final Report

Days Of Repair: 14
 Resurvey No. of Trip: 1

Survey Fee:	
Transportation:	
\$ + RS, SI	
Police	
Others	
TOTAL	

Add Fee: Site Insp (\$ _____)
 Interview (\$ _____)
 Tech. Invs (\$ _____)
 Wheel and (\$ _____)

TP
 15286.94