

ASS. REC. BY:

REF: CS3/ASM21003698/R1qf3

Special Instruction:

Surveyor: RASUL

ASSIGNMENT (Office)

From (Person): TAN JUN HONG of AXA Date/Time: 22/3/2021 2:00 PM

Estimated Cost: Bill to:

OD ☒ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJA 6216G Insured: SHA 3147R

at Workshop m/s RIGHT CLICK AUTOWORKS Tel: 8783-5544

of 7 SOON LEE ST, ISPACE, #01-27 SINGAPORE 627608

Policy No: Claim No: S1M035U9

Sum Insured: Excess:

Make of Veh: D.O.A. 18-03-21
(Client's Record)

CA / REV / REP. / REV 24 HRS WP"

H.O.D. Endorsement:

Date/Time: 22-0.3-21 6.13P.M Person Contacted: SIMON Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	SJA 6216G- ☒
	SHA 3147R - CS/MSG16005297/H1vh3n2 DOA :19/03/2016