



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556  
ATTN: DAVID PHUA

Ref: CS/INC21003721/Atf3n2

Date: 30/04/2021

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 3503K	Veh. Inspected	SLN 4593M
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1125251-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	22/03/2021

### 2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU11110262	Colour	MAROON
Odometer	55765 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	FALKEN	6 mm
L/H Front Tyre	215/60 R16	FALKEN	6 mm
R/H Rear Tyre	215/60 R16	FALKEN	6 mm
L/H Rear Tyre	215/60 R16	FALKEN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	23/03/2021	Inspect Date / Time	23/03/2021 ( 11:00 AM )
Survey held at	CN MOTORS PTE LTD 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **9 Working Days**