



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO21003727/AUtf3n2 Date: 21/04/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMU 1136X	Veh. Inspected	GBB 9414X
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2100891/RUC	Excess (\$)	0.00
Assign From	MELVIN YE	Assign Date	22/03/2021
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JN1YBAM20U0003007	Colour	SILVER
Odometer	154746 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/70 R14	DUNLOP	6 mm
L/H Front Tyre	185/70 R14	DUNLOP	6 mm
R/H Rear Tyre	185/70 R14	DUNLOP	6 mm
L/H Rear Tyre	185/70 R14	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/03/2021	Inspection Date	23/03/2021
Survey held at	RYDER AUTO WORKSHOP LLP 2 Kaki Bukit Ave 2# 02-19 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	