

ASS. REC. BY:

REF:

LPC / 21003732/Kb

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP / 24 HRS

Date: 06/23 Person Contacted: _____ Vehicle: IN / OUTVeh No: STF 79315 Yr Regn: 06, 08Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: NIS Latio c.c. 1800Colour: White A/C: Insured / Std / NI / NASp. Reading: 208249 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1BAAC118009322Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rim / STD A/Rim orTyre Size: F: 195/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 20/3/21

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Survey Fee:

Transportation:

S - RS - SI

F. Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

TSAO SU HUA @ CINDY TSAO
141 JALAN BATALONG EAST
SINGAPORE 509633

File No : SH/2021/025103/008/TP

Date : 23-March-2021

Not Authorized

6 days Repair After Paint

Estimated cost of repair for vehicle no : **SJF7931S** Model **NISSAN LATIO**
Accident involving vehicle no: **SJF7931S** & **GBA610K** on **20.03.2021**

Description	Quantity	Cost Price
Rear boot	1	\$ <i>R</i> 280.00 ✓
Rear boot emblem	1	\$ <i>na</i> 40.00 ✓
Rear boot badge "Latio"	1	\$ <i>na</i> 50.00 ✓
Rear boot chrome moulding	1	\$ <i>CM</i> 95.00 ✓
RH Rear boot hinge	1	\$ <i>R</i> 55.00 ✗
LH Rear boot hinge	1	\$ <i>R</i> 55.00 ✗
Rear boot spoiler	1	\$ <i>CM</i> 160.00 ✓
Rear boot inner lock	1	\$ <i>na</i> 125.00 ✓
Rear boot weatherstrip	1	\$ <i>DIY</i> 65.00 ✓
Rear bumper	1	\$ <i>na</i> 260.00 ✓
Rear bumper clips (1 set)	1	\$ <i>na</i> 16.00 ✓
Rear bumper spoiler	1	\$ <i>na</i> 280.00 ✓
Rear bumper spoiler rubber seal	1	\$ <i>na</i> 35.00 ✓
RH Rear bumper retainer	1	\$ <i>DIY</i> 38.00 ✓
LH Rear bumper retainer	1	\$ <i>DIY</i> 38.00 ✓
Rear end panel	1	\$ 180.00 ?
Rear end panel top trim	1	\$ <i>na</i> 80.00 ✓
RH tail lamp	1	\$ 110.00 ?
LH tail lamp	1	\$ 110.00 ?
		\$ 2,072.00
		Add 15% \$ 310.80
		\$ 2,382.80
Rear number plate	1	\$ <i>na</i> 45.00 ✓
Rear parking sensors	1	\$ <i>short</i> 260.00 2 coin

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out damaged panels, to reweld, reshape and repair LH and RH rear fender and inner panel, to straighten out rear chassis member and adjust rear body and boot alignment.

\$ 680.00 *650*

To spray paint rear bumper, rear boot, rear end panel, LH & RH rear fender, affected rear and inner damaged portion inclusive of preparatory works and materials.

\$ 750.00 *720*

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.

\$ 30.00 ^{20%}

To apply anti-corrosion Tuff-Kote on rewelded seams.

\$ 100.00 ^{60%}

\$ 4,247.80

T/Party: Lonpac Insurance Bhd

Vehicle number: 5037423667-11 SJF 7931S T5A0 Name of policyholder: SU HUA @ CINDY T5A0

To claim for damage I have caused

☒ To make a third party claim

☐ To report my accident only

Date (dd/mm/yyyy)

20/03/2021

Time

1408HRS

Brief description of accident

Type of collision

HEAD INTO REAR

Weather condition

☒ Clear ☐ Raining ☐ Others

Road surface

☐ Wet ☒ Dry ☐ Others

Was the accident reported to the police?
If yes, please state which police station

☐ Yes ☒ No

Details of driver

Name (as shown in NRIC)

T5A0 SU HUA
@ CINDY T5A0

Pass date of driving licence

14/04/1989

NRIC number

S25582620

Contact number

9649 5087

Date of birth (dd/mm/yyyy)

07/01/1958

Email

SUHUAT5A0@YAHOO.COM
-56

Sex

☐ Male ☒ Female

Address

141
EAST

JALAN BATALONG
S'PORE 509633

Is your occupation

☒ indoor? ☐ outdoor?

Purpose for which the vehicle was being used at the time of the accident

☒ Personal ☐ Commercial ☐ Private Hire

Others, please specify:

Relationship to policyholder

PH

Details of passenger(s)

number of passenger(s) including Driver

01

Name of passenger(s)

Sex

☐ Male ☐ Female

☐ Male ☐ Female

☐ Male ☐ Female

☐ Male ☐ Female

Details of the other driver(s) and vehicle(s) involved

Name of other driver (or drivers)

ARUMY GAM

Vehicle number

G6A610K

NRIC number

G3409971K

Contact number

90683079

Injury details

Was anybody injured in this accident?
If yes, please go to the next question.

☐ Yes ☒ No

Name of injured person

Sex

☐ Male ☐ Female

☐ Male ☐ Female

☐ Male ☐ Female

☐ Male ☐ Female

Convey by ambulance

☐ Yes ☐ No

☐ Yes ☐ No

☐ Yes ☐ No

☐ Yes ☐ No

Vehicle number

Contact number

SIMS AVENUE



JALAN EUNUS

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 20/03/2021 at about 1400hrs,
I was driving my vehicle along Jalan
Eunus. I took the left filter lane which
leads to Sims Avenue. There was a bus on
the main road of Sims Avenue thus I had
stopped before the give way line. That's when
a lorry GBA610K collided into the rear of
my vehicle. No one was injured.

DECLARATION

(We declare the foregoing particulars are true in every respect)

Policyholder's Signature

Date & Time: 21/03/2021 12:51 PM

Driver's Signature

(If driver is not the policyholder)

Date & Time: 21/03/2021 12:51 PM

Reporting Centre Personnel's Signature

Name: Sumari Sukuman

NRIC/FIN No.: J8823603C