

ASS. REC. BY:

REF:

LPC / 21003732/kb

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STF 79315 Yr Regn: 06, 08Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS 6010 c.c. 1800Colour: White A/C: Insured / Std / NI / NASp. Reading: 208249 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1BAAC118009322Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: F: 195/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. P mmL/Bal. P mmD.O.A. 20/3/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8/6 11 PM @ 3000h Continued 15/6/21

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$ _____)

Transportation:

☐ : Interview (\$ _____)

S - RS, SI

☐ : Tech Invs (\$ _____)

Fees

☐ : Weekend (\$ _____)

Others

Report Format :

Lump Sum / I.B.I. (\$ _____)

TOTAL

TSAO SU HUA @ CINDY TSAO
141 JALAN BATALONG EAST
SINGAPORE 509633

File No : SH/2021/025/03/008/TP
Date : 23-March-2021

Not Authorized
6 days Repair @ 3000/hr
Repair After Paint

Estimated cost of repair for vehicle no : **SJF7931S** Model **NISSAN LATIO**
Accident involving vehicle no: **SJF7931S** & **GBA610K** on **20.03.2021**

Description	Quantity	Cost Price
Rear boot	1	\$ <i>R</i> 280.00 ✓
Rear boot emblem	1	\$ <i>na</i> 40.00 ✓
Rear boot badge "Latio"	1	\$ <i>na</i> 50.00 ✓
Rear boot chrome moulding	1	\$ <i>cm</i> 95.00 ✓
RH Rear boot hinge	1	\$ <i>R</i> 55.00 X
LH Rear boot hinge	1	\$ <i>R</i> 55.00 X
Rear boot spoiler	1	\$ <i>cm</i> 160.00 ✓
Rear boot inner lock	1	\$ <i>na</i> 125.00 ✓
Rear boot weatherstrip	1	\$ <i>DIY IR</i> 65.00 ✓
Rear bumper	1	\$ <i>Bu</i> 260.00 ✓
Rear bumper clips (1 set)	1	\$ <i>na</i> 16.00 ✓
Rear bumper spoiler	1	\$ <i>Bu</i> 280.00 ✓
Rear bumper spoiler rubber seal	1	\$ <i>na</i> 35.00 ✓
RH Rear bumper retainer	1	\$ <i>DIY</i> 38.00 ✓
LH Rear bumper retainer	1	\$ <i>DIY</i> 38.00 ✓
Rear end panel	1	\$ <i>R</i> 180.00 X
Rear end panel top trim	1	\$ <i>na</i> 80.00 ✓
RH tail lamp	1	\$ <i>my car</i> 110.00 ✓
LH tail lamp	1	\$ <i>my car</i> 110.00 ✓
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		\$ 2,072.00
		Add 15% \$ 310.80
		\$ 2,382.80
Rear number plate	1	SN \$ <i>na</i> 45.00 ✓
Rear parking sensors	1	SN \$ <i>short</i> 260.00 <i>2 coin</i>

To remove rear damaged parts, to jack out rear end panel and rear floor panel and cut out damaged panels, to reweld, reshape and repair LH and RH rear fender and inner panel, to straighten out rear chassis member and adjust rear body and boot alignment.

\$ *650* 680.00

To spray paint rear bumper, rear boot, rear end panel, LH & RH rear fender, affected rear and inner damaged portion inclusive of preparatory works and materials.

\$ *720* 750.00

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.

\$ 30.00 ^{20%}

To apply anti-corrosion Tuff-Kote on rewelded seams.

\$ 100.00 ^{60%}

\$ 4,247.80

T/Party: Lonpac Insurance Bhd

Motor accident report and claim form

TRAH: AUTO

Policy number: 5037423667-11
 Vehicle number: SJF 7931S
 Name of policyholder: TSAO SU HUA @ CINDY TSAO

Use only for reporting:
☐ To claim for damage I have caused
☒ To make a third party claim
☐ To report my accident only

Date (dd/mm/yyyy): 20/03/2021
 Time: 1408HRS
 Brief description of accident: HEAD INTO REAR
 Type of collision: ☒ Clear ☐ Raining ☐ Others
 Road surface: ☐ Wet ☒ Dry ☐ Others

Location: SLIP ROAD OF JALAN BUNIOS 3 SIMS AVENUE
 Was the accident reported to the police? ☐ Yes ☒ No
 If yes, please state which police station:

Details of driver:
 Name (as shown in NRIC): TSAO SU HUA
 Pass date of driving licence: 14/04/1989
 NRIC number: S25582620
 Contact number: 9649 5087
 Date of birth (dd/mm/yyyy): 07/01/1958
 Email: SUHUATSAO@YAHOO.COM
 Sex: ☐ Male ☒ Female
 Address: 141 JALAN BATALONG 3 POKE 509633
 Is your occupation: ☒ indoor? ☐ outdoor?

Purpose for which the vehicle was being used at the time of the accident:
☒ Personal ☐ Commercial ☐ Private Hire
☐ Others, please specify:
 Relationship to policyholder: PH

Details of passenger(s)		
Number of passenger(s) including Driver: 01		
Name of passenger(s)	Sex	
1	☐ Male	☐ Female
2	☐ Male	☐ Female
3	☐ Male	☐ Female
4	☐ Male	☐ Female

Details of the other driver(s) and vehicle(s) involved			
Name of other driver (or drivers)	Vehicle number	NRIC number	Contact number
1 ARUMUGAM	GBA610K	G3409971K	90683079
2			
3			

Injury details				
Was anybody injured in this accident? ☐ Yes ☒ No				
If yes, please go to the next question				
Name of injured person	Sex	Convey by ambulance	Vehicle number	Contact number
1	☐ Male ☐ Female	☐ Yes ☐ No		
2	☐ Male ☐ Female	☐ Yes ☐ No		
3	☐ Male ☐ Female	☐ Yes ☐ No		
4	☐ Male ☐ Female	☐ Yes ☐ No		

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 262D

Vehicle Details

Vehicle No.: SJF7931S
Vehicle to be Exported: Yes
Intended Deregistration Date: 22 Mar 2021
Vehicle Make: NISSAN
Vehicle Model: LATIO 1.5L T
Primary Colour: White
Manufacturing Year: 2007
Engine No.: HR15253341A
Chassis No.: JN1BAAC11Z0009322
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$15,372.00
Original Registration Date: 11 Jun 2008
First Registration Date: 11 Jun 2008
Transfer Count: 0
Actual ARF Paid: \$15,372.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 10 Jun 2023
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
POP Paid: \$19,107.00
COE Rebate Amount: \$8,478.00
Total Rebate Amount: \$8,478.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Mar 2021

OK