

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21003740/Aqf3n2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924		Date	: 07/09/2021	
			Code	e: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLU 3206B	Veh. Inspected	SMP 3966E	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10009498/ST	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	23/03/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E250	c.c	1796	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	WDD2074472F080143	Colour	RED	
	Odometer	142873 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	245/35 R19	DUNLOP	6 mm	
	L/H Front Tyre	245/35 R19	DUNLOP	6 mm	
	R/H Rear Tyre	245/35 R19	DUNLOP	6 mm	
	L/H Rear Tyre	245/35 R19	DUNLOP	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	20/03/2021	Inspection Date	23/03/2021	
	Survey held at	CAS GARAGE PTE LTD			
		NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: