



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21003742/Gqf3n2	Date: 29/07/2021
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJS 285B	Veh. Inspected	SLK 8716R
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10009319/KY	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	23/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL 1.5X	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	RU11206349	Colour	BROWN
	Odometer	59332 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	MICHELIN	6 mm
	L/H Front Tyre	215/60 R16	MICHELIN	6 mm
	R/H Rear Tyre	215/60 R16	MICHELIN	6 mm
	L/H Rear Tyre	215/60 R16	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/03/2021	Inspection Date	24/03/2021
	Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	