



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL  
(BUDGET DIRECT INSURANCE)  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRESINGAPORE  
239924

Ref: CS/AGI21003747/Avd3n2

Date: 09/06/2021

Code: AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SMP 8418M	<b>Veh. Inspected</b>	SLG 5381M
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	C10009529/ST	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	IVY RATILLA	<b>Assign Date</b>	23/03/2021

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA VEZEL	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	RU11110354	<b>Colour</b>	BLUE
<b>Odometer</b>	76452 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/60 R16	YOKOHAMA	6 mm
<b>L/H Front Tyre</b>	215/60 R16	YOKOHAMA	6 mm
<b>R/H Rear Tyre</b>	215/60 R16	YOKOHAMA	6 mm
<b>L/H Rear Tyre</b>	215/60 R16	YOKOHAMA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	23/03/2021	<b>Inspection Date</b>	23/03/2021
<b>Survey held at</b>	ISHARE AUTO PTE. LTD. 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>9 Working Days</b>
--	-----------------------