


Kenneth

ASSIGNMENT

Front: _____ Date: _____
 Estimated Cost: _____
 OO/TP/WS/TPRES/OO RES/EVA/INV/INV
 To inspect Vehicle No: _____
 at Workshop no: West Auto
 of _____
 Insured: _____
 Policy No: _____
 Claims No: 5274855397SG
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAG Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 4-5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT
Anthony

Veh No: SUH 6705B Yr Regn: 11, 16
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Weapon
 Make: Honda Shuttle C.G. 1996
 Colour: M. Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 204895 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GP 7 104328P
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/60R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 7 mm Rear R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 18/3/21 D.O.I. 22/3/2021
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Kenneth confirmed LS \$3950. (Red \$4007.76, 50%)

Date/Time, File Pass to? : Prel. Report
 : Final Report
 1) 01/04 Typist
 Date/Time, File Return to?

Days Of Repair: 5
 Resurvey No. of Trlp: 1

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S - RS - SI _____

 TOTAL

Report Format: MER-TP
 Lump Sum / L.B. / S 3950

Trust Autoworks

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
 HP 91082728

*Not Notified
 11/11/17
 Meaning After Rain*

Tan Tong Lim
 Blk 163B Rivervale Crescent
 #06-252
 Singapore 542163

Vehicle No : SLH 6705 B
 Make/Model : Honda Shuttle
 Year : 2017

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy		Ry \$1,193.70 ✓
1 pc	Rear tail-gate glass moulding		Mu \$105.20 ✓
1 pc	Rear tail-gate emblem "Shuttle"		Mu \$65.10 ✓
1 pc	Rear tail-gate emblem "Hybrid"		Mu \$57.20 ✓
1 pc	Rear tail-gate outer garnish		Sm \$385.70 X
1 pc	Rear tail-gate inner lock		Mu \$207.80 ✓
1 pc	Rear tail-gate inner trim board		MJ Sm \$287.40 ?
2 pcs	Rear fender inner trim board	015? \$398.60	MJ Sm \$797.20 X
1 pc	Rear boot rubber		Mu \$195.70 50% M
1 pc	Rear end panel		Pr: \$588.60 ?
1 pc	Rear end panel inner garnish		Mu \$185.90 ✓
1 pc	Rear bumper		Mu \$465.70 ✓
2 pcs	Rear bumper side retainer	\$38.20	Sm \$76.40 X
2 pcs	Rear bumper reflector	\$155.20	Sm \$310.40 X
2 pcs	Rear bumper reflector garnish	\$106.70	Sm \$213.40 X
2 pcs	Rear bumper reflector inner sponge	\$87.10	\$164.20 ?
1 pc	Rear antenna		\$125.60 ?
			<u>\$6,573.00</u>
Less 20 %			\$1,314.60
			<u>\$5,258.40</u>

S Nett

1 pc	Rear tail-gate glass sealant		Mu \$55.00 40% M
20 pcs	Rear bumper clip	\$2.00	Mu \$40.00 ✓
1 pc	Rear reverse sensor		Sm \$200.00 X
			<u>\$295.00</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

balance c/f

\$5,553.40

SLH 6705 B

balance b/f \$5,553.40

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,200.00 ?

To putty and spray paint

\$1,200.00 *60d*

Check & reconnect wiring.

\$45.00 *20d*

To respray anti-rust proofing treatment

\$120.00 ?

Remove/refit rear windscreen to facilitate repair

\$100.00 ✓

Remove/refit rear tail-gate mechanism to new door.

\$150.00 *60d*

Remove/refit rear boot upholstery to facilitate repair.

\$100.00 *60d*

Total

\$8,468.40

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 17/03/2021 11:30 (SGT)
Date of Accident 16/03/2021 19:00 (SGT)
Exact Location of Accident Punggol E, Singapore
Additional Location Information TWDS PUNGGOL CENTRAL
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLH6705B

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner TAN TONG LIM (CHEN DONGLIN)
NRIC No SXXXX625G
Email Address PHLP_1022@YAHOO.COM.SG
Mobile Phone No (Phone) +65-82980700
Alternative Phone No +65-82980700

VEHICLE PARTICULARS

Manufacturer Honda
Model Shuttle
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private hire

INSURANCE COMPANY

Name of Insurance Company NTUC
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5103820887-02
Cover Note Number -

DRIVER

Name of Driver TAN TONG LIM (CHEN DONGLIN)
NRIC No SXXXX625G
Date Of Birth 18/06/1979
Occupation Outdoor

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to renewate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature] 17/3/2021

[Signature]

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

