



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:GARNET LOW			Ref: CC4/ASM21003766/Apa3q2 Date: 05/08/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6296G	Veh. Inspected	SMK 6417E	
Policy No.	P2419138	Coverage (\$)	0.00	
Claim No.	S1M03634	Excess (\$)	0.00	
Assign From		Assign Date	23/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MNTBBAB17Z0034931	Colour	SILVER	
Odometer	21500 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/60 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/60 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/03/2021	Inspection Date	23/03/2021	
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			13 Working Days	