

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERA	L INSURANCE (S) PL	Re	ef:	CS/AGI21003778/Uvf3n2
190 CLEMENCEA	J AVENUE #03-01	Da	ate:	07/04/2021
		Co	ode:	AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLS 4500E	Veh. Inspected		SLR 4450X
Policy No.		Coverage (\$)		0.00
Claim No.	C10009518/JM	Excess (\$)		0.00
Assign From	IVY RATILLA	Assign Date		24/03/2021
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI LANCER EX (A)	c.c		1590
Engine No.	HIDDEN	Year of Reg.		2017
Chassis No.	JMYSRCY1AGU006829	Colour		SILVER
Odometer	102304 KM	Steering		IN ORDER
Brakes	IN ORDER	Modification		SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make		Balance
R/H Front Tyre	205/60 R16	DUNLOP		7 mm
L/H Front Tyre	205/60 R16	DUNLOP		7 mm
R/H Rear Tyre	205/60 R16	DUNLOP		7 mm
L/H Rear Tyre	205/60 R16	DUNLOP		7 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/03/2021	Inspection Date		24/03/2021
Survey held at	TICK HAI MOTOR & WELDING SERVICES			
	BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	(BUDGET DIRECT 190 CLEMENCEAN SINGAPORE SHO 239924  Insured Veh. Policy No. Claim No. Assign From  Make & Model Engine No. Chassis No. Odometer Brakes General  R/H Front Tyre L/H Front Tyre L/H Rear Tyre L/H Rear Tyre  THE VEHICLE SUS DAMAGES SEE D  Accident Date Survey held at	Affiliated to Federation Internation AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924  Policy Particulars Insured Veh. SLS 4500E Policy No. Claim No. C10009518/JM Assign From IVY RATILLA  Vehicle Particulars  Make & Model MITSUBISHI LANCER EX (A) Engine No. HIDDEN Chassis No. JMYSRCY1AGU006829 Odometer 102304 KM Brakes IN ORDER General GOOD  Condition  Size R/H Front Tyre 205/60 R16 L/H Rear Tyre 205/60 R16  L/H Rear Tyre 205/60 R1	Affiliated to Federation Internationale Des Experts En At AUTO & GENERAL INSURANCE (\$) PL	Affiliated to Federation Internationale Des Experts En Automot AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924  Code:  Policy Particulars: THIRD PARTY CLAIM Insured Veh. SLS 4500E Policy No. Coverage (\$) Claim No. C10009518/JM Excess (\$) Assign From IVY RATILLA Assign Date  Vehicle Particulars & Condition  Make & Model MITSUBISHI LANCER EX (A) c.c Engine No. HIDDEN Year of Reg. Chassis No. JMYSRCY1AGU006829 Colour  Odometer 102304 KM Steering Brakes IN ORDER Modification  General GOOD  Conditions of Tyres  Size Make R/H Front Tyre 205/60 R16 DUNLOP L/H Front Tyre 205/60 R16 DUNLOP L/H Rear Tyre 205/60 R16 DUNLOP L/H Rear Tyre 205/60 R16 DUNLOP  Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.  General Information  Accident Date 22/03/2021 Inspection Date  Survey held at TICK HAI MOTOR & WELDING SERVICES BLK 1 KAIS BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISE

7 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: