

ASS. REC. BY: Taufikh

REF:

CS/EQ121003793/Tiv83

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: XE 3994B

Policy No. _____

Claims No. DM21HO00438-JG

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Wp

Vehicle: IN/OUT

Veh No: XE 740L Yr Regn: 2015 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Vs/oo FEE 300 c.c. 7146Colour: white A/C: Insured / Std / NI / NASp. Reading: 770232 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YV2VH70D6FZ102486

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim orTyre Size: F: 225/80R22.5R: ~ ~ (D)BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Fivenza

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8/8 mmL/Bal. 8 mm L/Bal. 8/8 mmD.O.A. 4/11/20 D.O.I. 25/3/21Survey held at Sembawang Bedok

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/6/21 Taufikh confirmed \$362.90 (Red 0)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 29/6/21-Typist

Rep. Format: TP

Lump Sum / L.B.H. (\$) 362.90

Days Of Repair: 1

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL



Quotation Preview

Page 1 of 2

Cust. 810488
 UD Trucks Singapore (Pte.) Ltd.
 12 Tuas Avenue 10
 Singapore 639136

SEMBWASTE PTE LTD
 30 Hill Street #05-04
 Singapore 179360

Singapore SINGAPORE

No.	Quotation No.	13025277	Veh.ty	FEE7 64R
Date	08/03/2021	Order Dt.	08/03/2021	Chassis/SL No.
Expiry Dt	13/03/2021	Mil.	764450	Make
FEE300 64R (Manual) - n	Req. Delv. Dt		Regn.	XE740L
			CustRef.	FEE300 64R

Payment Desc 3 45Days Payment Due Date 22/04/2021

PC	Lab/Part	Description	Time/Qty	Price	Discount	GST	Amt
0		To provide labour and material for truck repair			0.00		0.00
0		MIRROR	1.00	199.00	30.00	7.00	139.30
0		HOUSING	1.00	94.50	30.00	7.00	66.15
0		COVER	1.00	66.00	30.00	7.00	46.20
0		INDICATOR LAMP	1.00	47.50	30.00	7.00	33.25
0	35000-2	Labour to check and assess damaged inclusive of parts replacement	1.20	65.00	0.00	7.00	78.00

Document Information Lines

Total Parts Cost 284.90

Total Labor Cost 78.00

Tanphn 77795744

wp' 25/3/21 @ 4:15pm

Resurvey new parts

Tanphn @ lkhant.com

0/day

Sub Total 362.90

7.00 % GST 25.40

Gross Total 388.30

Advance 0.00

Tot Amt 388.30

Total Amount In SGD 388.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Description of PC 0-Customer - VO

UD Trucks Singapore (Pte.) Ltd.

12 Tuas Avenue 10

Singapore 639136

Acknowledged by Repairer

Signature:

Date:

Telephone
+65 6672 7500

Telefax
+65 6861 7663

Registration No.
202007810M

www.volvotrucks.sg

Registered Office
Singapore

**Quotation Preview**

Page 2 of 2

		Cust.	810488		
UD Trucks Singapore (Pte.) Ltd.			SEMBWASTE PTE LTD		
12 Tuas Avenue 10			30 Hill Street #05-04		
Singapore			Singapore		
639136			179360		
Singapore			SINGAPORE		
No.		Quotation No.	13025277	Veh.ty	FEE7 64R
Date	08/03/2021	Order Dt.	08/03/2021	Chassis/SL No.	Z-102486
Expiry Dt	13/03/2021	Mil.	764450	Make	00 - VTC
FEE300 64R (Manual) - n		Req. Delv. Dt		Regn.	XE740L
				CustRef.	FEE300 64R " " " "
Payment Desc	3 45Days	Payment Due Date	22/04/2021		

Authorizing Signature : _____ PO Number : _____

Vehicle Registration Details

Vehicle No. XE740L	Make/ Model VOLVO/FEE300 64R RSS DCM	Vehicle Scheme -
Current Propellant Diesel	Chassis No. YV2VH70D6FZ102486	Vehicle Type Goods (Open) Garbage /Sanitary Wagon

Owner's Details

Owner Name:

SEMBWASTE PTE. LTD.

Owner ID Type:

Company

NRIC/Passport/Company Cert No.:

199507280G

Registered Address:

30 HILL STREET #05-04 SINGAPORE 179360

Mailing Address:

-

Birth Date:

-

Registration Details

Previous Vehicle No.:

-

Effective Date of Ownership:

15 Jun 2015

Original Registration Date:

15 Jun 2015

Registration Date:

15 Jun 2015

No. of Transfers:

0

IU Label No.:

2010493746

Vehicle Specifications

Engine No.:

11760828

Chassis No.:

YV2VH70D6FZ102486

Year of Manufacture:

2015

Primary Colour:

White

Secondary Colour:

Passenger Capacity:

-

2

Engine Capacity / Power Rating :

Maximum Power Output:

7146 cc / -

-

Max Unladen Weight:

Maximum Laden Weight:

10900 kg

28000 kg

Vehicle Attachment 1:

Vehicle Attachment 2:

With Roll On/Off

-

Vehicle Attachment 3:

-

Additional Registration Fee (ARF) and COE Information

Open Market Value:

Additional Registration Fee Rate:

\$112,589.00

5.00 %

Actual ARF Paid:

Vehicle Lifespan Expiry Date:

\$5,630.00

14 Jun 2035

OPC Cash Rebate Eligibility:

QP during COE Bidding Exercise:

No

\$52,001.00

COE No.:

COE Expiry Date:

2015060105000509Z

14 Jun 2025

COE Category:

COE Registration Category:

C - Goods Vehicle & Bus

C - Goods Vehicle & Bus

Quota Premium (QP) / Prevailing Quota Premium :

Actual QP Paid

\$52,001.00 / -

\$52,001.00

QP (Regn Cat):

\$52,001.00

PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

No

-

Minimum PARF Benefit:

-

Vehicle Emissions Details

CO2 Emission: