



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21003799/Uqf3n2	Date: 07/04/2021
			Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLX 9952A	Veh. Inspected	SDQ 1865C	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10009538/ST	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	24/03/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CITY (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	MRHGM6660LT000199	Colour	GREY	
Odometer	9626 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	BRIDGESTONE	7 mm	
L/H Front Tyre	185/55 R16	BRIDGESTONE	7 mm	
R/H Rear Tyre	185/55 R16	BRIDGESTONE	7 mm	
L/H Rear Tyre	185/55 R16	BRIDGESTONE	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/03/2021	Inspection Date	25/03/2021	
Survey held at	15 KAKI BUKIT ROAD 4# 01-53			
Repairer	ZOOM AUTOWERKS PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	