

ASS. REC. BY:

602
PRS

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. S1M03692

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMM 2416 Z Yr Regn: 24 Jun 2019

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Freed c.c. 1496

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

123513

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GB71100192

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65 R15

R:

U

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

25-03-21

Survey held at

W/S

3:30pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

CSE: 44314

\$3000 - \$4000.

26/03/21 @ 3.59pm revised to Chan Kian Chuan via Smart Claims.

26/03/21 Submit PRS.

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

5

1) 26/03 Typist

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Mech. Insp (\$

Survey Fee:

Transportation:

Photos

Other:

Report Forwarded:

SMART CLAIMS - PRS

Report Sum / File Date: