

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	EQ INSURANCE COMPANY LTD			ef:	CS/EQI21003870/R1qf3e2	
	5 MAXWELL ROAI #17-00 TOWER BL MND COMPLEXSI		Da	ate:	07/05/2021	
			Co	ode:	EQI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GY 9751S	Veh. Inspected		SLV 6756E	
	Policy No.	DMCPHQ20-001463	Coverage (\$)		0.00	
	Claim No.	DM21HO00453-JG	Excess (\$)		0.00	
	Assign From	JOEL GOH	Assign Date		25/03/2021	
2. Vehicle Particulars & Condition						
	Make & Model	KIA FORTE K3 1.6A	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	KNAFJ411MJ5757636	Colour		BLACK	
	Odometer	59483 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST LAKE		6 mm	
	L/H Front Tyre	195/65 R15	WEST LAKE		6 mm	
	R/H Rear Tyre	195/65 R15	WEST LAKE		6 mm	
	L/H Rear Tyre	195/65 R15	WEST LAKE		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	24/03/2021	Inspection Date		25/03/2021	
	Survey held at XINYA AUTO SERVICES PTE LTD BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					
-						