

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CCG/A16.21003875/Upa3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMU 73156

at Workshop m/s

21.

of

Insured:

SKG914

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

£70k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

£756

Vehicle: IN / OUT

Date:

Person Contacted:

027 7500

Veh No:

SMU 73156

Yr Regn:

26/18/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA 1

Make:

Honda fit

c.c 1317

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

22401

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GK31351386

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/70 R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

2x/3/21

D.O.I.

25/3/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body 2

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

31 involved LTA £37836
have G.A

19/4/21 2/5 £6500 confirmed with Alan.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

) TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)

TOTAL