

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 25/03/2021

To : INDIA INTERNATIONAL INSURANCE PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTHCVE000212

Accident Date : 01/03/2021

Vehicle No : GBD-5979-Z

Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	TAILLAMP RH <i>cm</i>	270.00	270
1	TAILLAMP LOWER PANEL RH <i>X SVC</i>	RESTORE	250
1	REAR FENDER RH <i>X SVC R.</i>	RESTORE	202.50
Sub Total		270.00	
Discount 25% On Parts		(67.50)	
Special Nett Item			
1	ADVERTISEMENT STICKER PANEL <i>no</i>	250.00	250

Date : 25/03/2021

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTHCVE000212

Accident Date : 01/03/2021

Vehicle No : GBD-5979-Z

Make & Model : TOYOTA HIACE 3.0 TURBO VAN G (M) EURO

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	250.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	300.00	200 300 30.00 530
	TO RESPRAY AFFECTED AREAS	400.00	
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	
	Sub Total	730.00	

Remarks:

3 days - 7/p / Rep after repair

SUB TOTAL

GST 7.0 % 82.78

TOTAL 1,265.28

Surveyor's name:

Rasul - Hp 9001366

Principal's name:

ETHOZ Group Ltd

Survey Date & Time:

25/03/21 @ 1700

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: