

ASS. REC. BY:

Steve

REF:

CS/ A16 21003889/Evf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 1700009447

Claims No. 2628612068SG


Sum Insured: Excess: 500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Cum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SLP 1829T

Yr Regn:

29/5/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA NITRO

c.c.

1580

Colour:

Red

A/C:

Insured / Std / NI / N

Sp. Reading

129052

T/Radio:

Insured / Std / NI / N

Eng/No:

KNA CCHCVA15715-666

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

205/55 R16

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

4

mm

Rear

R/Bal.

4

mm

L/Bal.

4

mm

U/Bal.

4

mm

D.O.A.

24/3/21

D.O.I.

25/3/21

Survey held at

cycle & carriage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Re-LH

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	MV-73K
16/4/21	Final fig \$2067.60 confirmed by email (Red 5136.40, 71%)

Date/Time, File, Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

19/4/21-Typist

Prepared: Merimen

Final Sum / L.F. / % \$2067.60

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp

(\$

☐

: Interview

(\$

☐

: Tech. Invs

(\$

☐

: Weekend

(\$

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
Yeo Min Si, Grace (yang Minsi, Blk 312C Sumang Link #07-157 Singapore 823312 Contact No Mobile: 91432273	<table> <tr> <td>Cust No/Name</td><td>/Yeo Min Si, Grace (yang Minsi,</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLP1829T / 29/05/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>KNACC81CVH5075666</td></tr> <tr> <td>Engine No</td><td>G4LEHS205947</td></tr> <tr> <td>Make/Model</td><td>KIA/NIRO 1.6 A</td></tr> <tr> <td>Colour/Trim</td><td>K3R TEMPTATION RED / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/Yeo Min Si, Grace (yang Minsi,	Reg No/Reg Date	SLP1829T / 29/05/201	Date In/Mileage	/ 0	Chassis No	KNACC81CVH5075666	Engine No	G4LEHS205947	Make/Model	KIA/NIRO 1.6 A	Colour/Trim	K3R TEMPTATION RED / WK SATURN BLACK
Cust No/Name	/Yeo Min Si, Grace (yang Minsi,														
Reg No/Reg Date	SLP1829T / 29/05/201														
Date In/Mileage	/ 0														
Chassis No	KNACC81CVH5075666														
Engine No	G4LEHS205947														
Make/Model	KIA/NIRO 1.6 A														
Colour/Trim	K3R TEMPTATION RED / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	25/03/2021/ 11:01	QUD	247 / DonBong	31034			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON LOWER COVER BUMPER, BUMPER MOULDING, REPAIR LH REAR FENDER, REPAIR REAR UPPER BUMPER					430			1600.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST								60.00
E PNT98000 PAINT WORK SPRAY LH REAR FENDER, REAR BUMPER AND AFFECTED PORTION					350 X2			1050.00
M SUNDRY PERFORM RUST PREVENTION								80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment								120.00
A 34900099 RENEW REAR UNDERCARRIAGE DAMAGES					?			400.00
M SUNDRY LABOUR RENEW LH REAR SPORT RIM INCLUDING BALANCING								30.00
M SUNDRY SUPPLY LH REAR TIRE								350.00
A 10028901 TO CARRY OUT AFTER RADAR CALIBRATION AND SETTINGS AFTER REPAIR REAR PORTION					?			120.00
M SUNDRY SUNDRIES					70			50.00
M MOULDING ASSY-RR BUMPER SIDE,L / CUT					1.00	20.00	00.00	20.00
M BRACKET ASSY-RR BUMPER SIDE,LH / ?					1.00	25.00	00.00	25.00
M GARNISH ASSY-QTR SIDE,LH / CUT					1.00	144.00	00.00	144.00
M COVER-RR BUMPER LWR / CUT					1.00	392.00	00.00	392.00
M WHEEL ASSY-ALUMINIUM / CUT					1.00	629.00	00.00	629.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
Yeo Min Si, Grace (yang Minsi, Blk 312C Sumang Link #07-157 Singapore 823312 Contact No Mobile: 91432273	Cust No/Name /Yeo Min Si, Grace (yang Minsi, Reg No/Reg Date SLP1829T / 29/05/201 Date In/Mileage / 0 Chassis No KNACC81CVH5075666 Engine No G4LEHS205947 Make/Model KIA/NIRO 1.6 A Colour/Trim K3R TEMPTATION RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	25/03/2021/ 11:01	QUD	247 / DonBong	31034			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	HUB & BEARING ASSY-RR				1.00	437.00	00.00	437.00
M	ARM ASSY-RR TRAILING ARM, LH				1.00	117.00	00.00	117.00
M	ARM COMPLETE-RR LWR, LH				1.00	379.00	00.00	379.00
M	ARM ASSY-RR ASSIST				1.00	90.00	00.00	90.00
M	ARM & BUSH ASSY-SUSP UPR, LH				1.00	108.00	00.00	108.00
M	CROSSMEMBER-RR				1.00	637.00	00.00	637.00

Estimate

SURVEYOR NAME: Steve (LKK) OO-AM M

SURVEYOR SIGNATURE: Expers - ?

DATE: P/P

REMARKS: My Bel dy

5 days
25/3/21, 2.00pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Confirm & accepted by _____

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Authorized signatory and company stamp

	Nett	6,988.00
7% GST on	6988.00	489.16
Total Payable		7,477.16

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 25/03/2021 09:55 (SGT)
Date of Accident 24/03/2021 16:26 (SGT)
Exact Location of Accident Singapore
Additional Location Information TUAS ROAD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLP1829T
INSURED/POLICYHOLDER
Is company? No
Name Of Registered Owner YEO MIN SI, GRACE (YANG MINSI, GRACE)
NRIC No SXXXX753Z
Email Address yeo_min_si_grace@moe.edu.sg
Mobile Phone No (Phone) +65-91432273
Alternative Phone No (Home) +65-91432273

VEHICLE PARTICULARS

Manufacturer Kia
Model Niro
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 1600

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 1700009447-03
Cover Note Number -

DRIVER

Name of Driver LIM TONG LEE, ANDREW
NRIC No SXXXX580B



Date of Birth
 Occupation
 Date of Driving Pass
 Driving experience
 Gender
 Mobile Number
 Alt. Phone Number
 Email Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

12/02/1979
 Indoor
 10/05/2007
 13 YEARS AND 10 MONTHS
 Male
 (Phone) +65-98367924
 -
 limtongleeandrew@gmail.com
 Blk 312c Sumang Link #07-157 Singapore
 -
 823312
 No
 Spouse
 No
 -
 -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
 Weather Conditions
 Road Surface

Collision - Cross Junction
 Raining
 Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
 Number of vehicles involved in the accident
 Was anybody injured in the Accident?
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged?
 Number of Passengers (Including Driver)
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No
 2
 No
 -
 Yes
 2
 No

PASSENGER 1

Name
 Gender

LI CHUN HONG
 Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?
 Was notice of intended Prosecution given?
 If yes, against whom?

No
 No
 -

CIRCUMSTANCES OF ACCIDENT

REFER TO THE ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?
 Was there any video captured by Car Camera?
 Was there any audio recorded?

Yes
 Yes
 No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category

SMR8438U
 Honda
 -
 -
 -
 Private car

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

5. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



VEHICLE A = SLR 1890T
VEHICLE B = SMR 8438U

Describe Circumstances of the Accident

WHEN I WAS TRAVELING ALONG THIS ROAD, AT THE JUNCTION AT TIAS AVE 5, I WAS
OUT THE RED LIGHT, THE CAR COMING OUT OF TIAS AVE 2, HIT INTO MY CAR FROM LEFT
SIDE.

THERE IS NO INJURY AT THE TIME OF INCIDENT.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

AK 25/3/2021 8:20 AM
Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel





CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Yeo Min Si Grace
Period of Insurance : 29 May 2020 To 28 May 2021
Engine No. : G4LEHS205947
Chassis No. : KNACC81CVH5075666

Vehicle No. : SLP1829T
Policy No. : 1700009447-03
Endorsement No. :
Issued Date : 05 May 2020

ABOUT THE COVER

Make/Model : KIA Niro 1.6
Engine Capacity/Tonnage : 1,580.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission
This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" (IDEX) if You are or Your Authorized Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 35 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019 are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$1000

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Yeo Min Si Grace - \$1000 (Own Damage), \$1000 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

- 1 Cycle & Carriage Body & Paint Centre Add: 229 Parden Gardens Singapore 609330 65684501
- 2 Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
- 3 Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 120031 64778200
- 4 Cycle & Carriage Authorized Service Centre (For accident reporting & windscreen claim only) Add: 600 Ser Ming Ave Singapore 575733 65328000

For other Approved Reporting Centres/Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that this policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia).

0500710050

C&C FULCO-GCHP SALES

22 UBI ROAD 4 FULCO BUILDING
SINGAPORE 408617 ANSP - MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

AIGASIA.PTE.LTD