

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Ms.
JASMIN
KAUR
BLK 126 BUKIT MERAH VIEW
#04-370
SINGAPORE 151126

Document no.
Document date 24-03-2021
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2021011908/ 1
Job order date 24-03-2021
Service Advisor TIOW CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SMS7433J	BQ13HZC0	12-03-2020	VWVZZZAUZKW183831	Golf Comfortline 1.4 TSI 92kW DSG	10,879

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
5G0807217FNGRU	Cover For Bumper Primed	1	pcs.	1,247.94	#1	1,247.94	1,335.30
5G0807723F	Support Part	1	pcs.	57.27	#1	57.27	61.28
	LHS BUMPER INNER BRACKET	1	pcs.	57.27	#1	57.27	61.28
5G0807724F	Support Part	1	pcs.	57.27	#1	57.27	61.28
	RHS BUMPER INNER BRACKET	1	pcs.	21.92	#1	21.92	23.45
5G0807049B	Guide Piece	1	pcs.	21.92	#1	21.92	23.45
	BUMPER SIDE BRACKET LH	1	pcs.	21.92	#1	21.92	23.45
5G0807050B	Guide Piece	1	pcs.	21.92	#1	21.92	23.45
	BUMPER SIDE BRACKET RH	1	pcs.	43.84	#1	43.84	46.91
5G0807248G	Foam Insert	1	pcs.	635.13	#1	635.13	679.59
5G0807109AL	Impact Beam	1	pcs.	12.86	#1	12.86	13.76
	REINFORCEMENT	1	pcs.	12.39	#1	24.78	26.51
5G0919493L	Sensor Bracket	2	pcs.	12.86	#1	12.86	13.76
5G0919493J	Sensor Bracket	1	pcs.	164.62	#1	329.24	352.29
5G0919494G	Sensor Bracket	2	pcs.	1.28	#1	2.56	2.74
5Q0919275B GRU	Seal Ring Satin Black	2	pcs.	62.81	#1	62.81	67.21
5Q0919133 9B9	Bonding Agent For Plastic	1	pcs.	78.91	#1	78.91	84.43
D 822150A1	2k-Plastic Adhesive	1	pcs.	448.77	#1	448.77	480.18
D 180KU2A1	Radiator Grille Satin Bla	1	pcs.	91.91	#1	91.91	98.34
5G0853651CCZLL	Vw Sign Black/Bright Chro	1	pcs.	251.31	#1	251.31	268.90
3G0853601B DPJ	Cooling Air Grill Satin B	1	pcs.	2,759.41	#1	2,759.41	2,952.57
5G0853671G RYP	BUMPER CTR BRACKET	1	pcs.	2,759.41	#1	2,759.41	2,952.57
5G2941774	Led Headlight	1	pcs.	41.56	#1	41.56	44.47
	H/LAMP RH	1	pcs.	45.23	#1	45.23	48.40
5G2941773	Led Headlight	1	pcs.	840.00	#1	3,200.00	3,595.20
	H/LAMP LH	1	pcs.	800.00	#1	3,200.00	3,424.00
5G0805705R	Guide	1	pcs.	80.00	#1	80.00	85.60
	BUMPER CTR BRACKET	1	pcs.				
5G0805567	Support For Lock Carrier	1	pcs.				
	LABOUR	4	pcs.				
	SPRAY PAINT	4	pcs.				
	FRT NUMBER PLATE	1	pcs.				
	AIG DIRECT SETTLEMENT						
	DOA : 24/03/2021						
	TP VEH : SMQ5332R						
	SURVEY BY						

Quotation valid till 31-03-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	15,646.91	7%	1,148.48	16,406.91	17,555.39

Rasul
Hp 90010068
45 day

26/03/21

@New

Resing before paint

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/2

Company

AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:

Ms.
JASMIN
KAUR
BLK 126 BUKIT MERAH VIEW
#04-370
SINGAPORE 151126

Document no.

Document date

24-03-2021

Customer no.

5211043795

Customer GST-ID

201009404M

Dealer

30001

Job order number

2021011908/ 1

Job order date

24-03-2021

Service Advisor

TIOU CHUAN CHEE

License plate SMS7433J	Model code BQ13HZC0	First registration 12-03-2020	VIN WVWZZZAUZKW183831	Model Golf Comfortline 1.4 I TSI 92kW DSG	Mileage 10,879
---------------------------	------------------------	----------------------------------	--------------------------	--	-------------------

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
Total	760.00	15,646.91		1,148.48	16,406.91	17,555.39

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: