

VOLKSWAGEN CENTRE SINGAPORE

Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:
Ms.
JASMIN
KAUR
BLK 126 BUKIT MERAH VIEW
#04-370
SINGAPORE 151126

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor
24-03-2021
5211043795
201009404M
30001
2021011908/ 1
24-03-2021
TIOU CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SMS7433J	BQ13HZC0	12-03-2020	WVWZZZAUZKW183831	Golf Comfortline 1.4 I TSI 92kW DSG	10,879

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
5G0807217FNGRU	Cover For Bumper Primed	1	pcs.	1,247.94	#1	1,247.94	1,335.30
5G0807723F	Support Part	1	pcs.	57.27	#1	57.27	61.28
	LHS BUMPER INNER BRACKET	1	pcs.	57.27	#1	57.27	61.28
5G0807724F	Support Part	1	pcs.	21.92	#1	21.92	23.45
	RHS BUMPER INNER BRACKET	1	pcs.	21.92	#1	21.92	23.45
5G0807049B	Guide Piece	1	pcs.	21.92	#1	21.92	23.45
	BUMPER SIDE BRACKET LH	1	pcs.	43.84	#1	43.84	46.91
5G0807050B	Guide Piece	1	pcs.	635.13	#1	635.13	679.59
	BUMPER SIDE BRACKET RH	1	pcs.	12.86	#1	12.86	13.76
5G0807248G	Foam Insert	1	pcs.	12.39	#1	12.39	26.51
5G0807109AL	Impact Beam	1	pcs.	12.86	#1	12.86	13.76
	REINFORCEMENT	1	pcs.	164.62	#1	329.24	352.29
5G0919493L	Sensor Bracket	2	pcs.	1.28	#1	2.56	2.74
5G0919493J	Sensor Bracket	2	pcs.	62.81	#1	62.81	67.21
5G0919494G	Sensor Bracket	1	pcs.	78.91	#1	78.91	84.43
5Q0919275B GRU	Sensor Primed	1	pcs.	448.77	#1	448.77	480.18
5Q0919133 9B9	Seal Ring Satin Black	1	pcs.	91.91	#1	91.91	98.34
D 822150A1	Bonding Agent For Plastic	1	pcs.	251.31	#1	251.31	268.90
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	2,759.41	#1	2,759.41	2,952.57
5G0853651CCZLL	Radiator Grille Satin Bla	1	pcs.	2,759.41	#1	2,759.41	2,952.57
3G0853601B DPJ	Vw Sign Black/Bright Chro	1	pcs.	41.56	#1	41.56	44.47
5G0853671G RYP	Cooling Air Grill Satin B	1	pcs.	45.23	#1	45.23	48.40
	BUMPER CTR BRACKET	1	pcs.	840.00	#1	840.00	3,595.20
5G2941774	Led Headlight	1	pcs.	800.00	#1	800.00	3,424.00
	H/LAMP RH	1	pcs.	80.00	#1	80.00	85.60
5G2941773	Led Headlight	1	pcs.				
	H/LAMP LH	1	pcs.				
5G0805705R	Guide	1	pcs.				
	BUMPER CTR BRACKET	1	pcs.				
5G0805567	Support For Lock Carrier	1	pcs.				
	LABOUR	4	pcs.				
	SPRAY PAINT	4	pcs.				
	FRT NUMBER PLATE	1	pcs.				
	AIG DIRECT SETTLEMENT						
	DOA : 24/03/2021						
	TP VEH : SMQ5332R						
	SURVEY BY						

Quotation valid till 31-03-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	15,646.91	7%	1,148.48	16,406.91	17,555.39

Rasul
Hp 90010068
day

26/03/21

@New

Resing before paint

VOLKSWAGEN CENTRE SINGAPORE

Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



SKODA

Commercial
Vehicles

Quotation

Non binding - Preview

Page

2/2

Company

AIG ASIA PACIFIC INSURANCE P/L
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Customer Details:

Ms.
JASMIN
KAUR
BLK 126 BUKIT MERAH VIEW
#04-370
SINGAPORE 151126

Document no.

Document date 24-03-2021
Customer no. 5211043795
Customer GST-ID 201009404M
Dealer 30001
Job order number 2021011908/ 1
Job order date 24-03-2021
Service Advisor TIOW CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SMS7433J	BQ13HZC0	12-03-2020	WVWZZZAUZKW183831	Golf Comfortline 1.4 TSI 92kW DSG	10,879

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
Total	760.00	15,646.91		1,148.48	16,406.91	17,555.39

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: