

A.S.S. REC. BY:

Steve

REF:

AIG

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 1900151806

Claims No. 4674164854SG


Sum Insured: _____ Excess: 0/-

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Cum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

SNIP 1825S

Yr Regn:

2/9/19

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Cerato

c.c.

1591

Colour:

Blue

A/C:

Insured / Std / NI / N

Sp. Reading

N/A

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

KNIAFS416MK5052969

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NFERA

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

23/3/21

D.O.I.

25/3/21

Survey held at

Cycle & Collage

Des. of Damages ☒ Frt / ☒ Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV-83K

26/03/21 @11.55am revert to AIG via Merimen.

26/03/21 @2.10pm Kok Chong informed C/A via Merimen.

26/03/21 @4.24pm Informed Coco C/A & ex:\$0/- by email

03/05/21 @12.29pm confirmed with Ms Loi final fig \$17279.20, 9 days. (Red \$10240.80, 37%)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 9

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

MER-OD

17279.20



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
YEO CHOK LIH	Cust No/Name LCV11003/YEO CHOK LIH
BLK 593B MONTREAL LINK	Reg No/Reg Date SMP1825S / 02/09/201
#15-56	Date In/Mileage / 0
SINGAPORE 752593	Chassis No KNAF5416MK5052969
Contact No	Engine No G4FGKH749566
	Make/Model KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV11003	CRDVCH	25/03/2021/ 13:30		442 / Cocolu	30926		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							400.00
RENEW FRT BUMPER		400 X 1					
M SUNDRY							350 20.00
SPRAY PAINT FOR FRT BUMPER		350 X 1					60.00
E PNT88000							50.00
REMOVE & INSTALL FRT PARKING SENSOR							30.00
M SUNDRY							120.00
FRT NUMBER PLATE WITH FRAME							
A 90000001							
CHECK WIRING & ELECTRICAL SYSTEM							
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
E PNT88000							4000.00
SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR COMPARTMENT							1200
REPAIR REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH, REAR CHASSIS RH		3 X 400					
E PNT88000							300.00
REMOVE & INSTALL REAR COMPARTMENT TRIMS							60.00
E PNT88000							300.00
REMOVE & INSTALL PARKING SENSOR							
E PNT88000							3500.00
REMOVE & INSTALL CARPAT AND REAR SEATS							1400
E PNT98000							100.00
SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR COMPARTMENT							40
REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH, REAR CHASSIS RH		4 X 350					120.00
E PNT88000							50.00
REMOVE & INSTALL REA SPOILER							40.00
M SUNDRY							
APPLY SEALANT FOR ACCIDENT PORTION							
M SUNDRY							
REAR NUMBER PLATE WITH FRAME							
M SUNDRY							
C&C LOGO							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
YEO CHOK LIH	Cust No/Name LCV11003/YEO CHOK LIH
BLK 593B MONTREAL LINK	Reg No/Reg Date SMP1825S / 02/09/201
#15-56	Date In/Mileage / 0
SINGAPORE 752593	Chassis No KNAF5416MK5052969
Contact No	Engine No G4FGKH749566
	Make/Model KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV11003	CRDVCH	25/03/2021/ 13:30		442 / CocoLu	30926			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								500.00
TO STRAIGHTEN REAR BOTH CHASSIS								
A 90000001								300.00
RENEW REAR EXHAUST SYSTEM								
M SUNDRY								20.00
Sundry								
M COVER-FR BUMPER / CRU ?	1.00	633.00	00.00	633.00				
M GRILLE-FRONT BUMPER	1.00	485.00	00.00	485.00				
M COVER-FR BUMPER FOG LAMP, LH / CUT	1.00	15.00	00.00	15.00				
M LAMP ASSY-FRONT FOG, LH X NAI	1.00	303.00	00.00	303.00				
M MOULDING-FRONT BUMPER, LH X NAI	1.00	216.00	00.00	216.00				
M LAMP ASSY-SIDE REPEATER, LH / CUT	1.00	143.00	00.00	143.00				
M ABSORBER-FRONT BUMPER ENERGY / ?	1.00	84.00	00.00	84.00				
M BRACKET-FR BUMPER UPR SIDE MTG / ?	1.00	22.00	00.00	22.00				
M ULTRASONIC SENSOR ASSY-P.A.S / BR	1.00	163.00	00.00	163.00				
M ORNAMENT-KIA NO.115 / REC	1.00	32.00	00.00	32.00				
M COVER-RR BUMPER / BR	1.00	651.00	00.00	651.00				
M COVER-RR BUMPER LWR / BR	1.00	241.00	00.00	241.00				
M COVER-RR BUMPER FOG LAMP, RH / ?	1.00	19.00	00.00	19.00				
M COVER-RR BUMPER FOG LAMP, LH / CUT	1.00	19.00	00.00	19.00				
M LAMP ASSY-SIDE T/SIGNAL, RH X NAI	1.00	181.00	00.00	181.00				
M LAMP ASSY-SIDE T/SIGNAL, LH X NAI	1.00	181.00	00.00	181.00				
M EXTN WIRING ASSY-BWS / ?	1.00	207.00	00.00	207.00				
M BRACKET-RR BEAM UPR MTG, RH / ?	1.00	9.00	00.00	9.00				
M BRACKET-RR BEAM UPR MTG, LH / ?	1.00	9.00	00.00	9.00				
M BRACKET-RR BEAM LWR, CTR / ?	1.00	6.00	00.00	6.00				
M BRACKET-RR BEAM LWR MTG / ?	2.00	6.00	00.00	12.00				
M ANTENNA ASSY-SMARTKEY / ?	1.00	46.00	00.00	46.00				
M BEAM-RR BUMPER / BR	1.00	318.00	00.00	318.00				
M STAY-RR BUMPER RH / ?	1.00	65.00	00.00	65.00				
M STAY-RR BUMPER LH / ?	1.00	65.00	00.00	65.00				
M COVER-RR BUMPER UNDER, RH / ?	1.00	33.00	00.00	33.00				
M BRACKET ASSY-RR BPR SIDE UPR, L / ?	1.00	25.00	00.00	25.00				

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
YEO CHOK LIH BLK 593B MONTREAL LINK #15-56 SINGAPORE 752593 Contact No	Cust No/Name LCV11003/YEO CHOK LIH Reg No/Reg Date SMP18255 / 02/09/201 Date In/Mileage / 0 Chassis No KNAF5416MK5052969 Engine No G4FGKH749566 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV11003	CRDVCH	25/03/2021/ 13:30		442 / CocoLu	30926			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BRACKET-ASSY RR BPR SIDE UPR R				1.00	31.00	00.00	31.00
M	PANEL ASSY-TRUNK LID				1.00	1297.00	00.00	1297.00
M	HINGE ASSY-TRUNK LID,LH				1.00	97.00	00.00	97.00
M	HINGE ASSY-TRUNK LID,RH				1.00	97.00	00.00	97.00
M	PANEL ASSY-BACK				1.00	324.00	00.00	324.00
M	LOGO ASSY-KIA SUB				1.00	32.00	00.00	32.00
M	EMBLEM-CERATO				1.00	28.00	00.00	28.00
M	EMBLEM-GT LINE				1.00	45.00	00.00	45.00
M	TRIM ASSY-TRUNK LID				1.00	202.00	00.00	202.00
M	W/STRIP-TRUNK LID OPNG				1.00	100.00	00.00	100.00
M	LATCH ASSY-TRUNK LID				1.00	112.00	00.00	112.00
M	TRIM ASSY-RR TRANSVERSE				1.00	41.00	00.00	41.00
M	TRIM ASSY-LUGGAGE SIDE RH				1.00	200.00	00.00	200.00
M	MAT ASSY-LUGGAGE COVERING				1.00	211.00	00.00	211.00
M	PANEL ASSY-REAR FLOOR,RR				1.00	219.00	00.00	219.00
M	LAMP ASSY-REAR COMB INSIDE,RH				1.00	608.00	00.00	608.00
M	LAMP ASSY-REAR COMB INSIDE,LH				1.00	608.00	00.00	608.00
M	LAMP ASSY-REAR COMB OUTSIDE,RH				1.00	675.00	00.00	675.00
M	LAMP ASSY-REAR COMB OUTSIDE,LH				1.00	675.00	00.00	675.00
M	LAMP ASSY-CENTER GARNISH				1.00	690.00	00.00	690.00
M	MUFFLER ASSY-REAR				1.00	757.00	00.00	757.00
M	PROTECTOR-HEAT REAR				1.00	136.00	00.00	136.00

Estimate

Steve (LKK) 00-NH AL
25/3/21 4.34pm Excess - ?
P/P
M BCL SJ
9 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Confirm & accepted by
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Authorized signatory and company stamp

7% GST on **Nett** 21,338.00
1493.66
Total Payable 22,831.66

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/03/2021 16:37 (SGT)
Date of Accident	23/03/2021 08:30 (SGT)
Exact Location of Accident	CTE, Singapore
Additional Location Information	CTE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMP1825S

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	YEO CHOK LIH
NRIC No	SXXXX421Z
Email Address	marx_yeo@yahoo.com.sg
Mobile Phone No	(Phone) +65-98465001
Alternative Phone No	+65-98465001

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900151806
Cover Note Number	-

DRIVER

Name of Driver	YEO CHOK LIH
NRIC No	SXXXX421Z

Birth Date 25/02/1976
 Location Indoor
 Date of Driving Pass 02/01/2002
 Driving experience 19 YEARS AND 2 MONTHS
 Gender Male
 Mobile Number (Phone) +65-98465001
 Alt. Phone Number +65-98465001
 Email Address marx_yeo@yahoo.com.sg
 Address BLK 593B MONTREAL LINK #15-56
 Address complement -
 Postcode 752593
 Is the driver the policyholder? Yes
 If No, Relationship of the Driver with the Insured -
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Chain Collision
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 4
 Was anybody injured in the Accident? Yes
 Was any injured conveyed to hospital by ambulance? Yes
 Was any other material or property damaged? Yes
 Number of Passengers (Including Driver) 2
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name EMILY JASMINE NGU
 Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
 Police Station Name Sembawang Neighbourhood Police Centre
 Police Station Phone No (Phone) +65-18005549999
 Police Station Address 4 Sembawang Crescent Singapore 757633
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number SHC4601D
 Vehicle Manufacturer -
 Vehicle Model -

Variant	-
Colour	-
Category	Taxi
Name of Driver	MR MOHAMAD NIZAMULMULUK BIN HUSSAIN
Contact Number	(Phone) +65-98435229
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	3RD CAR
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMC3054H
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	1ST CAR
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SMN64M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	MR CHIA KOK SENG
Contact Number	(Phone) +65-96880777
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	LAST CAR
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	EMILY JASMINE NGU BEIXE
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	NECK & HEAD
Injured person in which vehicle?	SMP1825S
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

INJURED 2

Name of injured person	YEO CHOK LIH
------------------------	--------------

NECK & SHOULDER
SMP1825S
Yes
No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A: SLP 1825'S
B: SHC 4601D
C: SMN 64M
D: SMC 3054H

Describe Circumstances of the Accident

Refer to police report T/20210325/2064

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



SINGAPORE POLICE FORCE



T/20210325/2064

1 of 4

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

Report No. T/20210325/2064

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/03/2021 14:10	Vide Report No.:	Station Diary No.: 51
--	------------------	--------------------------

Informant's Particulars		
Name of Informant: YEO CHOK LIH		Address: APT BLK 593B MONTREAL LINK #15-56 SINGAPORE 752593
ID Type / ID No.: NRIC NO / S 421Z		Contact No.: Home/Office: Mobile: 98465001
Nationality: SINGAPORE CITIZEN		Email:
Sex: Male	Age: 45	Date of Birth: 25/02/1976
Type of Informant: Driver		
Race: Chinese		Language: Institution / School Name:
Occupation: CIVIL SERVANT		Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 23/03/2021 08:30	Type of Location: Straight Road
Location: CENTRAL EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC4601D	Car				Seriously Damaged	1
SMP1825S	Car	KIA	CERATO 1.6(A) SUNROOF	Blue	Seriously Damaged	1

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date



SINGAPORE POLICE FORCE



T/20210325/2064

2 of 4

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

Report No. T/20210325/2064

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMP1825S	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1900151806	02/09/2019	01/09/2021

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA		
Driver				
Name	MOHAMAD NIZAMULMULUK BIN HUSSAIN	ID No.	S	382G
Related Vehicle	SHC4601D (Car)	Contact No.	98435229	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL	Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
Driver				
Name	YEO CHOK LIH	ID No.	S	421Z
Related Vehicle	SMP1825S (Car)	Contact No.	98465001	
Hospital/Clinic	GLENEAGLES MEDICAL CENTRE	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3	Date of Expiry: NIL
Date Treatment	24/03/2021	Date Discharge	24/03/2021	
No. of Days granted Medical Leave	03	Degree of Injury	Slight	
Passenger				
Name	EMILY JASMINE NGU BEIXE	ID No.	S	266Z
Related Vehicle	SMP1825S (Car)	Contact No.	81681703	
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL	Date of Expiry: NIL
Date Treatment	23/03/2021	Date Discharge	23/03/2021	
No. of Days granted Medical Leave	01	Degree of Injury	Slight	



**SINGAPORE
POLICE FORCE**



T/20210325/2064

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

3 of 4

Report No. T/20210325/2064

CONTINUATION OF REPORT

Brief Details.

On the above mentioned date, time and location, I was driving my car bearing the number plate SMP1825S, on the first lane along CTE towards the City. There was a silver car bearing the number plate SMC3054H ahead of me and I was keeping a safe distance away from the car. I was travelling at about 70km/h. The silver car ahead of me came to a gradual stop, I gradually slowed down and stopped as well. When I was stationary, I felt a sudden and huge impact coming from the rear of my car, causing my car to move forward and hit onto the silver car, I am not sure if my car had collided onto the railing of the expressway. The driver of the silver car then alighted his car to make a check on his car and drove away. I then alighted from my car and discovered that a SMRT Taxi bearing the number plate of SHC4601D had collided onto the rear of my car. I immediately called for the ambulance as my wife is pregnant.. LTA enforcement and EMS Tow services came down. LTA enforcement officers came down and took my particulars and I exchanged my particulars with the driver of the Taxi. After which, I accompanied my wife as she was being conveyed to Singapore General Hospital by the ambulance. My wife was given one day medical certificate from SGH on 23/03/2021 and I was given 3 days of medical certificate from Gleneagles Medical Centre for my neck and shoulder on 24/03/2021. I wish to state that the incident number given by TP is F/20210323/0045.



SINGAPORE POLICE FORCE



T/20210325/2064

Police Station Of Origin:
Sembawang N.P.C
4 Sembawang Crescent SINGAPORE
757633
Tel No: 1800-5549999

4 of 4


Report No. T/20210325/2064

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan


IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: 
L/
Sgt 2 DANIAL SYAFIQ BIN MOHAMED SHARIL

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Staff Sgt NUR ADELINA BINTE MOHAMMAD
FUAT
Contact No: 65476066
Authentication Stamp
NP168

NP168

Signature: 

Signature Of Informant:



Date/Time:
25/03/2021 14:10

Classification Of Case:

CERTIFICATE OF INSURANCE

AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder
Date of Insurance
Policy No.
Vehicle No.

: YEO CHOK LIH
: 02 Sep 2019 To 01 Sep 2021
: G4FGKH749566
: KNAF5416MK5052969

Vehicle No. : SMP18253
Policy No. : 1900151806
Endorsement No. :
Issued Date : 06 Sep 2019

ABOUT THE COVER

Make/Model : KIA Cerato
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2019
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

YEO CHOK LIH - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 675733 69328000
2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES


Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622237

C&CKICP2 - GORDON
239 ALEXANDRA ROAD
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE