



CYCLE & CARRIAGE

AIG - OD (REVERT)
SURVEY: 26/03/21
LKK - STEVE

VEHICLE NO : SMJ 5285 E

MODEL : KIA/CERATO 1.6 A SX

WIP : 31131

Material	:	\$	<u>1,037.60</u>
Labour	:	\$	<u>1,630.00</u>
Sub-Total	:	\$	<u>2,667.60</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>2,667.60</u>
GST 7%	:	\$	<u>186.73</u>
Grand Total	:	\$	<u>2,854.33</u>
Finalise By/Date : <u>LARRY ON 16/04/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 05 WORKING DAYS + 2 days (wk.end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08778/ABDUL WAHID THOWZEEFAHAMED Reg No/Reg Date SMJ5285E*KC17/ 11/03/2019 Date In/Mileage 26/03/2021/ 35249 Chassis/Package KNAF3416MK5031024 /# Engine No G4FGJH722457 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK
26/03/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	16/04/2021/ 09:48	BLK	884 / Lauro Songcuan	31131

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, BUMPER LOWER & AFFECTED AREAS				400.00 ✓
E PNT98000 SPRAY PAINT ON REAR BUMPER PANEL				350.00 ✓
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST				120.00 ✓
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED PORTIONS				40.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
E PNT88000 REPAIR REAR END PANEL → <i>Supp.</i>				200.00 ✗
E PNT98000 SPRAY PAINT REAR END PANEL → <i>Supp.</i>				350.00 ✗
X COVER-RR BUMPER ✓	1.00	651.00	20.00	520.80 ✓
X COVER-RR BUMPER LWR ✓	1.00	241.00	20.00	192.80 ✓
X COVER-RR BUMPER UNDER, LH ✓	1.00	33.00	20.00	26.40 ✓
X COVER-RR BUMPER FOG LAMP, LH ✓	1.00	19.00	20.00	15.20 ✓
X BRACKET-RR BEAM LWR MTG ✓	1.00	6.00	20.00	4.80 ✓
X BEAM-RR BUMPER ?	1.00	318.00	20.00	254.40 ?
X CLIP → <i>Supp.</i>	10.00	2.00	20.00	16.00 ✗
X BRACKET-RR BEAM UPR MTG, LH ?	1.00	9.00	20.00	7.20 ?
Z TEXT AIG OD CLAIM - REVERT DOA: 25.03.2021 SURVEY: STEVE (LKK) 26/03/2021 05 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	1,037.60			
Labour	1,570.00			
Standard Menu	0.00	7% GST on	2667.60	186.73
Specialist Job	0.00			
Diagnostics Job	0.00			
Sundry/Others	60.00			
Total (w/o GST)	2,667.60			
			Total Payable	2,854.33

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMJ 5285 E

<u>Materials</u>		<u>Cost \$</u>
1	Clip (10 pcs)	20.00
	20% Discount	4.00
		<u>16.00</u>
<u>Labour</u>		
1	Repair Rear End Panel	200.00
2	Spray Paint Rear End Panel	350.00
		<u>550.00</u>
	Labour & Materials	566.00
	7% GST	39.62
	Total	<u>605.62</u>

REC

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD


Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens
Tel. # 6568 4658

CAR NO: SNJ 5285EWIP: 31131

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	BEAM - RR Bumper	(?) SUPP		/ RR	
2	BRACKET LH	(?) SUPP		/ RR	
3	Bumper clip	? / SUPP		/ RR	
4	repair RR panel	? / SUPP		/ RR	Stere
5	PAINT WORK RR panel	? / SUPP		/	26/3/21
6	repair Work in Bay (2)	? / SUPP		/	
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Corado 166SURVEYOR: Steve Will

HOME Online CERATO/FORTE../2019/G 1.6 MPI.. VCI

Fault Code Searching

Rescan Erase All DTC Go to DTC Save

ICU CLU WPC

12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0242	VCI Ver.	02.51
ECU Ver.	M-E-K-01-00-0183	OS Ver.	Android 10

HOME
 Online
CERATO/FORTE../2019/G 1.6 MPI..
VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

ICU
 CLU
 WPC

12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0242	VCI Ver.	02.51
ECU Ver.	M-E-K-01-00-0183	OS Ver.	Android 10



HOME

Online



CERATO/FORTE../2019/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



ICU



CLU



WPC

12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0242

VCI Ver.

02.51

ECU Ver.

M-E-K-01-00-0183

OS Ver.

Android 10