



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21003958/AUvf3e2	
			Date: 07/09/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBQ 7646C	Veh. Inspected	SMG 811K	
Policy No.	D20MTMC01008375	Coverage (\$)	0.00	
Claim No.	CMTD2100902/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	26/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	DAIHATSU COPEN	c.c	659	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	L880K0046005	Colour	GREY	
Odometer	156564 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	165/50 R15	YOKOHAMA	6 mm	
L/H Front Tyre	165/50 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	165/50 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	165/50 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/03/2021	Inspection Date	29/03/2021	
Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	