

2/03/2002

ASS. REC. BY:

REF:

2018020437/Jc 621

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

25/03/2021

From (Person): Chhia Nyuk Pui

of MSG

Date/Time: 12/11/2018

Estimated Cost:

Bill to:

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No: SLV3715T

Insured: SLC1905A

at Workshop m/s Sat Motors.

Tel:

of 24 Dahi Lane 12

Policy No: MSD/VPCP/18-000756

Claim No: MSCV/18-001474

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 7/11/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12/11

Person Contacted: Joele

Vehicle IN/OUT


| Date/Time | Action/Instruction ( X ) Estimate |
|-----------|-----------------------------------|
|           | <u>SLV3715T-X.</u>                |
|           | <u>SLC1905A-X</u>                 |
|           | <u>Dismantle: 21/11/2018</u>      |
|           | <u>Resurvey: 23/11/2018</u>       |
|           | <u>After repair: 26/11/2018</u>   |

PBS  
Surrey Area Jc


REF: MSIG

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s 24 DEFV lane 12  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT



Veh No: SLV 3715 T Yr Regn: 28 Dec 2017  
 Type:  Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: ~~Honda~~ Toyota C-HR o.c. 1797  
 Colour: RED A/C: Insured / Std / NI / NA  
 Sp. Reading: 42450 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: ZYX102077264  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  Order / ~~Grinding~~ / Leaked / Burnt or  
 Brake:  Order / Jammed / Leaked / Burnt or  
 Modi: Nil /  Rrim / STD A/Rim or  
 Tyre Size: F: 215/60R17  
 R: \_\_\_\_\_  
 BS:  OUT / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A: 7/11/18 D.O.I: 19/11/18  
 Survey held at: \_\_\_\_\_ @ 1200  
 Des. of Damages:  Front / Rear / O/S /  N/S / U/C / Rooftop or  
Front, N/S  
 The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction   |
|-------------|--|
|             | Range: <u>\$4,000 - \$4,800</u><br><u>4 days</u>   |
|             | <br><u>23/11/2018</u> |

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 Days Of Repair: 4  
 Resurvey No. of Trip: 3  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 ) S + RE )  
 ) Photos )  
 ) Other )  
 ) \_\_\_\_\_ )  
 TOTAL

Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format: PRB  
 Lump Sum / I.B.I: (\$)  
 Add Fee:  Site Insp (\$)  
 Interview (\$)  
 Tech. Invs (\$)  
 Weekend (\$)

### ...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING |             |               |  |         |               |            |  |
|--------------------------|-------------|---------------|--|---------|---------------|------------|--|
| Case                     | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status   |
| Main                     | 09 Nov 2018 |               | 12 Nov 2018<br>14:31<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured: **HITACHI CAPITAL ASIA PACIFIC PTE. LTD.,** Co. Reg. No.: 199400399N

Main Claimant: **YUSRA LIMO SERVICES,** Co. Reg. No.: 53345781E

|                             |                             |                        |  |
|-----------------------------|-----------------------------|------------------------|--|
| Vehicle Reg. No.:           | <b>SLV3715T</b>             | Date of Loss:          | 07/11/2018 08:00 - :59<br>[10 Months and 10 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | <b>TP / MSC/V/18-001474</b> | Policy/Cover Note No.: | MSD/VPCP/18-000756<br>Coverage: 01/06/2018 - 31/05/2019                      |
| Vehicle Reg. No. (Insured): | <b>SLC1905A</b>             | Policy No. (Claimant): |  |
|                             |                             | Excess:                | \$52,000.00  |

Repairer: **Sat Motors (HQ)** 24 Defu Lane 12, 539131 Defu Lane - Tel:

Handling Insurer: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Chhia Nyuk Pui** - 6594 2521]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [**Imm.Advice** due 13/11/2018]

Adj Asg. Remarks: SURVEY DISAGREE ON SJE - ASSIGN LKK. OI NOT REPORTED. CONTACT: JESSIE ONG 9859 9677

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

NOT IN

Jessie

12/11/2018

2:45pm

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                        |
|----------------------------|------------------------|
| Date Of Report             | 08/11/2018 17:51       |
| Date Of Accident           | 07/11/2018 08:40       |
| Exact Location Of Accident | STILL RD TOWARDS EUNOS |
| Country/State of Loss      | SINGAPORE              |

### DETAILS OF OWN VEHICLE

|                             |                     |
|-----------------------------|---------------------|
| Vehicle Registration Number | SLV3715T            |
| <b>Insured/Policyholder</b> |                     |
| Name Of Registered Owner    | YUSRA LIMO SERVICES |
| Co Reg No                   | 53345781E           |
| Email Address               | NOEMAIL             |
| Mobile Phone No             |                     |
| Alternative Phone No        | OFFICE-82003645     |

### Vehicle Particulars

|  |              |
|--|--------------|
| Manufacturer   | TOYOTA       |
| Model  | CHR          |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE  |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO           |
| If No, Please state action to be taken                                       | THIRD PARTY  |
| Vehicle Category   | PRIVATE HIRE |

### Insurance Company

|                           |  |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | COMPREHENSIVE                          |
| Fleet Policy              | NO                                     |
| Policy Number             | 5096937419                             |
| Cover Note Number         |  |

### Driver

|                      |                            |
|----------------------|----------------------------|
| Name of Driver       | DZULKIFLEE BIN ABDUL HALIK |
| NRIC No              | S8629781G                  |
| Date Of Birth        | 21/10/1986                 |
| Occupation           | INDOOR                     |
| Date Of Driving Pass | 05/08/2008                 |
| Driving Experience   | 10 YEARS AND 3 MONTHS      |
| Gender               | MALE                       |
| Mobile Number        | (LOCAL) +65-82003645       |
| Fax Number           |                            |
| Contact Number       |                            |
| EEmail Address       | NOEMAIL                    |

Address

Postcode

Insurance Company Name

MSIG INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

DZULKIFLEE BIN ABDUL HALIK

Approximate Age

Injuries Sustain

BACK PAIN

Injured person in which vehicle?

SLV3715T

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7 Jul 18 at around 8:12am, I was driving along Still Rd towards Marine Parade, just after I check closed my left hand side of my lane (lane 3) I noticed in suddenly vehicle B 31C 1905A speed in from the most left lane (lane 4) which is a left turning lane and cut in to the front of my vehicle A (SLV 37157) and slammed Brake and causes my car to hit onto his rear right side of his car. At the point of accident my car had been fully shifted in to lane 3 while vehicle B was still half on lane 2 & lane 3. And from my footage I realised there was no vehicle in front of him but he had slammed his brake the moment he cut onto our lane. This incident was recorded by my in car camera and I would like

DECLARATION to claim against the other party.  
I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

X  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars     |                                  |
|-------------------------------|----------------------------------|
| Owner ID Type:                | Business                         |
| Owner ID:                     | 5781E                            |
| Vehicle Details               |                                  |
| Vehicle No.:                  | SLV3715T                         |
| Vehicle to be Exported:       | No                               |
| Intended Deregistration Date: | 21 Nov 2018                      |
| Vehicle Make:                 | TOYOTA                           |
| Vehicle Model:                | CHR 1.8 S HYBRID A               |
| Primary Colour:               | Red                              |
| Manufacturing Year:           | 2017                             |
| Engine No.:                   | 2ZR8200461                       |
| Chassis No.:                  | ZYX102077264                     |
| Maximum Power Output:         | 90.0 kW (120 bhp)                |
| Open Market Value:            | \$26,771.00                      |
| Original Registration Date:   | 28 Dec 2017                      |
| First Registration Date:      | 28 Dec 2017                      |
| Transfer Count:               | 0                                |
| Actual ARF Paid:              | \$5,000.00                       |
| Intended PARF Rebate Details  |                                  |
| PARF Eligibility:             | Yes                              |
| PARF Eligibility Expiry Date: | 27 Dec 2027                      |
| PARF Rebate Amount:           | \$3,750.00                       |
| Intended COE Rebate Details   |                                  |
| COE Expiry Date:              | 27 Dec 2027                      |
| COE Category:                 | E - Open - all except motorcycle |
| COE Period(Years):            | 10                               |
| QP Paid:                      | \$48,011.00                      |
| COE Rebate Amount:            | \$42,769.00                      |
| <b>Total Rebate Amount:</b>   | <b>\$46,519.00</b>               |

The information contained herein is correct as at 21 Nov 2018

OK

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

**CLAIM SUBFOLDER TRACKING**

| Case | Notified    | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                              | Ins Auth'ed | Status  |
|------|-------------|---------------|--|--|--|-------------|---|
| Main | 09 Nov 2018 |               | 12 Nov 2018<br>14:31<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

**CLAIM SUBFOLDER DETAILS**

[Created by insurer]

|                             |   |                        |  |
|-----------------------------|---|------------------------|--|
| Insured:                    | <b>HITACHI CAPITAL ASIA PACIFIC PTE. LTD.</b> , Co. Reg. No.: 199400399N  |                        |  |
| Main Claimant:              | <b>YUSRA LIMO SERVICES</b> , Co. Reg. No.: 53345781E  |                        |  |
| Vehicle Reg. No.:           | <b>SLV3715T</b>   | Date of Loss:          | 07/11/2018 08:00 - :59<br>[10 Months and 10 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | <b>TP / MSC/V/18-001474</b>   | Policy/Cover Note No.: | MSD/VPCP/18-000756<br>Coverage: 01/06/2018 - 31/05/2019                      |
| Vehicle Reg. No. (Insured): | <b>SLC1905A</b>   | Policy No. (Claimant): |  |
|                             |   | Excess:                | S\$2,000.00  |
| Repairer:                   | <b>Sat Motors (HQ)</b> 24 Defu Lane 12, 539131 Defu Lane - Tel:   |                        |  |
| Handling Insurer:           | <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Chhia Nyuk Pui</b> - 6594 2521]        |                        |  |
| Adjuster:                   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... [Imm.Advice due 13/11/2018] |                        |  |
| Adj Asg. Remarks:           | SURVEY DISAGREE ON SJE - ASSIGN LKK. OI NOT REPORTED. CONTACT: JESSIE ONG 9859 9677   |                        |  |

**ASSOCIATED MAIL RECEIVED**

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS**

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |



## Claim Documents

**\*SLV3715T (MSC/V/18-001474)  
[SLC1905A]**

TP

**YUSRA LIMO SERVICES**

**Nov 7 2018 8:00AM**

**[HITACHI CAPITAL ASIA PACIFIC PTE. LTD.]**

**Sat Motors**

| <a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a> |                 |   | <b>View</b> <span style="border: 1px solid black; padding: 2px;">View in Browser ▾</span> |                                     |
|---|-----------------|---|---|-------------------------------------|
| <b>Video</b>  |                 |   | 1 per page ▾ <input checked="" type="checkbox"/>  |                                     |
| No  | Finalized On    | MSIG Insurance (Singapore) Pte. Ltd. (HQ)   | Thumbnail   | Print                               |
| 1   | 26/11/18 13:53  | <b>Video - Accident</b><br>From: SC - Reg. No: SLC1905A, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD   | Load MOV  | <input type="checkbox"/>            |
| <b>Assessment Reports</b>   |                 |   | 1 per page ▾ <input checked="" type="checkbox"/>  |                                     |
| No  | Finalized On    | MSIG Insurance (Singapore) Pte. Ltd. (HQ)   | Thumbnail   | Print                               |
| 1   | 26/11/18 13:53  | <b>Accident Statement</b><br>From: SC - Reg. No: SLC1905A, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD | Load HTM  | <input type="checkbox"/>            |
| <b>Photos/Images</b>  |                 |   | 3 per page ▾ <input checked="" type="checkbox"/>  |                                     |
| No  | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)   | Thumbnail   | Print                               |
| 1   | 21/11/18 17:36  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 2   | 21/11/18 17:36  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 3   | 21/11/18 17:36  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 4   | 21/11/18 17:36  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 5   | 21/11/18 17:36  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 6   | 21/11/18 17:36  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 7   | 21/11/18 17:36  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 8   | 21/11/18 17:36  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 9   | 21/11/18 17:36  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 10  | 21/11/18 17:36  | <b>General View</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 11  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 12  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 13  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 14  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 15  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 16  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 17  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 18  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 19  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 20  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 21  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 22  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 23  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 24  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 25  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 26  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |
| 27  | 21/11/18 17:39  | <b>Photographs of Damaged Parts</b>   | Load JPG <input checked="" type="checkbox"/>  | <input checked="" type="checkbox"/> |

| Video |                |   | 1 per page | <input checked="" type="checkbox"/> |
|-------|----------------|---|------------|-------------------------------------|
| No    | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ) | Thumbnail  | Print                               |
| 28    | 04/12/18 15:35 | <b>Photographs of Damaged Parts</b>       | Load JPG   | <input checked="" type="checkbox"/> |
| 29    | 04/12/18 15:35 | <b>Photographs of Damaged Parts</b>       | Load JPG   | <input checked="" type="checkbox"/> |
| 30    | 04/12/18 15:35 | <b>Photographs of Damaged Parts</b>       | Load JPG   | <input checked="" type="checkbox"/> |
| 31    | 04/12/18 15:35 | <b>Photographs of Damaged Parts</b>       | Load JPG   | <input checked="" type="checkbox"/> |
| 32    | 04/12/18 15:35 | <b>Photographs of Damaged Parts</b>       | Load JPG   | <input checked="" type="checkbox"/> |
| 33    | 04/12/18 15:35 | <b>Photographs of Damaged Parts</b>       | Load JPG   | <input checked="" type="checkbox"/> |
| 34    | 04/12/18 15:35 | <b>Photographs of Damaged Parts</b>       | Load JPG   | <input checked="" type="checkbox"/> |
| 35    | 04/12/18 15:35 | <b>Photographs of Damaged Parts</b>       | Load JPG   | <input checked="" type="checkbox"/> |
| 36    | 04/12/18 15:35 | <b>Photographs of Damaged Parts</b>       | Load JPG   | <input checked="" type="checkbox"/> |
| 37    | 04/12/18 15:35 | <b>Photographs of Damaged Parts</b>       | Load JPG   | <input checked="" type="checkbox"/> |
| 38    | 04/12/18 15:35 | <b>Photo After Spray</b>                  | Load JPG   | <input checked="" type="checkbox"/> |
| 39    | 04/12/18 15:35 | <b>Photo After Spray</b>                  | Load JPG   | <input checked="" type="checkbox"/> |
| 40    | 04/12/18 15:35 | <b>Photo After Spray</b>                  | Load JPG   | <input checked="" type="checkbox"/> |
| 41    | 04/12/18 15:35 | <b>Photo After Spray</b>                  | Load JPG   | <input checked="" type="checkbox"/> |

| Documentation |                |  | 1 per page | <input checked="" type="checkbox"/> |
|---------------|----------------|--|------------|-------------------------------------|
| No            | Finalized On   | MSIG Insurance (Singapore) Pte. Ltd. (HQ)  | Thumbnail  | Print                               |
| 1             | 12/11/18 09:21 | <b>SLV3715T TP E-FILE REPORT</b>           | Load PDF   |                                     |
| 2             | 12/11/18 09:21 | <b>PRI - K.KRISHNA &amp; PARTNERS</b>      | Load PDF   |                                     |
| 3             | 12/11/18 09:21 | <b>SURVEY DISAGREE ON SJE - ASSIGN LKK</b> | Load PDF   |                                     |

## Documents Checklist

|  |   |
|--|---|
| <b>DOCUMENTS CHECKLIST</b>                   | <input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/> |
| There are no document checklists configured. |   |

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer  
Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18020437/JCBS2  
Date: 05/12/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VPCP/18-000756  
 Claimant Vehicle No: SLV3715T Insured Vehicle No: SLC1905A  
 Date of Loss: 07/11/2018 Nature of Claim: TP Claim No: MSC/V/18-001474

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SLV3715T**  
 Make & Model: TOYOTA C-HR HYBRID, 1.8 S (A) Engine No: 2ZR8200461  
 Reg. Date: 28/12/2017 (Man. Year: 2017) Chassis No: ZYX102077264  
 Colour: Red Odometer: 42450 km  
 Engine Capacity: 1797 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60R17 Rear Tyre Size: 215/60R17  
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

## INSPECTION

Date of Assignment: 12/11/2018  
 Date Inspected: 19/11/2018 Inspected At: Sat Motors (HQ)  
 24 Defu Lane 12  
 Singapore 539131  
 Estimated Period of Repair: 4.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$4,800.00

## REPAIR DETAILS

### Reference

|                            |  |
|----------------------------|--|
| <b>Part Source:</b> MRM-SG | Version: 1.0 (Last Synchronised: 05 Dec 2018)  |
| <b>Parts:</b> M1-SUV       | TOYOTA C-HR HYBRID 1.8 S (A) (Catalogue:Merimen Singapore 1.0)   |
| <b>Labour:</b> Repairer's  | (Price-denominated Standard List)  |
| <b>Print Code:</b>         | (Unsubmitted, no print-code for SLV3715T)  |
| <b>Validity:</b>           | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>       | Items/values not in reference catalogue are prefixed with an asterisk *.   |

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >