

ASS. REC. BY: Sun Pin

REF:

CS/ASM21003986/Qvf3Veron**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SLX 3668X

Policy No. _____


Claims No. 81M0359T

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: G3E 1239Y Yr Regn: 09/09/2015Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Dyna c.c. 2982Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 172596 T/Radio: Insured / Std / NI / NAEng/No: -C/No: JTFAT35Y10K204975Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/R.m / STD A/Rim or _____Tyre Size: F: 195 R15CR: 195 R15CBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm / R/Bal. 6 mmL/Bal. 6 mm / L/Bal. 6 mmD.O.A. 13/03/2021 D.O.I. 30/03/2021Survey held at Heng Lee.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: 40,000PR: 8,641NV: 31,3596/5/21 LS 8900 Confirmed by email (Recd 12.7.27.59, 5990)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 7/5 - typistReport Format: SMART claimLump Sum / L.B.L. C: 8900/2Days Of Repair: 7

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

SC1G213F0005 / CHENG HOE MOTOR PTE LTD[768761]
 ENTRY DATE & TIME: 15/03/2021 15:36 (SGT)
 SUBMITTED BY: CHIONG BENG CHOON
 VERSION: 1 (15/03/2021 15:36 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	15/03/2021 15:36 (SGT)
Date of Accident	13/03/2021 10:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	UPP EAST COAST ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBE1239Y

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	MASTSCAPE LANDSCAPING
Company Reg No	3XXXX900E
Email Address	MASTLAND99@YAHOO.COM
Mobile Phone No	(Phone) +65-96785391
Alternative Phone No	(Office) +65-96785391

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	TOYOTA DYNA 150 MANUAL
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company	Tokio Marine
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	20-MS009759-R01
Cover Note Number	09/09/20 - 08/09/21

DRIVER

Name of Driver	SUBRAMANIAN KANNAN
Passport No/FIN	GXXXX942L
Date Of Birth	21/05/1984
Occupation	Outdoor

Date Of Driving Pass	03/01/2017
Driving experience	4 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90520462
Alt. Phone Number	-
Email Address	mastland99@yahoo.com
Address	-
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	COLLEAGUE
Gender	Male

PASSENGER 2

Name	COLLEAGUE
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHED. (REPAIR BY HING LEE MOTOR)

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLX3668K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	-
Name of Driver	Private car
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKZ6092C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Private car
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
 2. This Form must be completed by the Policyholder and/or the Authorized Driver
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
 5. Any false reporting may be referred to the Police for investigation
 6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firm/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claim;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firm/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firm/law firms), which may be sited outside of Singapore, for one or more of the above Purposes



Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

(12) and 15/3/21

PLEASE
TURN
OVER

SKETCH PLAN #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Ins: Tokio Marine Vch No: GRE1339Y D.O.A. 13/3/21 10:50am

It was red light. My vehicle was stationary. SLX3668K hit onto my rear portion. The impact pushes my vehicle to hit onto SKZ6092C. It was chain collision of 3 vehicles.

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION
I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.

() Claim Own Policy () Claim Third Party () Reporting Only
(/) Claim ODP/TP at other workshop (Hing Lee Motor)



bp

興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996
TEL : 762 1010, 763 9909 FAX : 760 2724 Email: hinglee@pacific.net.sg

P-1-3

Masts Cape Landscaping

GBE 12394

Date

16/3/21

NO.

1.	Rear tail gate / DD	\$ 1217.45	✓
2.	2 Rear tail gate hinges \$ 177.80 @ /BT.	\$ 355.60	290
3.	Rear No plate panel. / DD.	\$ 371.75	281
4.	Rear LH tail Lamp Assy X / CRA	\$ 249.90	✓
5.	Rear LH tail Lamp panel / BT	\$ 272.10	185
6.	Rear LH Stopper Bracket / CRA / BT	\$ 78.10	✓
7.	Rear LH Stopper Rubber "A" / CRA	\$ 121.10	75.50
8.	Rear LH Stopper Rubber "B" Xsvc	\$ 134.45	X
9.	Rear tail gate "TOYOTA" sticker / NEC	\$ 180.00	N79 S/N
10.	Rear tail gate "DYNA" sticker / NEC	\$ 58.20	✓
11.	Rear end panel XR.	\$ 971.45	X
12.	Rear Exhaust / BT	\$ 991.25	756
13.	Rear spare tyre holder ? / BT	\$ 371.75	✓
14.	front panel. / DD	\$ 1387.75	950
15.	front "DYNA" emblem / NEC	\$ 138.20	72
16.	front logo / NEC	\$ 171.45	71.80
17.	front grille / CRA	\$ 581.90	✓
18.	1 Set front grille clip / NEC S/N	\$ 35.00	✓ S/N
19.	1 front LH head lamp Assy ? / CRA	\$ 932.40	✓
20.	front panel garnish / SCR.	\$ 308.90	✓
21.	front bumper / DD	\$ 441.60	✓
22.	2 R/L front bumper bracket \$ 231.34 @ ? Xsvc	\$ 462.68	X
23.	front windshield rubber / NEC	\$ 358.10	303.70





bp

興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996

TEL : 762 1010, 763 9909 FAX : 760 2724 Email: hinglee@pacific.net.sg

Pg-2

GFE 1239Y

Date 16/3/21 NO.

24	front Head Lamp Assy RH	107, 1 CRA	\$ 932.40	✓
25	front Aircon Blower Housing	7, X SVC	\$ 978.20	X
26	front Aircon Casing Housing	7, X SVC	\$ 2332.10	X
27	Refrig Strap Band	1 BT	\$ 450.00	SN 380.
				S/N
			8,197.60	494.
			-25%	
			6,148.20	





bp

興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996
TEL : 762 1010, 763 9909 FAX : 760 2724 Email: hinglee@pacific.net.sg

Pg.3

Masts Cape Landa Caping
GBE1239Y

Date 16/3/21 NO.

	Labour Charge		
1	To Remove & Refit front w/screen	\$ 120.00	/
2	To Remove & Replace front AirCo System & TO up gas	\$ 160.00	1020
3	To Remove & Refit front Instrument panel	\$ 320.00	300
4	Wiring fee	\$ 50.00	30
5	front no plate cru	\$ 40.00	/
6	Rear no plate cru	\$ 40.00	/
7	Rear taxi gate inner Cover Remove & Refit	\$ 120.00	60
8	spray Painting Damage area front & Rear	\$ 1400.00	1,200
9	To Repair front & Rear Acc Damage Portion	\$ 1500.00	1,100
10	Rear Exhaust Remove & Refit & Repair	\$ 120.00	60
11	Rear "8 pax" Sticker nec	\$ 15.00	/
12	Rear "70 km" Sticker nec	\$ 15.00	/
13	front LH Door Add Sticker nec	\$ 25.00	/

Repair day 7 days

L/S

After pur photo

Sun Pin (HKK)

30/03/2021

TP withn prejud



16,848.78

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



bp

興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996
 TEL : 762 1010, 763 9909 FAX : 760 2724 Email: hinglee@paciflc.net.sg

Acc: MK Sun pin

Masts Cape Lands Caping

GBE 1239 Y

Supplementary.

Date 29/3/21 NO.

1.	Rear LH front gate Lock (side) ✓ BT.	\$ 198.35	✓
2.	Rear 1 Set Sensor ✓ short.	\$ 220.00	SN ✓
3.	front wiper panel cover. XR.	\$ 438.70	X
4.	front panel RH GARNISH ✓ CRA	\$ 571.75	95
5.	Air blower Air hose ✓ def.	\$ 185.00	SN ✓
6.	Rear tyre Bracket Member ✓ BT.	\$ 561.60	380
7.	front cross member. ✓ BT	\$ 443.32	✓
8.	Anti Rust	\$ 80.00	SN 40
9.	front Panel joint Sealant nec	\$ 80.00	SN 50
		2778.72	S/N
		1,116.67	495
		- 25%	
		837.50	
	P = 6,148.20		
	Supr P = 837.50		
	S/N = 494		
	Supr SN = 495		
	L = 3,125		
	11,099.70		
	- 20%		
	8,879.76		
	LIS		
	\$ 8,900		
	4 days		

