

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	24/03/2021 14:29 (SGT)
Date of Accident	23/03/2021 16:04 (SGT)
Exact Location of Accident	Tampines Avenue 2 & Tampines Street 22, Singapore
Additional Location Information	Junction of Tampines Ave 2 and Tampines St 22 After BS76099 >TCI
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBS8518Y
-----------------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	SBS TRANSIT LTD
Company Reg No	1XXXXXXXXXXTE01
Email Address	seahhh@sbstransit.com.sg
Mobile Phone No	(Phone) +65-62444534
Alternative Phone No	(Office) +65-62444534

VEHICLE PARTICULARS

Manufacturer	Scania
Model	KUB4X2, SD, AC, 2 Axle
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Bus
Transmission	Auto
CC	8867

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ActLiability
Fleet Policy	No
Policy Number	D-20095429MFBP
Cover Note Number	-

DRIVER

Name of Driver	Chin Chee Keong
----------------------	-----------------

Passport No/FIN	FXXXX072W
Date Of Birth	09/05/1972
Occupation	Outdoor
Date Of Driving Pass	12/04/2018
Driving experience	2 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-85773722
Alt. Phone Number	-
Email Address	seahhh@sbstransit.com.sg
Address	512 Tampines Central 1
Address complement	Blk 497C Tampines St 45 #06-52 Postal Code : 522497
Postcode	520512
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Parked Vehicle
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	15
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	UNKNOWN
Gender	Male

PASSENGER 2

Name	Norlela Binte Mohd Idris
Gender	Female

PASSENGER 3

Name	UNKNOWN
Gender	Male

PASSENGER 4

Name	UNKNOWN
Gender	Female

PASSENGER 5

Name	UNKNOWN
Gender	Male

PASSENGER 6

Name	UNKNOWN
Gender	Female

PASSENGER 7

Name	UNKNOWN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
 Police Station Name Bedok North Neighbourhood Police Centre
 Police Station Phone No (Phone) +65-18002449999
 Alt. Police Station Phone No (Fax) +65-62447258
 Police Station Address 30 Bedok North Road Singapore 469676
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

When my bus was stationary at the traffic light as it was red light, I felt an impact on my bus rear & heard a loud sound. I then found the GAS bus SBS6511D svc 34 front had hit my stationary bus rear. OCC was informed. One of my passengers who was a female in her 50s informed me her waist area pain but declined my offer for ambulance assistance. CRS was activated & my trip was disrupted. My passengers alighted to other bus. Then my bus RTD back to WS. That's all. Pax : Norlela Binte Mohd Idris (S7003284H)/ 8821 9545

ATTACHMENT(S)

Are accident photos available for attachment? No
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SBS6511D
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Bus
 Name of Driver GAS svc 34 BC11071
 Contact Number -
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage front windscreen shattered, front bumper and left view mirror damaged
 Details of property damaged in accident front windscreen shattered, front bumper and left view mirror damaged
 No. Of Passenger (Including Driver) -

INJURED PERSONS DETAILS

INJURED 1

Name of injured person Norlela Binte Mohd Idris (S7003284H)
 Address -
 Address Complement -
 Post Code -
 Approximate Age Years Old 50
 Injuries Sustained her waist area pain
 Injured person in which vehicle? -
 Were seat belts worn? No
 Was this injured conveyed to hospital by ambulance? No

The Holy Trinity Church

000

St 22

TAMPINS AVE 2

SBS 8518 Y

39

SBS 6511 D

34

BIK 285
Bus Stop



**SINGAPORE
POLICE FORCE**



G/20210323/2117

1 of 2

POLICE REPORT (NP299)

Report No. G/20210323/2117

Police Station Of Origin
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

Date/Time Report Made 23/03/2021 18:44	Vide Report No.	Station Diary No. 116
Name Of Informant CHIN CHEE KEONG	Address APT BLK 497C Tampines Street 45 #06-52 SINGAPORE 522497	
ID Type / ID No. FIN NO / F8264072W	Contact No. Home/Office	Mobile 85773722
Nationality MALAYSIAN	Email Address	
Occupation Bus driver	Sex Male	Age 48
	Date of Birth 09/05/1972	Race Chinese
Institution/School Name	Language English	
Date/Time Of Incident 23/03/2021 16:00 - 23/03/2021 16:00	Location Of Incident TAMPINES AVENUE 2 SINGAPORE Traffic light ^{before} Church of the Holy Trinity, towards Bedok direction, ^{after} Blk 285 Tampines Ave 2 bus stop	

Brief details.

On 23/03/21 at about 1600hrs, I was driving bus service 39 (licence plate: SBS8518Y) ^{towards} away from the bus stop in front of the Church of the Holy Trinity. As I approached the traffic light, which had just turned red, I slowed the bus down gradually before coming to a complete stop. A few moments later however, I felt an impact coming from the rear of the bus. I immediately checked on my passengers. The passenger seated at the rear most seat informed that he is fine, however a female Malay passenger in her fifties, who was

Signature Of Officer Recording The Report: G / Staff Sgt NG ZHENG YANG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 23/03/2021 18:44
Officer In-Charge Of Case: G / Bedok Police Divisional Investigation Branch / Sgt 3 MOHAMED ELFIE BIN MOHAMED AMIN Contact No.: 62447200	Classification Of Case:

Authentication Stamp





SINGAPORE
POLICE FORCE



G/20210323/2117

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20210323/2117

seated at the priority seat at the front of the bus, complained that she felt pain in her waist due to the impact. I asked if she needs an ambulance however she refused.

I then alighted from my bus and saw that a bus with bus service 34 (licence plate: SBS6511D) had collided into the rear of my bus. The damages to my bus are cracks on the rear windscreen, dented rear panel and dented engine cover. The other bus suffered a cracked front windscreen and dented front portion. Subsequently I brought the injured female passenger and other passengers to the next bus stop to board another bus. She gave her name as Norhela Bte Mohd Idris (last 4 digits of NRIC: 284H) and her contact number as 88219545. The other driver informed me that there were no injuries sustained by his passengers or himself. I am lodging this report for my company's record purposes.

Signature Of Officer Recording The Report: G / Staff Sgt NG ZHENG YANG 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 23/03/2021 18:44
Officer In-Charge Of Case: G / Bedok Police Divisional Investigation Branch / Sgt 3 MOHAMED ELFIE BIN MOHAMED AMIN Contact No.: 62447200	Classification Of Case:
Authentication Stamp  	