rennerh .	
	ASSIGNMENT 0
From: Date:	Veh No: 51= 2 3311K Yr Regn: 09, 16
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP WS ITP RES I OD RES I EVALINY MY	Truck / Trailer or (A) Wagen
To Inspect Vehicle No:	Make: Mit APX c.c 1998
al Workshop m/s Alan's	Colour White AC: Insured / Std / NI / NA
of	Sp.Reading 108241 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: JMFX+GA 2WF7-C22368
Ctalms No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inefdet / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
The second secon	Tyre Size: F: 225/55R18
(Policy Condition)	R:
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZA /MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value:	Front
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 3 mm R/Bal. 3 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 3 mm L/Bal. 3 mm
Est Repairs: days Res.: Yes or No	D.O.A. 1/12/20 D.O.I. 26/3/202
Lum Sum: % 3 Val.: Yes or No	Survey held at
OL L DEL L DED L CALLED	Des. of Damages : Frt Rear OIS NIS UIC Rooftop or
CA / REV / REP. / 24 HRS Vehicle: Person Contacted:	The U/C / Chassis frame & Body Structure affected due to collision.
Date: Person Contacted: Vehicle: Date / Time Action / Instruction	IN/OUT & Roy
Date: Person Contacted: Vehicle: Date / Time Action / Instruction T/Loss	The U/C / Chassis frame & Body Structure affected due to collision.
Date / Time Action / Instruction T/Loss MV & 62/6	The U/C / Chassis frame & Body Structure affected due to collision.
Date: Person Contacted: Date / Time Action / Instruction T/Loss Mr. B. 62/6 LtA nhau 8 46, 2	The U/C / Chassis frame & Body Structure affected due to collision.
Date: Person Contacted: Date / Time Action / Instruction T/Loss Mr. B. 62k LTA nhau 8 46, 2 Bay 8 15 7	The U/C / Chassis frame & Body Structure affected due to collision. L
Date: Person Contacted: Date / Time Action / Instruction T/Loss Mr. B. 62/6 LtA nhau 8 46, 2 Bay 8 15 7	The U/C / Chassis frame Dody Structure affected due to collision.
Date: Person Contacted: Date / Time Action / Instruction T/Loss Mr. B. 62/6 LtA nhau 8 46, 2	The U/C / Chassis frame Dody Structure affected due to collision.
Date: Person Contacted: Date / Time Action / Instruction T/Loss Mr. B. 62/6 LTA nhau 8 46, 2 Bay 8 15 7	The U/C / Chassis frame Dody Structure affected due to collision.
Date: Person Contacted: Date / Time Action / Instruction T/Loss Mr. B. 62/6 LTA nhau 8 46, 2 Bay 8 15 7	The U/C / Chassis frame & Body Structure affected due to collision. L
Date: Person Contacted: Date / Time Action / Instruction T/LOSS Mr. B. 62/6 LTA nhau B. 46, 2 Bal B. 15, 7 Zavoice bill to owner	The U/C / Ghassis frame & Body Structure affected due to collision. L 53 47 Circly Quelt I his Pers
Date: Person Contacted: Date / Time Action / Instruction T/LOSS MW & 62/6 LA nhau & 46,2 Bal & 15,7 Javoice bill to owner Data/Time, File Pass 107 : Prell. Report	The U/C / Chassis frame & Body Structure affected due to collision. L
Date: Person Contacted: Date / Time Action / Instruction 7/Loss Mw & 62/6 LtA nhau & 46,2 Bay & 15,7 Zavorce bill to owner Date/Time, File Pass to? : Prell. Report : Final Report	The U/C / Ghassis frame & Body Structure affected due to collision. L 53 47 Circly Quelt I his Pers
Date: Person Contacted: Date / Time Action / Instruction 7/Loss Mw & 62/6 LtA nhau & 46,2 Bay & 15,7 Zavorce bill to owner Date/Time, File Pass to? : Prell. Report : Final Report	The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. Const. The U/C / Ghassis frame & Body Structure affected due to collision. The U/C / Ghassis frame & Body Structure affected due to collision. The U/C / Ghassis frame & Body Structure affected due to collision. The U/C / Ghassis frame & Body Structure affected due to collision. The U/C / Ghassis frame & Body Structure affected due to collision. The U/C / Ghassis frame & Body Structure affected due to collision. The U/C / Ghassis frame & Body Structure affected due to collision. The U/C / Ghassis frame & Body Structure affected due to collision. The U/C / Ghassis frame & Body Structure affected due to collision. The U/C / Ghassis frame & Body Structure affected due to collision. The U/C / Ghassis frame & Body Structure affected due to collisi
Date: Person Contacted: Date / Time Action / Instruction T/Loss Mr. B. 62/c LtA nhau B. 46, 2 Bal B. 15, 7 Zavoice bill to owner Date/Time, File Pass to? : Prell. Report Cite/Time, File Return to?	The U/C / Ghassis frame Body Structure affected due to collision. L 53 47 Cinal Quelc I hi Pen Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportative
Date: Person Contacted: Date / Time Action / Instruction T/Loss Mr. B. 62/6 LtA nhau 8 46, 2 Bay 8 15, 7 Zaverce bill to owner Pate/Time, File Pass to? : Preli. Report Cute/Time, File Return to?	The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affected due to collision. Legarity The U/C / Chassis frame Leody Structure affe
Date: Person Contacted: Date / Time Action / Instruction T/LOSS MV B 62/6 LTA nhau B 46, 2 Bal B 15, 7 Zavorce bill to owner Prell. Report Final Report Sule/Time, File Return to?	The U/C / Chassis frame & Body Structure affected due to collision. Collision
Date: Person Contacted: Date / Time Action / Instruction T/LOSS W & 62/6 LtA nhau & 46, 2 Bal & 15, 7 Zavorce bill to owner Prell. Report State/Time, File Pass to? : Final Report Cute/Time, File Return to?	The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affected due to collision. L The U/C / Chassis frame Body Structure affect
Date: Person Contacted: Date / Time Action / Instruction T/LOSS MV B 62/6 LTA nhau B 46, 2 Bal B 15, 7 Zavorce bill to owner Prell. Report Final Report Sute/Time, File Return to?	The U/C / Chassis frame & Body Structure affected due to collision. Collision

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No.: 06293

Vehicle Insured: GBA7C

Accident Date : 01-Dec-2020

Date : 03-Dec-2020

Our Ref : 020172 (NTUC) / CHAN

PAGE: 1

CINDY QUEK HUI PENG BLK 165 HOUGANG AVE 1 Not Motherise

#06-1598

Singapore 530165

Usy 8? Thos

ESTIMATED COST OF REPAIR FOR MIT. ASX SFE3311K

		R and an
1 p	c Tail	gate (4.00 - 1,014.00 -
1 p	c Tail	gate glass Sherror 826.00 —
		gate glass moulding
1 p		gate inner leak
1 p		gate rubber 175.00 50 100
		72 455 00 —
		gate wiper arm 189.00 kg
		gate top centre trim P/7 85.00
		gate top side trim @ S\$ 66.00 % 132.00 —
1 p	c Tail	gate inner trim cover
2 n	ce Tail	gate damper @ S\$178.00 356.00 /
2 p	cs Tail	gate lamp 6/1 M (M) MISSANG S\$289.00 578.00
2 D	cs Tail	gate license plate lamp @ S\$ 31.00 62.00
1 p	c Tail	gate open sensor 195.00 7
		gate open pocket nu 65.00
		gate 10go
2 n	re Rear	fender 37/80 , @ \$\$827.00 1.654.00
2 p	re Rear	fender inner trim 4/1 Defm. @ S\$676.00 0/371,352.00
2 D	re Rear	fender arch garnish @ S\$185.00 9cc/07370.00
2 0	ce Rear	fender inner shield MICH @ S\$ 58.00 116.00
		n/s fender inner panel R 380.00 X
		er garnish @ S\$488.00 976.00 7
		n/s fender pertol lid
		n/s inner top panel / 165.00 X
		n/s inner arch panel A 140.00
2 5	c Real	quater glass c/w moulding @ S\$450.00 % 900.00
		fender air duct @ S\$ 37.00 74.00 7
z p	CS TAIL.	lamp olimi can wish @ \$\$588.00 1,176.00

Con't Page 2 ...

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBA7C Page : 2

		الم	R	
2	pcs	Taillamp corner panel (top)	^	
2	pcs	Taillamp corner panel (lower)	a	\$\$155.00 \$\$175.00 4/14 350.00
2	pcs	Taillamp side clip	ē	S\$ 5.00 10.00
	pc	Rear bumper fascia		780.00
2	pcs	Rear bumper side retainer	@	S\$ 34.00 % 68.00
1	pc	Rear bumper reinforcement	·	R 270.00
2	pcs	Bumper reinforcement bracket	0	S\$ 65.00 Ry 130.00
1	pc	Rear bumper tow cover		7, 14.00
		Rear bumper clip	@	
	pc	Rear spare tyre panel		4 1,138.00
1	-	Rear spare tyre board		428.00
	pc	N/s spare tyre panel extension		980.00 7
	pc	Rear centre cross member		280.00 7
1	рc	Rear end panel		340.00
2	pcs	Rear end panel side panel	9	S\$ 28.00 % 56.00 ~
	pc	End panel top garnish		- No 175.00 V
	pc	Spare tyre panel tray		2M 319.00
	pc	Rear compartment top cover		Pri 650.00 —
	pc	Rear compartment front garnish		Or 190.00 -
	pc	Rear o/s tool sponge		165.00 7
	pc	Rear o/s tool sponge tray		115.00 7
	pc	Rear n/s tool sponge		170.00 ?
		Rear n/s tool sponge tray		160.00 7
	pc	Rear spare tyre round cover		170.00 ?
	pc	Rear exhaust silencer box	•	458.00 -
1	pcs	Rear exhaust box mounting	6	S\$ 35.00 % 70.00 ~
	pc	Rear exhaust chrome pipe		20 57.00 W
		Rear exhaust heat seal Centre exhaust box		184.00 —
		Centre exhaust heat seal		A 1,866.00 —
		Front w/s glass		95.00 ?
	pc	Front w/s glass		cm 1,173.00 —
	pc	Front w/s glass moulding Bonnet		158.00 —
	pc	Bonnet inner lock		786.00
		Bonnet insulator		Pri 89.00 -
		Bonnet insluator clip	a	160.00 X
2	pcs	Bonnet side rubber	0	
	pc	Bonnet rubber	9	
				601 35.00 U

Con't Page 3 ...

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.
Tel: 6453 8686 (3 Lines) Fax: 6459 6550
Company Reg. No.: 201113667N
GST Reg. No.: 201113667N

Vehicle Insured: GBA7C Page: 3

```
2 pcs Bonnet hinge
                                                    122.00
                                      @ S$ 61.00
 2 pcs Headlamp
                                  CM @ S$781.00
                                                  1,562.00
 2 pcs Headlamp lower bracket
                               NIJEM @ S$ 75.00
                                                    150.00
                                                 By 180.00 L
 2 pcs Headlamp top panel clin
                                 MJ @ S$ 90.00
1 pc
       Front top panel
                                                  M 384.00 -
      Front top panel guide
                                                  nd 59.00 -
1 pc
      Front support lower member
1 pc
                                                     362.00 7
2 pcs Lower member side bracket
                                      @ S$ 37.00
                                                     74.00 7
1 pc
      Radiator
                                               Ku 1,038.00 -
1 pc
      Radiator fan colwing
                                                 cm 245.00
1 pc
      Radiator fan motor
                                                  Ja 423.00
                                                  01 67.00
1 pc
      Radiator fan blade
      Radiator top hose (short)
1 pc
                                                  In 47.00 X
      Radiator top hose (long)
1 pc
                                                  102.00 X
      Radiator hose adapto joint
1 pc
                                                     82.00 7
                                                  mi7 29.00
1 pc
      Adaptor joint bracket
                                                  57.00 ×
1 pc
      Radiator lower hose
                                                1,023.00
1 pc
      Air con condenser
                                                 7h 423.00
1 pc
     Air con condenser fan motor
     Air con condenser fan blade
1 pc
                                                      67.00
     Air con discharge hose
                                                 M 187.00
1 pc
1 pc
     Air con liquid pipe
                                                     191.00 7
1 pc
     Air con suction hose
                                                     249.00 7
1 pc
                                                    239.00
      Radiator grille base top
                                                 cm 287.00
     Radiator grille lower
1 pc
                                                  cm 759.00
     Radiator grille chrome
1 pc
                                               1811 CM 855.00
1 pc
     Front bumper fascia
                                                   48.00
     Front bumper top beam
1 pc
                                                  By 373.00
     Front bumper reinforcement
2 pcs Front bumper side sponge
                                      @ S$ 59.00 cm 118.00 \
                                                   <sup>nd</sup> 28.00
    Front bumper top cover
2 pcs Front bumper foglamp
                                      @ S$393.00
                                                     786.00 7
2 pcs Front bumper day runing light
                                                   1,320.00 7
                                      @ S$660.00
                                                     290.00 4
2 pcs Front fender arch garnish MJ 4 @ S$145.00
                                                  10 169.00 -
     Front bumper under cover
1 pc
     Air cleaner housing cover
1 pc
                                                     132.00 7
1 pc Air cleaner housing duct
                                                  N 140.00 -
1 pc Rear n/s shock absober
                                                     247.00 ?
```

Con't Page 4 ...

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBA7C	Page : 4
<pre>1 pc Rear n/s lower arm 1 pc Rear n/s knuckle arm 1 pc Rear n/s knuckle bearing hub 2 pcs Rear stabiliza bar link 1 pc Rear cross member</pre>	136.00 7 470.00 7 423.00 7 0 S\$ 96.00 192.00 7 1,118.00 7
	40,067.00 Less 10%: 4,006.70
1 pc Rear bumper top plate 1 pc Rear w/s glass sealant 1 pc Rear no.plate with box 1 pc Rear bumper reverse sensor 1 pc In car camera (front & rear) 2 pcs Rear quater glass sealant 1 pc Front w/s glass sealant 1 pc ERP IU bracket 1 pc Radiator coolant 1 pc Front no.plate with box 1 pc Front w/s glass solar film	36,060.30 Ay 180.00 sn Au 40/ 60.00 sn Al 45/N 50.00 sn Al 5/N 50.00 sn Au 1 350/ 450.00 sn Au 350/ 60.00 sn Au 40/ 60.00 sn Au 25.00 sn Au 25.00 sn Au 25.00 sn Au 25/N 50.00 sn Au 20/ 300.00 sn Au 20/ 300.00 sn
To rewire damaged parts and refocus headlamp beam.	50.00 401
To remove & renew front windscreen glass and conduct water leak test.	150.00 12d
To remove & renew rear windscreen glass and conduct water leak test.	150.00 1201
To remove roof lining, front and rear seats, trim board and carpet	280.00 180
To remove air con condenser, pipes and drier, vacuum and to recharge gas	120.00 'Ool

Con't Page 5 ...

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642. Tel: 6453 8686 (3 Lines) Fax: 6459 6550 Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured: GBA7C

Page: 5

To apply undersealing

300.00

To dismantle and lower rear undercarriage

2001 250.00

2101

To check and adjust wheel alignment

65.00 -

To remove and renew exhaust silencer box (rear & centre)

1001 120.00

To putty and spray replaced parts

220d 2,600.00

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

2800/ 3,200.00

OWNER REQUEST FOR GENUINE PARTS FOR THE REPAIR

Total:

S\$44,930.30

=========

Singapore Dollars Forty Four Thousand Nine Hundred and Thirty and Cents Thirty Only

uire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	832Z
Vehicle Details	
Vehicle No.:	SFE3311K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Dec 2020
Vehicle Make:	MITSUBISHI
Vehicle Model:	ASX 2.0 CVT ABS D/AIRBAG 2WD
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4B11RY3637
Chassis No.:	JMFXTGA2WFZC22368
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$18,690.00
Original Registration Date:	29 Sep 2016
irst Registration Date:	29 Sep 2016
Fransfer Count:	0
Actual ARF Paid:	\$18,690.00
ntended PARF Rebate Details	\$10,070.00
ARF Eligibility:	Yes
ARF Eligibility Expiry Date:	28 Sep 2026
ARF Rebate Amount:	\$14,017,00
ntended COE Rebate Details	
OE Expiry Date:	28 Sep 2026
OE Category:	B - Car above 1600cc or 97kW (130bhp)
OE Period(Years):	10
P Paid:	\$55,501.00
OE Rebate Amount:	\$32,236.00
otal Rebate Amount:	\$46.253.00

RMART.COM

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Login Sign up

Forum

Resources



Mitsubishi

Price Range

➤ Depreciation ➤ Year Reg ➤ SUV

Home » Used Cars » Ka-Hup Vehicles Trading » Mitsubishi ASX 2.0A

Mitsubishi ASX 2.0A

Financial

Similar

60.153



*preciation (?)

KA-HUP ESTABLISHED SINCE 1989





Price \$64,800

> \$8,930 /yr View models with similar depre

Reg Date

30-Mar-2017 (6yrs 3mths 22days COE left)

Mileage

58,138 km (15.7k /yr)

\$46,339 as of today (change)

Manufactured (?)

2017

Road Tax (?) Dereg Value ②

\$1,210 /yr

Transmission

Auto \$16,945

\$53,300

OMV ② ARF ⑦

\$16,945

Engine Cap

COE ②

1,998 €

110.0 kW (147 bhp)

Curb Weight (?)

1,417 kg

No. of Owners (?)

Type of Vehicle

SUV

Features

Reliable 2.0L DOHC Engine, 147Bhp,6 Speed Auto W/ Paddle Shifters, ABS, Airbags, Cruise Control, Keyless Fntry/Start-Stop,Auto Headlights/Rain Sensors. View specs of the Mitsubishi ASX (2014-2017)

Accessories

18" Sports Rims, Dual Tone Leather Seats, Factory Fitted Audio With Navigation/Bluetooth/Reverse Camera/Sensors, Steering Audio Control, Solar Film.

Description

Talk To Us Now, You Do The Price Negotiation. Sell At Low Depreciation Below \$9K. Excellent Condition.100% Accident Free!Well Taken Care Unit+Regular Serviced C&C 58,138Km Done By 1 Owner. View To Offer Your Price We Will Match.

Category

PARF Car, Premium Ad Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Find out the market value of your existing car for free. Get started



Ised Car Warranty

Compare [3]

nty for \$0 future car repair bills. Learn more

https://www.sgcarmart.com/used_cars/info.php?ID=936563&DL=1026
















Shortlist Report Error More Actions

Seller Information

Ka-Hup Vehicles Trading

51 vehicles for sale. 73 sold in past 3 mths

Q 61 Ubi Avenue 2 #03-17 Automobile Megamart Tel: 67415939 Search cars nearby

DJ Lim

82333664 🕒

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material racus may allow miscurate.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDEN	T STATEMENT
Date of Submission	TOTAL STATE OF THE
Date of Accident	03/12/2020 11:34 (SGT)
Sacr Eucation of Accident	01/12/2020 13:10 (SGT)
Jditional Location Information	Near Braddell Flyover, Singapore
Country/State of Loss	CTE towards AYE (10km) Singapore
DETAILS OF	F OWN VEHICLE
Vehicle Registration Number	SFE3311K
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CINDY QUEK HUI PENG
NAIC NO	SXXXX832Z
Email Address	DAVEMING29@GMAIL.COM
Mobile Phone No	(Phone) +65-98893311
Alternative Phone No	+65-98893311
VEHICLE PARTICULARS	
`anufacturer	Mitsubishi
vlodel	Asx
ariant	
exact purpose for which vehicle was being used at time of	
ccident	Private use
ve you claiming under your own insurance policy for repair to	
our vehicle?/ehicle Category	No - Claiming third party
since dategory	Private car
INSURANCE COMPANY	
ame of Insurance Company	ECICS
ype of Coverage	Comprehensive
leet Policy	No
olicy Number	MPC20P00148400
Cover Note Number	
DRIVER AND THE STATE OF THE STA	
ame of Driver	TEO JIUN MENG
RIC No	SXXXX720H
	10/09/1978
ate Of Birth	
ate Of Birth	Indoor Page 1 of 18

address	
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-
	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	
Vehicle Manufacturer	SHA9366K
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	. •
Nome of D.:	Taxi
Contact Number	-
Address	-
Address complement	•
Doctorde	-
	-
Insurance Company Name	
rature Of Damage	
Details of property damaged in accident No. Of Passenger (Including Driver)	_
no. or rassenger (including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	
1.	SFF1715L
Vehicle Medal	-
Vobiala Votiant	-
Vehicle Colour	-
Vobiolo Cotono	•
Name of the state	Private car
Contact Number	•
A	
Address	
D	-
	•
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	
'O Of Passanger (Including Daise)	
5. Of Passenger (including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	01440000
Vehicle Manufacturer	SMK8293G
Vehicle Model	•
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Private car
Contact Number	-
Address	-
Address complement	- × × × ×
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-
NO UT PASSEDOET UNCHOING LINVAY)	

INJURED PERSONS DETAILS



IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

			with the tenth of the tenth of the tenth of the
A= SFE3311k		and the property of the property of the property of	or from the form to design the first of the first of the
77 77 7211	LTE +01	wards ME (Before	Braddell zxit)
		وليد نهيد زوي والإرشاء والأولية والمنافرة والمدولية والمؤثث مؤدا والمواضية	many many many in franchistic franchisti franchistic franchistic franchistic franchistic franchistic franchistic franchistic f
B= GBATC	-1″t-1 -1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1		
hala be to the ford of the first of	angerest in the of a finisher than special and in the ad-	o Koke Kal	n D
C = SHA9366K			
	constant a feet of the first of the		
entratario de la finale de la contratario del contratario de la contratario de la contratario della co	and the best of th		
DE SFF 1719L			
12301775			
E- SMK 82936			ETTITITITITI
	and the state of t	- francisco francisco francisco francisco	
		and an interest and the second	-14- harmon but in finite fraction for the
	and advantage of mining a few front		a fra frankrig frigher fright
to the first of the fact of wind of the		and overgraphy and make it is a first over the	and and another of marks a special point for adjust of the forest constitution of
Landinate of hind and weather the wife in the wife and a straight and	بالبيد والمستهدية ويتناه سيسة ستساهنوه بالجدر يرماك معالما يديو فادم بمكر بسيار نبي	in the land of the street of the former of the street	where he of the printer is not printer of a copy of the printer where the ist

Accident report SA0W20C30002

Page 5 of 18





Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

1 of 3 Report No. T/20201202/7006

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/12/2020 10:45		Vide Report No.: F/20201201/0116	Station Diary No.:	
Informan	t's Particu	lars -	2011年12日1日 12日 12日 12日 12日 12日 12日 12日 12日 12	to pre-citizento de 1861.
Name of I TEO JIUN	nformant:		Address: 165 HOUGANG AVENUE 1	#06-1598 SINGAPORE 530165
ID Type / NRIC NO	ID No.: / S782672	20H	Contact No.: Home/Office:	Mobile: 83663311
Nationalit SINGAPO	y: ORE CITIZ	EN	Email: DAVEMING29@GMAIL.COI	M S S S S S S S S S S S S S S S S S S S
Sex: Male	Age: 42	Date of Birth: 10/09/1978	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation Sales and profession	d related as	ssociate	Driving Licence Information: Class: 3	Date of Expiry:

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 01/12/2020 13:10	Type of Location: expressway
Location: CTE (AYE)	10km			er 4 Jahre
	CHARLES AND AREA OF	and the same of th	(na.), her 35 3 m	Marintal Maridae
Weather:	Case Case Case Case Case Case Case Case	Road Surface: Dry		Road Speed Limit: 0 Km/h
Weather: Clear Traffic Flow: One Way	Total Dimini	News	6 T	

Vehicle No.	Type	Make	Model	Color	Conditio	No of
SFE3311K	Car	MITSUBISHI	ASX	White	Totally Damaged	0
	Car					0
A	Van			7.	N	0



2 of 3

Report No. T/20201202/7006

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Vehicle No.	Type	Make	Model	Color	Conditio	No of
	Car					0
	Car					0
	Car				- 1	0
	Car					0

Thaiso N	hicle insurance		A Constitution of	The second of th
Vehicle No.	Insurance Company	Insurance No 🛶	and the state of t	
SFE3311K	ECICS LIMITED	mpc20p00148400	29/09/2020	28/09/2021

No. of Pedestrians injured. The			Use of Pe	Use of Pedestrian Crossing: NA			
Driver Name	TEO JIUN MENG			ID No.		S7826720H	
Related Vehicle	SFE3311K (Car)		Contact No.		83663311		
Hospital/Clinic	SENGKANG GENE LTD.	RAL HOSP	PITAL PTE.	Class of Driving Licence Expiry		Class: 3 Date of Expiry: NIL	
	01/12/2020		Date		02/12	/2020	

travelling along cte on left lane about to exit to pie (changi), the vehicles and taxi infront emgency brake and manage to slow and stop immeditaly but got by the van behind me with impact.upon on site TP officer approval my appointed workshop towtruck is allowed to towed my vehicle to workshop and i proceed to sengkang hospital for treament.