



ESTABLISHED 1984

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556
ATTN: CHARLOTTE CHEW

Ref: CS/INC21004046/Uqf3n2
Date: 12/04/2021
Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLW 8106M	Veh. Inspected	SMP 5026E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1126208-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	30/03/2021

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	RU11320310	Colour	WHITE
Odometer	65311 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/03/2021	Inspect Date / Time	30/03/2021 (11:36 AM)
Survey held at	15 KAKI BUKIT ROAD 4, BARTLEY BIZ CENTRE, #01-53		
Repairer	ZOOM AUTOWERKS PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------