

(08/11/13) wef

ASS. REC. BY: marcus

REF:

CS / ASM21004051/49c**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / FP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: FBR 645Xat Workshop m/s swfu

of _____

Insured: SHD5275A

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$17k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 3905

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBR 645XYr Regn: 11/2/20Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha C2D300A XMAX c.c. 292Colour: Black A/C: Insured / Std / NI / NASp. Reading: 15845 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH3SH084XKK009256Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 120/70-15R: 150-70-14 P.R

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 22/3/21 D.O.I. 30/3/21

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Frt, o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$) _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 633B

Vehicle Details

Vehicle No.: FBR645X
Vehicle to be Exported: No
Intended Deregistration Date: 26 Mar 2021
Vehicle Make: YAMAHA
Vehicle Model: CZD300A / XMAX300
Primary Colour: Black
Manufacturing Year: 2019
Engine No.: H336E0067463
Chassis No.: MH3SH084XKK009256
Maximum Power Output: -
Open Market Value: \$4,311.00
Original Registration Date: 11 Feb 2020
First Registration Date: 11 Feb 2020
Transfer Count: 1
Actual ARF Paid: \$647.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 10 Feb 2030
COE Category: D - Motorcycle
COE Period(Years): 10
QP Paid: \$4,400.00
COE Rebate Amount: \$3,905.00
Total Rebate Amount: \$3,905.00

The information contained herein is correct as at 25 Mar 2021

OK

Yamaha Xmax 300 (/listing/usedbike/yamaha-yamaha-xmax-300/20035/)



(/listing/usedbike/yamaha-yamaha-xmax-300/20035/)

SGD\$15800

Reg : 26/10/2018

Type: Scooters

292cc

6880km

Fully Stock. Low Mileage. Parked Under Shelter.

Posted on : 22/02/2021

★ DIRECT SELLER

DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-XMAX-300/20035/) ■ COMPARE

Yamaha Xmax 300 (/listing/usedbike/yamaha-yamaha-xmax-300/19962/)



(/listing/usedbike/yamaha-yamaha-xmax-300/19962/)

SGD\$16000

Reg : 29/02/2020

Type: Scooters

292cc

22000km

Yamaha Xmax 300 For Sale. Using Continental Contischoot Tyre. Whatsapp For More Details.

Posted on : 14/02/2021

★ DIRECT SELLER

DETAILS > (/LISTING/USEDBIKE/YAMAHA-YAMAHA-XMAX-300/19962/) ■ COMPARE

Yamaha Xmax 300 (/listing/usedbike/yamaha-yamaha-xmax-300/19882/)



(/listing/usedbike/yamaha-yamah

SGD\$17000

Reg : 29/10/2019

Type: Scooters

292cc

3486km

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Email: erofia@singnet.com.sg

AXA

Name : Muhammad Hamim Bin Hussien

Accident Date : 22-Mar-21

Vehicle No : FBR645X

Yamaha
Vehicle Model : CZD300A /
XMAX300

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
1	Front fork assy <i>snx</i>	\$ 980.00
1	Front sport rim <i>nx</i>	\$ 550.00
1	Front brake disc <i>nx</i>	\$ 180.00
1	Front rim shaft <i>nx</i>	\$ 52.00
1	Front rim slider (1 set) <i>nx</i>	\$ 165.00
1	Side mirror <i>snx</i>	\$ 180.00
1	Handle bar <i>nx</i>	\$ 135.00
1	Handle bar balancer (1 set) <i>cnx</i>	\$ 80.00
1	Brake lever <i>cnx</i>	\$ 52.00
2	Front fender side cover <i>o/s cnx 1pc</i>	\$ 320.00
2	Front signals <i>o/s cnx 1pc</i>	\$ 150.00
2	Footstep panels <i>cnx 1pc</i>	\$ 310.00
2	Rear handles <i>nx</i>	\$ 170.00
1	Rear slider (1 set) <i>cnx</i>	\$ 300.00
1	Exhaust cover <i>nx</i>	\$ 170.00
1	Fairing cover (1 set) <i>cnx</i>	\$ 1,150.00
		\$ 4,944.00
	Less 10%	\$ 494.40
		\$ 4,449.60

Special Net Items

2	Fork oils <i>nx</i>	\$ 30.00
2	Fork oil seals <i>nx</i>	\$ 56.00
1	Steering cone (1 set) <i>nx</i>	\$ 120.00
1	Number plate (1 set) <i>nx</i>	\$ 28.00
1	"X MAX" emblem <i>nx</i>	\$ 60.00
		\$ 294.00

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Email: erofia@singnet.com.sg

Name : Muhammad Hamim Bin Hussien

Accident Date : 22-Mar-21

Vehicle No : FBR645X

Yamaha
Vehicle Model : CZD300A/
XMAX300

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service (LOD)	\$ 120.00 50
2	To check wiring and reset headlamp focusing	\$ 11 80.00 X
3	To provide labour	\$ 480.00 280
4	To respray painting	\$ 800.00 450
5	To repair body frame	\$ 11 450.00 X
		<u>\$ 1,930.00</u>
Grand Total		<u>\$ 6,673.60</u>

Singapore Dollars: Six Thousand Six Hundred Seventy-Three and Cents: Sixty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIKE RECOVERY SERVICE

HP: 8298 6622

Business Reg. No: 201216510M

CASH SALE

NO: 01679

Date: 23/3/21

Particular: _____

Vehicle No: FBR 645X Model No: X MAX

From: LORZI Geyloun To: Idal TO EROFA

Time: (Day/Night): _____

Others: _____

CASH \$: 50/-

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or others misdemeanour to your vehicle while being towed.