



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving TPVD Yamaha CZD300A (FBR645X)

Date of Loss 22 March 2021

Time of Loss 18.00

Loss Description SHD5275A C/W FBR645X (TP)

Comment

### Workshop Details

Total Rebate Amount 3905

Nett Loss Amount \$13,095.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work completion \* 20



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details   Vehicle & Driver Details   Vehicle Condition   Taxes & Ratio   Parts & Labour   Miscellaneous   Summary

## Vehicle & Driver Details



Vehicle Registration#	FBR645X	Purchase Date	<input type="text" value="dd/mm/yyyy"/>
Registration State	<input type="text" value="SINGAPORE"/>	Registration Date *	<input type="text" value="11/02/2020"/>
Mileage	<input type="text" value="15845"/>	Age of Vehicle	1

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<input type="text" value="2019"/>
Make	TPVD Yamaha	<input type="text" value="YAMAHA"/>

### Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	MUHAMMAD HAMIM BIN HUSSIEN	<input type="text"/>
Date of Birth	7 November 1990	<input type="text" value="dd/mm/yyyy"/>

Model CATEGORY	CZD300A POLICY INFORMATION	CZD300A / XMAX300 ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="MH3SH084XKK009256"/>
Engine No		<input type="text" value="H336E0067463"/>
Engine Capacity		<input type="text" value="292"/>
Sum Insured		<input type="text" value="0"/>
Market Value		<input type="text" value="17000"/>

CATEGORY Age	FNOL INFORMATION 30	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Unknown	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	S9041633B	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Detailed Assessment

Inspection Date \*

30/03/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver  
Excess

0

### Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake  
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres	<input type="text"/>	Spare wheel	<input type="text"/>
Front Tyre Size	<input type="text" value="120/70-15"/>	Rear Tyre Size	<input type="text" value="150-70-14"/>
Front left side	<input type="text" value="PIRELLI6mm"/>	Rear left side	<input type="text" value="PIRELLI6mm"/>
Front right side	<input type="text"/>	Rear right side	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="10"/>	Settlement%	<input type="text" value="100"/>

## Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save







SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts










Add




Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		FRONT FORK ASSY	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT SPORT RIM	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT BRAKE DISC	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT RIM SHAFT	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		SET FRONT RIM SLIDER	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		SIDE MIRROR	Broken	0	180	No		10			162	Reviewing

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		HANDLE BAR	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		HANDLE BAR BALANCER O/S	Cut	0	35	No		10			31.5	Reviewing
<input type="checkbox"/>		0	1		BRAKE LEVER	Cut	0	52	No		10			46.8	Reviewing
<input type="checkbox"/>		0	1		FRONT FENDER SIDE COVER N/S	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT FENDER SIDE COVER O/S	Cut	0	120	No		10			108	Reviewing
<input type="checkbox"/>		0	1		FRONT SIGNAL N/S	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT SIGNAL O/S	Damaged	0	65	No		10			58.5	Reviewing
<input type="checkbox"/>		0	1		FOOTSTEP PANELS (2PCS)	Cut	0	155	No		10			139.5	Reviewing
<input type="checkbox"/>		0	2		REAR HANDLES	Serviceable	0	0	No		10			0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		SET REAR SLIDER	Cut	0	180	No		10			162	Reviewing
<input type="checkbox"/>		0	1		EXHAUST COVER	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		SET FAIRING COVER	Cracked	0	900	No		10			810	Reviewing


Labour

Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TO PROVIDE TOWING SERVICE (LOD)	0	50	0	0	Reviewing	
<input type="checkbox"/>		0		TO CHECK WIRING AND RESET HEADLAMP FOCUSING	0	0	0	0	Deny	
<input type="checkbox"/>		0		TO PROVIDE LABOUR	0	280	0	0	Reviewing	
<input type="checkbox"/>		0		TO RESPRAY PAINTING	0	450	0	0	Reviewing	
<input type="checkbox"/>		0		TO REPAIR BODY FRAME	0	0	0	0	Deny	



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary








Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 4 DAYS	Reviewing		0		
<input type="checkbox"/>		0	FORK OILS (2PCS)	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	FORK OIL SEALS (2PCS)	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		-	1 SET	-	-	-	NOT	

	 EDIT	0 SR NO	STEERING NAME	Deny ACTION	ESTIMATED AMOUNT	0 ADJUSTED AMOUNT	NECESSARY COMMENT	 REMOVE
<input type="checkbox"/>		0	1 SET NUMBER PLATE	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	"X MAX" EMBLEM	Deny		0	NOT NECESSARY	



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount

\$0.00

Adjusted Claim Amount

\$2,298.30

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$1,518.30
Labour	\$0.00	\$780.00

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	FINAL LUMP SUM	Reviewing	1800		



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount

\$0.00

Adjusted Claim Amount

\$1,800.00

CATEGORY

ESTIMATE

ADJUSTED

Miscellaneous

\$0.00

\$1,800.00

Submit for Review