

ASS. REC. BY: Steve REF: CS / AIG 21004952 / EA F3

ASSIGNMENT

SME 2357C

Yr Regn: 24/9/18

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 1800109811-01

Claims No. 9795007515SG

Sum Insured: _____ Excess: 600

(Client's Record)

Make of Veh: _____

Veh No: _____

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: Mitsubishi Attrage c.c. 1193

Colour: Red A/C: ☐ Insured / ☐ Std / ☐ N / ☐ N

Sp. Reading: 7105 T/Radio: ☐ Insured / ☐ Std / ☐ N / ☐ N

Eng/No: _____

C/No: MMB5TA13AJ1-1923 944

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☐ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☐ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: ☒ Nil / ☐ S/R / ☐ STD A/R / ☐ or

Tyre Size: F: 185/55R15

R: _____

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm


D.O.A. 28/3/21 D.O.I. 30/3/21

Survey held at cycle & college

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S ☒ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

MV-SSK

30/03/21 @ 5pm revert to AIG via Merimen.

30/03/21 @ 8.07pm Kok Chong informed C/A via Merimen.

31/03/21 @ 10.18am Informed Edwin C/A & ex: \$600 by email.

20/04/21 @ 12.29pm confirmed with Larry final fig \$4037.96, 7 days. (Red \$4010.46, 50%)

Date/Time, File, Pass to?

☐ : Prel. Report

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

Approved: MER-OD

Net Sum / L.F. : 4037.96



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV09356/ANG HWE KHENG Reg No/Reg Date SME2357C / 24/09/201 Date In/Mileage / 0 Chassis No MMBSTA13AJH003044 Engine No 3A92UHG4358 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	29/03/2021/ 17:25	BLE	261 / Edwin Caina	64574		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW LHR DOOR , RR BUMPER & RR BUMPER BODY KIT REPAIR LHF DOOR & LHR FENDER				1 1/2 + 80			1205 2700.00
E PNT98000 RESPRAY LHF DOOR , LHR DOOR , LHR FENDER , RR BUMPER & RR BUMPER BODY KIT				5 x 350			1750.00
E PNT88000 REMOVE & REFIT LHR DOOR COMPONENT							120.00
E PNT88000 REMOVE & REFIT RR FLR BOARD , TRIM, CARPET & SEAT				(photo)			120.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR							60.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS							40 60.00
M SUNDRY SUPPLY BODY PNL SEALANT							20.00
M SUNDRY Sundries							
M PANEL ASSY,RR DOOR,LH				1.00	803.00	23.00	618.31
M MLDG,R/DR WDO BELT LINE,LH				1.00	76.00	23.00	58.52
M TAPE,RR DOOR SASH,LH				1.00	29.00	23.00	22.33
M REGULATOR,R/DR WINDOW,LH				1.00	132.00	23.00	101.64
M MOTOR,R/DR PWR WDO RGLTR,R				1.00	391.00	23.00	301.07
M BRACKET,RR BUMPER,LH				1.00	28.00	23.00	21.56
M CLIP,RR BUMPER				4.00	4.00	23.00	12.32
M FACE,RR BUMPER				1.00	751.00	23.00	578.27
M UNPAINTED BODYKITS				1.00	1643.00	20.00	1314.40

Estimate

30/3/21, 2.00pm

Steve (LKK)

SURVEYOR NAME: 00-14 M

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: [Signature]

Confirm & accepted by

DATE: P/P, R/L, S/L

REMARKS: 7 days

Nett

8048.42

Total Payable

8,048.42

563.39

8,611.81

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ST0008 / CYCLE & CARRIAGE AUTOMOTIVE PTE LTD
DATE & TIME: 29/03/2021 15:49 (SGT)
REPORTED BY: TAN SHIEH YUEN
SESSION: 1 (29/03/2021 15:49 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 29/03/2021 15:49 (SGT)
Date of Accident 28/03/2021 18:50 (SGT)
Exact Location of Accident 1012 Upper Serangoon Rd, Singapore 534750
Additional Location Information 1012 UPPER SERANGOON RD S534750
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SME2357C
INSURED/POLICYHOLDER
Is company? No
Name Of Registered Owner ANG HWE KHENG
NRIC No SXXXX320I
Email Address HKANG2009@YAHOO.COM.SG
Mobile Phone No (Phone) +65-97116739
Alternative Phone No +65-97116739

VEHICLE PARTICULARS

Manufacturer Mitsubishi
Model Attrage
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 1193

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 1800109811-01
Cover Note Number -

DRIVER

Name of Driver ANG HWE KHENG
NRIC No SXXXX320I

Birth
Date of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

19/04/1968
Indoor
03/07/1987
33 YEARS AND 8 MONTHS
Female
(Phone) +65-97116739
+65-97116739
HKANG2009@YAHOO.COM.SG
126 SERANGOON AVENUE 3 #15-01

-
556126
Yes
-
No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Side Swipe
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?

No
2
No
-
Yes
4
No

PASSENGER 1

Name
Gender

ANG PING KUN
Male

PASSENGER 2

Name
Gender

CHON GET
Female

PASSENGER 3

Name
Gender

TUAN PAR DIM
Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?
If yes, against whom?

No
No
-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
No
No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SLJ8930T
Vehicle Manufacturer	Mini
Vehicle Model	Cooper
Vehicle Variant	-
Vehicle Colour	Gray
Vehicle Category	Private car
Name of Driver	VICKI WOO
Contact Number	(Phone) +65-81861171
Address	-
Address complement	-
Postcode	-
Insurance Company Name	AXA Insurance Pte Ltd
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

I was driving along Upper Serangoon Rd to pick up my parent & maid after our dinner at Heng Long Teochew Porridge. While filtering/ cut in towards ^{where} my parent waiting place, I accidentally hit a Mini Cooper parking at the roadside waiting. As a result, my rear left hand door and bumper was dented and scratched against the Mini Cooper driver side bumper. \$.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

CERTIFICATE OF INSURANCE

CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Ang Hwe Kheng
 Period of Insurance : 24 Sep 2020 To 23 Sep 2021
 Engine No. : 3A92UHG4358
 Chassis No. : MMBSTA13AJH003044

Vehicle No. : SME2357C
 Policy No. : 1800109811-01
 Endorsement No. :
 Issued Date : 05 Aug 2020

ABOUT THE COVER

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT
 Engine Capacity/Tonnage : 1,193.00 CC Sum Insured : Market Value First Year of Registration : 2018
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
 - b) Any other person who is driving on the Policyholder's order or with his/her permission.
- This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above Mileage Condition : Unlimited Mileage

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Ang Hwe Kheng - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708688
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504623050
 FULCOMICP2 - CORPORATE

22 UBI ROAD 4 FULCO BUILDING
 SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

AIGSGMOBILEAPP

1003523245/AC4