CS/AIG21004060/Eqf3

ASS. REC. BY: Steve A14	Controlly Sprace
ASS. REC. BY: OTOTO ASSI	GNMENT 17/1/17
From: Dale:	Veh No: SLM 88060 Yr Regn: 174/17 Type: (M.Ca) / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
Estimated Cost:	Truck / Trailer or
OD/TP/WS/JP RES/OD RES/EVA/INV/MY	Make: KIA (e141) c.c. 1591
To Inspect Vehicle No:	Colour A/C: Insured / Std / NI / N
ol	Sp.Reading : 853/4 T/Radio; Insured / Std / NI / N
Insured:	Eng/No:
Policy No. 2100506485	C/No: KAIAFX 411 MI- 5696918
Claims No. 7354967347SG	Gen, Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess: 300	Steering: Ingreer / Jammed / Leaked / Burnt or
(Client's Record)	Brakes Inorder / Jammed / Leaked / Burnt or
Make of Veh;	Modi: NII / S/Rin / STO A/Rim or
	Tyre Size: F: 205/55 R/6
(Policy Condition)	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Remark: The veh had commenced its N/S'-1' 10/S.	
repair at the time of inspection.	Rear
Bal. or Market Value:	rroni
IDAC Accident Rport: Consistent?: Yes or No	R/Bal,
GIA / PR Seen: Consistent?: Yes or No	UBall 2013/01
Est. Repairs: 11 days Res.: Yes or No	U.O.K. I HOTEL CINE IN CONCOR
Lum Sum: % 3 Val.: Yes or No	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
CA I REV I REP. I 24 HRS	Des. of Damages: Frt / Rear / C/3 / K/3 / S/5
Vehicle: IN/OUT	The U/C / Chassis frame / Body Structure affected due to collision
Dale / Yima Action / Instruction	,
30/03/21@4.37pm revert to AIG via Merimen	
31/03/21@2.50pm Kok Chong informed C/A via I	Merimen:
31/03/21@3.57pm Informed Don C/A & ex:\$300	
22/04/21@12.38pm confirmed with JoJo final fig \$	10506, 11 days (Red \$3684, 26%)
D.	ys Of Repair: 11
, , , , , , , , , , , , , , , , , , , ,	survey No. of Trip: 3 Survey Fee:
Fillal Koport	Transportation:
Add Fee:	: Sile Insp (\$)s + RS,_SI
	: Interview (\$) Protos
operationnel: MER-OD	: Tech. Invs (%) Officers
10506	: Meal and (%)
TOOO TOO TO TO TOO TO TOO TO TOO TO TOO TO T	. YOTAL



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTI	M	AT	ΓΕ
------	---	----	----

GST Reg No : MR-8500111-X

	ESTIMATE	UST meg	
g No : 199405410K		Owner Name & Vehicle Info	
Invoice Name & Address AIG Asia Pacific Insurance Pte.	Cust No/Name Reg No/Reg Date	/Hagley Nigel Tak-King SLM8806D / 17/04/201	
Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16	OR CLAIM DEPARTMENT Date In/Mileage	4 06214	
AIG BUILDING	Engine No	G4FGGH667636	
SINGAPORE 079120 Contact No 64191000	Make/Model Colour/Trim	KIA/CERATO K3 1.6 A EX MST METAL STREAM / WK SATURN BLACK	

		- Drinked	CSE	Operator		WIP No			
Account No	Terms	Date/Time Printed	OUD	247 / DonBong		31335			
AX00000	Credit	30/03/2021/ 13:11		Z47 / Bollbolly	Qty	Unit Price	Disc%		ount
		Description of Good	s / Services					11100	2000.00
PNT88000			2	MEI OF V	1100		i	1400	
DENELL AC	CIDENT DA	AMAGED PART ON FRONT	SUPPORT PA	NEL, 3-5 X	400				
FRONT BO	NNET, RH	FRONT FENDER, REPAIL	K KH FRUNT	DOOK,					100 0
REPAIR L	H FRONT F	FENDER							100.00
PNT88000		L DADIATOR AND A/COL	N CONDENSER	}					80.0
	ND INSTAL	LL RADIATOR AND A/CO	COMBENSE	`					
M SUNDRY	CAS CAS	AND CHECK A/CON SYS	TFM						2100.0
TOP OP A	/CON GAS	AND CHECK MY CON GIO		-	750			1400	2100.0
PNT98000	DE CDDAY	FRONT BONNET, FRONT	BUMPER, RE	front fender,	4 x 330			,,,,,	
PAINI WO	DOOR II	FRONT FENDER AND A	FFECTED POP	RTION	П			1,0	80.0
SUNDRY	, DOOK,	IL (2551	1100	2015			40	00.0
APPLY BOI	DY SEALAI	NT	5111	111116	5111(=				30.0
54900099					الله الله				50.0
CHECK WIL	RING AND	CHASSIS ELECTRICAL	SYSTEM					40	80.0
SUNDRY								1 70	-
PERFORM I	RUST PREV	VENTION							120.0
10028901		TOTAL AUGOL HOTHO	UT CCAN DD	1 TEST					
		SNOSTIC CHECK USING	HI-SCAN PRO	J IESI				l	
USING HI	-SCAN PRO) TEST							400.
33900099	/04/	DAMACES						l	
		RRIAGE DAMAGES							120.
WHEELALIG	NMENIBP	terize Full Wheel Al	ianment					1	
SUNDRY	ct compu	terize ruit wheel At	rgimerie					1	400.
	H EDONT	SPORT RIM SSW266							
SUNDRY	II I KONT .	51 OKT KITT 55 M2 55							30.
	FNFW RH	FRONT SPORT RIM INCL	UDING BALA	NCING				1 00	
SUNDRY	en							20	50.0
SUNDRIES		_						1	
CARRIER	ASSY-FRO	NT END MODULE $ egthinspace / B$	K		1.00		20.00		540.0
A RESERVOI	R & PUMP	ASSY-WASHER /	UK		1.00		20.00		100.0
M LAMP ASS					1.00	1707.00	20.00	1	1365.6

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTIMATE GST Reg No : MR-8500111-X

Reg No : 199405410K Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Make/Model	/Hagley Nigel Tak-King SLM8806D / 17/04/201			

	T	Date/Time Printed	CSE	Operator		WIP No		
Account No	Terms Credit	30/03/2021/ 13:11	OUD	247 / DonBong		31335		
LAX00000	Credit	Description of Goods			Qty	Unit Price	Disc%	Amount
			7 Services		1.00	34.00	20.00	27.20
M HINGE AS		,			1.00	34.00	20.00	27.20
M HINGE AS		-H -			1.00	1384.00	20.00	1107.2
M PANEL AS		/ 00 ING X AIA!			1.00	141.00		112.8
M PAD-HOOD					1.00	35.00	20.00	28.0
M ROD ASSY		X WI			1.00	65.00	20.00	52.0
M LATCH AS					1.00	28.00	20.00	22.4
M INSULATO		/ 00			1.00	435.00	20.00	348.0
M PANEL-FE	NUER, KH	STOP MICH X MM			1.00		20.00	10.4
M BRACKET-	FR BUMPE	R SIDE MTG,LH X MAI R SIDE MTG,RH / BK)		1.00	13.00	20.00	10.4
M BRACKET-	FK BUMPE			7	1.00	496.00	20.00	396.8
M RAIL ASS	T-FK BUM			ino a	1.00	114.00	20.00	91.2
M STIFFNER	FR BPK I	JMPER ENERGY X NA	2711	1100121	1.00	84.00	20.00	67.7
M ABSORBER	FRONT DI	IMPER A/INTAKE	2) []	11111111(21	1.00	91.00	20.00	72.8
M MOULDING	- FRUNI DI	PER UPR X MAI			1.00	29.00	20.00	23.
M CADMICH I	DANTATOD	GRILLE, UPR X MM			1.00	54.00	20.00	43.
M GARNISH-I	CADIATOR	TOP 1			1.00	328.00	20.00	262.
M RETAINER					2.00	1.00	20.00	1.
		- OR			1.00	633.00	20.00	506.
					1.00	55.00	20.00	44.
					1.00	6.00	20.00	4.
					1.00		20.00	26.
					1.00		20.00	192.
					1.00		20.00	25.
					1.00		20.00	304.
	LEIG-FR L	WK, KII > 01			1.00		20.00	18.
	CO COMDI	1			1.00	1330.00		1064.
M CROSSMEM		- j			1.00		20.00	224.
M STRUT ASS		n ´			1.00		20.00	43.
M BEARING-: M PAD-FRON		IIDP 1			1.00		20.00	33.
					1.00		20.00	74.
M INSULATO M LINK-STA		87			1.00		20.00	57.0
M GEAR ASS					1.00		20.00	665.0
II GEAR ASS	, JILLINI							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTIMATE

GST Reg No : MR-8500111-X

o Reg No : 199405410K	LOTHWATE	G51 Keg No : PIK-030011			
Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Engine No Make/Model	/Hagley Nigel Tak-King SLM8806D / 17/04/201			

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
		/ / / 12 11	QUD	247 / DonBong		31335		
LAX00000	Credit	Description of Goods			Qty	Unit Price	Disc%	Amount
M HUB ASSY M BEARING-F M RING-SNAF M KNUCKLE-F	FRONT WHE	EL HUB			1.00 1.00 1.00 1.00	150.00 131.00 11.00 350.00	20.00	120.00 104.80 8.80 280.00

Estimate

SURVEYOR NAME: Steve (LKK) 30/3/21, 2-30/14

SURVEYOR SIGNATURE: OD- MM AL

Extris - ?

REMARKS: P/P, M BLM

10 days

LKK Auto Consultants hence notify the Repairer of the following:		
Confirm SuiAccepted Dyart(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis	Nett 7% GST on 14098.00	14,098.00 986.86
No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Authorized signatory and company stamp	Total Payable	15,084.86

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SC1A213U0003 / CYCLE & CARRIAGE AUTOMOTIVE PTE LTD SCIAZI 300003 / CTULE & CARRIAGE AUTON ENTRY DATE & TIME: 30/03/2021 13:39 (SGT) SUBMITTED BY: TAN SHIEH YUEN SUBMITTED 31. 13.0 SINE 11 10EN VERSION: 1 (30/03/2021 13:39 (SGT))



SINGAPORE ACCIDENT STATEMENT

- 2. This norm must be completed by the nonleyholder and/or the Authorised Driver
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 3. Information provided most be as truting and accurate as possible. Any willul misrepresentation of witholding of mischange companies, policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the mission of Singapore (GIA) for archiving
 Any false reporting may be referred to the Police for Investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENTISTATEMENTS

30/03/2021 13:39 (SGT) Date of Submission 29/03/2021 17:20 (SGT) Date of Accident SLIP ROAD EXIT FROM SLE TO UPPER THOMSON RD **Exact Location of Accident** Additional Location Information Singapore Country/State of Loss

SLM8806D Vehicle Registration Number

INSURED/POLICYHOLDER

Is company? HAGLEY NIGEL TAK-LING Name Of Registered Owner SXXXX341I NRIC No NHAGLEY777@GMAIL.COM Email Address (Phone) +65-83639093 Mobile Phone No +65-83639093 Alternative Phone No

VEHICLE PARTICULARS

Kia Manufacturer Cerato Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Private car Vehicle Category Auto 1591

INSURANCE COMPANY

AIG Asia Pacific Insurance Pte. Ltd. Name of Insurance Company Type of Coverage Comprehensive Fleet Policy No Policy Number 2100506485-03 Cover Note Number

DRIVER

HAGLEY NIGEL TAK-LING SXXXX341I

<i>b</i>	
Pate of Birth	02/05/1966
Pate Of Birti	Indoor
	02/05/1987
priving experience	33 YEARS AND 10 MONTHS
conder	Male
Mobile Number	(Phone) +65-83639093
Alt. Phone Number	+65-83639093
Email Address	NHAGLEY777@GMAIL.COM
Address	193 JALAN LOYANG BESAR #04-03
Address complement	*
Postcode	506928
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	•
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
The state of the s	•
Insurance Company of Other Vehicle Owned by Driver	
GENERAL INFORMATION OF THE ACCIDENT	
	Collision - Head to Rear
Type of Accident	Raining
Weather Conditions	Wet
Road Surface	AACT
OTHER INFORMATION	
	No
Was any foreign vehicle involved in the accident?	2
Number of vobicles involved in the accident	No
Was anybody injured in the Accident?	-
to hospital by ambulance:	Yes
at an motorial or property (latilidueu :	1
Number of Desengers (Including Driver)	,
	Yes
soliciting/offering accident claims assistance?	
107/04	
DETAILS OF POLICE ACTION	
to the police?	No
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	•
If yes, against whom?	
CIRCUMSTANCES OF ACCIDENT	
REFER TO ATTACHMENT	
REFER TO ATTACHIMENT	taring ang pangang ang nggangan ang panggap ang ang ang ang ang panggapang ang panggapan isang ng
ATTACHMENT(S)	
the same of the sa	
Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera r	Yes
Was there any audio recorded?	No
LOSTALS OR OTHER	VEHICLE PROPERTY: 11
HOSTAICO OF COLLEGE	
Vehicle Registration Number	SGB46A
Vehicle Manufacturer	Toyota
Vehicle Model	Previa
Vehicle Variant	•
Vehicle Colour	

Private car

ZHOU YAN SONG

(Phone) +65-80282898

Vehicle Colour

Vehicle Category

Name of Driver

Contact Number
Address
Address complement

n_{strance} Company Name

Insurance Company Name

Insurance Of Damage

Nature Of Damage

Details of property damaged in accident

Details Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (CIA) for control of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

30/03/21 Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centr Personnel

Time Sketch Plan SLM880 SLE PLYOVER

n by conclude 17.70 one Tance down to
At roughly 17.20 pm I was driving down son roach.
Slip road Fxit from SLE to upper Thomson roach
FAT Red Btill doir
There was light drizzle but the road was very wet from ealier heavy (ain.
very wet from ealier heavy rain.
There was a Toyota Previa SOB 46A infront of me and we both were considerative going to cross the traffic light to go only upper Francon road. As we approached the Isalus the traffic light twined
me and we both were costing the
acing to cross the traffic light to go one
upper Thousan road. As we applicated
the traits the tractic light two cossed
an bed. The Toyota Previce had already stop.
upper Thomson road. As we approached the Iralits the tractic trant twined amber. The Toyota Previous had already crossed the white line and did an emergency stop.
the white line and did all emission left I immediately braked and turned left to avoid from. but my periodit hand corner of my car hat the Previous
to avoid from but in previous
corner of my car ni inc
left havel back.
I called Cand C for fow truck as my
mud gand was sited out up pel of
Thomson road and called the traffic
Thomson road while Eulice.
police. Police camo, and took
down the details
when the previou was upper Thomson road side
after about 15 mins a blue Golf GII
after arout 13 men stopped
1 1 2 9511 11/2 10 000
$0 \times 1 \times $
12d DUSSER LIT DW
They were the tractic police came.
letot when the

Declaration

We declare the foregoing particulars are true in every respect.

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: Hagley Nigel Tak-Ling

Period of Insurance

: 17 Apr 2020 To 16 Apr 2021

Engine No.

: G4FGGH667636

Chassis No. : KNAFX411MH5696968 Vehicle No.

: SLM8806D

Policy No.

: 2100506485-03

Endorsement No.

Issued Date

: 16 Mar 2020 The same barren and water

ABOUT THE COVER --------

Make/Model

: KIA Cerato K3 1.6 EX

Engine Capacity/Tonnage: 1,591.00 CC **Driver Restriction**

Sum Insured : Market Value

First Year of Registration : 2017

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*:

a) The Policyholder

Any other person who is driving on the Policyholder's order or with his/her permission

: NA

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") If You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience than 2 years' driving experience.

Age Condition

: All Age Condition

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

Hagley Nigel Tak-Ling - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1.Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

1.Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65064501
2.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Read Transport Act 1987 (Malayris), Bood Transport Act 1987 (Mala у шастно року м многи на Continuote от начиалостовности и ассолцание мин до рисуваль от до мого ventices (т d Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500709920

CYCLE & CARRIAGE - JANMAO

239 ALEXANDRA ROAD

SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

SSPCUE