

ASS. REC. BY: TanplihREF: CS/CTI 21004264/71.tfs.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 985K.

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: Ren.

Vehicle: IN / OUT

Veh No: SM T76/35Yr Regn: 2020 Jly.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Stonic 1.0 SX SR

C.C

998

Colour: Red

A/C: Insured / Std / NI / NA

Sp. Reading: 5704

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAD6811V26449427

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 31/3/21Survey held at CSC Ubi Rd 3Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

the owner of SMU502B and our Client agreed on private settlement.

submit preli report

Date/Time, File Pass to?



: Preli. Report



: Final Report

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.I. (P) _____

Days Of Repair: 11

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. Invs (\$ _____)



: Weekend (\$ _____)

Survey Fee:

Transportation:

Photo:

Others:

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Mr Srinivasan Ravi
	Reg No/Reg Date	SMT7613B / 16/07/2020
	Date In/Mileage	29/03/2021/ 5653
	Chassis No	KNAD6811VL6449427
	Engine No	G3LCLP056877
	Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim	BEG / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000018	Credit	29/03/2021/ 13:23	DS	303 / Renemer	64278				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
S	MIPNT88088	DIAGNOSTIC/SCANNING					✓		250.00
S	MIPNT88088	TO CHECK ALL LIGHTING/WIRING SYSTEM ON FRONT & REAR ACCIDENT AFFECTED AREAS					80.		100.00
S	MIPNT88088	TO REMOVE & RE-INSTALL RADIATOR & AC CONDENSER TO FACILITATE REPLACEMENT OF FRONT SUPPORT PANEL TO TOP UP AIRCON GAS & COOLANT					?		180.00
S	MIPNT88088	TO REPLACE RADIATOR GRILLE, FRONT BUMPER UPR & LWR, BRACKETS, CLIPS, FRONT REINFORCEMENT, FRONT SUPPORT PANEL, ETC -TO REPAIR FRONT BONNET STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS					640.		3840.00
S	MIPNT98088	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS (FRONT BONNET, FRONT BUMPER)					550.		1650.00
S	MIPNT88088	TO TRANSFER TAILGATE COMPONENTS & MECHANISM PARTS					320.		640.00
S	MIPNT88088	TO REPLACE TAILGATE GLASS					✓		300.00
S	MIPNT88088	TO INSTALL RIKECOOL SOLAR FILM ON TAILGATE GLASS					✓		220.00
S	MIPNT88088	TO APPLY SEALANT KIT ON NEW TAILGATE GLASS					✓		100.00
S	MIPNT88088	TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS					320.		640.00
S	MIPNT88088	TO REPLACE TAILGATE, REAR BUMPER, EXTN BUMPER, BRACKETS, CLIPS SENSOR, REFELCTOR, REINFORCEMENT, STAY, ETC -TO CUT& WELD REAR END PANEL -TO REPAIR LHR FENDER STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS					3200.		4480.00
S	MIPNT98088						1650.		2750.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Mr Srinivasan Ravi
	Reg No/Reg Date	SMT7613B / 16/07/2020
	Date In/Mileage	29/03/2021/ 5653
	Chassis No	KNAD6811VL6449427
	Engine No	G3LCLP056877
	Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim	BEG / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000018	Credit	29/03/2021/ 13:23	DS	303 / Renemer	64278			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS (TAILGATE,EXTN BUMPER,LHR FENDER,REAR END PANEL)								✓ 280.00
S	MIPNT88088	OPC APPLIATION TO BREAK & RESEAL FRONT & REAR LICENSE PLATE						✓ 100.00
S	MIPNT88088	FRONT & REAR LICENSE PLATE WITH CASING						ne ✓ 50.00
M	SUNDRY	C&C LOGO						ne ✓ 32.00
M	KS 86318 3R 500	ORNAMENT - KIA NO. 1			1.00	32.00	0.00	ne ✓ 32.00
M	KS 86350 H8 410	GRILLE-RADIATOR			1.00	324.00	0.00	de ✓ 324.00
M	KS 86511 H8 400	UPR COVER-FR BUMPER			1.00	476.00	0.00	de ✓ 476.00
M	KS 86512 H8 400	LWR COVER-FR BUMPER			1.00	367.00	0.00	de ✓ 367.00
M	KS 86565 H8 400	SKID PLATE-FR BUMPER			1.00	55.00	0.00	de ✓ 55.00
M	KS 86522 H8 400	MLDG-FR BUMPER A/INT			1.00	61.00	0.00	de ✓ 61.00
M	KS 86560 H8 400	LWR GRILLE-FR BUMPER			1.00	96.00	0.00	de ✓ 96.00
M	KS 86520 H8 400	ABSORBER-FRONT BUMPE			1.00	98.00	0.00	de ✓ 98.00
M	KS 64900 H8 400	BEAM COMPLETE-FR BUM			1.00	544.00	0.00	de ✓ 544.00
M	KS 0G032 50 037A	FR CLIP- BUMPER			10.00	2.00	0.00	ne ✓ 20.00
M	KS 86513 H8 400	LH BRACKET-FR BUMPER			1.00	13.00	0.00	de ✓ 13.00
M	KS 86514 H8 400	RH BRACKET-FR BUMPER			1.00	13.00	0.00	de ✓ 13.00
M	KS 73700 H8 400	PANEL ASSY-TAIL GATE			1.00	1010.00	0.00	de ✓ 1010.00
M	KS 87110 H8 130	GLASS ASSY-TAIL GATE			1.00	395.00	0.00	ne ✓ 395.00
M	KS 86114 3D 000	PAD-W/SHLD GLASS			12.00	2.00	0.00	ne ✓ 24.00
M	KS 87114 3K 000	STOPPER-RR WINDOW GL			2.00	4.00	0.00	ne ✓ 8.00
M	KS 86114 2L 000	PAD-WINDSHIELD			2.00	17.00	0.00	ne ✓ 34.00
M	KS 86320 1W 250	LOGO ASSY - KIA SUB			1.00	51.00	0.00	ne ✓ 51.00
M	KS 86310 H8 400	EMBLEM-STONIC			1.00	26.00	0.00	ne ✓ 26.00
M	KS 86317 H8 400	EMBLEM-TURBO G.D.I			1.00	38.00	0.00	ne ✓ 38.00
M	KS 92501 D9 000	LAMP ASSY-LICENSE PL			2.00	119.00	0.00	X 238.00
M	KS 86681 H8 400	LH SIDE MOULDING ASS			1.00	152.00	0.00	ov ✓ 152.00
M	KS 86682 H8 400	RH SIDE MOULDING ASS			1.00	152.00	0.00	de ✓ 152.00
M	KS 86610 H8 410	LWR COVER-RR BUMPER			1.00	366.00	0.00	de ✓ 366.00
M	KS 86613 H8 400	LH BRACKET ASSY-RR B			1.00	27.00	0.00	ne ✓ 27.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Mr Srinivasan Ravi
	Reg No/Reg Date	SMT7613B / 16/07/2020
	Date In/Mileage	29/03/2021/ 5653
	Chassis No	KNAD6811VL6449427
	Engine No	G3LCLP056877
	Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim	BEG / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
F0000018	Credit	29/03/2021/ 13:23	DS	303 / Renemer	64278	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
M KS 86614 H8 400		RH BRACKET ASSY-RR B	1.00	27.00	0.00	X 27.00
M KS 86660 H8 410		SKID PLATE-RR BUMPER	1.00	122.00	0.00	fn ✓ 122.00
M KS 95720 H8 100		OTR ULTRASONIC SENSO	2.00	189.00	0.00	nu ✓ 378.00
M KS 95720 H8 110		INR ULTRASONIC SENSO	2.00	189.00	0.00	nu ✓ 378.00
M KS 86692 H8 400		UNDER SIDE COVER-RR	1.00	62.00	0.00	de ✓ 62.00
M KS 92405 H8 400		LH LAMP ASSY-REAR FO	1.00	111.00	0.00	an ✓ 111.00
M KS 92406 H8 410		RH LAMP ASSY-REAR FO	1.00	111.00	0.00	X 111.00
M KS 91890 H8 060		WIRING HARNESS-BWS E	1.00	245.00	0.00	? 245.00
M KS 86631 H8 410		BEAM-RR BUMPER	1.00	419.00	0.00	bt ✓ 419.00
M KS 86634 H8 400		LH BRACKET-RR BEAM L	1.00	7.00	0.00	? 7.00
M KS 86635 H8 400		RH BRACKET-RR BEAM L	1.00	5.00	0.00	? 5.00
M KS 86633 H8 400		BRACKET-RR BUMPER UP	2.00	7.00	0.00	? 14.00
M KS 95420 F9 100		ANTENNA ASSY-SMARTKE	1.00	32.00	0.00	? 32.00
M KS 86641 H8 400		LH STAY-RR BUMPER	1.00	55.00	0.00	cu ✓ 55.00
M KS 86642 H8 400		RH STAY-RR BUMPER	1.00	55.00	0.00	X 55.00
M KS 0G032 50 037A		RR CLIP- BUMPER	10.00	2.00	0.00	ng ✓ 20.00
M KS 92401 H8 500		OTR LAMP ASSY-REAR C	1.00	654.00	0.00	? 654.00
M KS 69100 H8 400		PANEL ASSY-BACK - photo	1.00	345.00	0.00	bt ✓ 345.00
M JJMZ313950		COOLANT	4.00	26.00	0.00	X 104.00
Z	NOTES					
ACCIDENT ON 27/03/2021 ALONG KPE EXIT OF PIE (CHANGI)						
OWNER CLAIMING THIRD PARTY						
TP#: SMU520B TP INS: CHINA TAIPING						
Taufik 97495449 / 6256561						
WP						
31/3/21 @ 1015						
taufik@lkhauto.com						
10-11 days						
* Resurvey before painting.						
Confirm & accepted by			<div><div>LKK Auto Consultants hence notify the Repairer of the following:</div><ul style="list-style-type: none">To resurvey before/after spray paintingTo display damaged part(s) during resurveyParts prices are subject to confirmationThird party survey is on a "Without Prejudice" basisNo illegal modification(s) is allowed<div>Part(s) elementary item(s) must be resurveyed and is subject to final approval from Insurance Company</div><div>Labour</div><div>Standard Menu</div><div>Acknowledged by Repairer</div><div>Signature</div><div>Others (Lub, etc)</div><div>Sundry</div><div>Total (w/o GST)</div></div>			
			7,764.00			
			0.00			
			0.00			
			15,530.00			
			0.00			
			50.00			
Authorized signatory and company stamp			23,344.00			

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	29/03/2021 10:53 (SGT)
Date of Accident	27/03/2021 18:45 (SGT)
Exact Location of Accident	KPE, Singapore
Additional Location Information	KPE EXIT OF PIE (CHANGI):EXIT 13
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMT7613B
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	SRINIVASAN RAVI
Passport No/FIN	GXXXX745L
Email Address	RAVIKSRINIVASAN@GMAIL.COM
Mobile Phone No	(Phone) +65-91193057
Alternative Phone No	+65-91193057

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Stonic
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	998

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2070106271
Cover Note Number	-

DRIVER

Name of Driver	SRINIVASAN RAVI
Passport No/FIN	GXXXX745L

Date Of Birth	01/07/1983
Occupation	Indoor
Date Of Driving Pass	01/06/2011
Driving experience	9 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91193057
Alt. Phone Number	+65-91193057
Email Address	RAVIKSRINIVASAN@GMAIL.COM
Address	29 JALAN SEMPADAN #04-04 VILLA MARINA
Address complement	-
Postcode	457402
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMU520B
Vehicle Manufacturer	Mercedes
Vehicle Model	E350
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	GUAN HONGGUI
Contact Number	(Phone) +65-84941868
Address	-
Address complement	-

Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	3RD CAR
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SGG4991T
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	WANG GUIDONG
Contact Number	(Phone) +65-88700581
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	1ST CAR
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Ravi

29/03/2021 08:31
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

t/n
Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

There was a traffic jam at Exit 13 to KPE from PIE Changi. I took the exit and stopped behind car in front of me (SG64991T). While both these cars were stationary, the car at fault came from behind and rear ended me due to not slowing down (SM0520B). The force pushed my car (SM7613B) forward and I hit the car in front (SG64991T as stated).

My car has severe damage on the back, & some scratches on the front. The entire incident has been captured on my video through front & rear dash cam.

Declaration

We declare the foregoing particulars are true in every respect.

Rain

29/03/2021

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Edm

Witnessed by Reporting Centre Personnel



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 - 17:00
UEN: S665500206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:


Original Report No : SC1A213T0001 Vehicle Registration No: SMT 7613 B
Name (as shown in NRIC) : SRINIVASAN RAVI NRIC/FIN/Passport No : _____
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore ()
Contact (Tel) : _____ Mobile No.: 9119 3057
Email Address : _____
Date of Accident : 27/03/2021 Time of Accident: 18:45
Place of Accident : KPE Exit of PIE (CHANGI) Exit 13
Insurance Company: AIG

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amend on TP vehicle Registration Number (Property 1)

Policyholder / Driver's Signature
Date:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date: 29/03/2021