



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:LYNN		Ref: CC4/ASM21004078/Aps3q2 Date: 01/12/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMW 5961T	Veh. Inspected	SLC 9260Z
Policy No.	P2416705	Coverage (\$)	0.00
Claim No.	S1M036OR	Excess (\$)	0.00
Assign From		Assign Date	30/03/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11117113	Colour	SILVER
Odometer	179153 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	TOURADOR	6 mm
L/H Front Tyre	215/55 R17	TOURADOR	6 mm
R/H Rear Tyre	215/55 R17	TOURADOR	6 mm
L/H Rear Tyre	215/55 R17	TOURADOR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/03/2021	Inspection Date	06/04/2021
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	