ASS. REC. BY: Taufill - REF: CS3/ASM 21004083/ TIC. ASSIGNMENT JSW 8531 Yr Regn: 1 Veh No: Dale: Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / From: Estimated Cost: Truck / Trailer or OD (TP) WS I TP RES I OD RES I EVA I INV I MV 135 Insured / Std / NI / NA To Inspect Vehicle No: Colour T/Radio: Insured / Std / NI / NA at Workshop m/s Sb.Reading Eng/No: Insured: C/No: Gen. Cond: Good Fair / Poor / Burnt Policy No. Steering: Inorder | Jammed / Leaked / Burnt or Claims No. Excess: Brake: Inorder) Jammed / Leaked / Burnt or Sum Insured: Modi: NH /S/Rim / STD A/Rim or (Client's Record) Make of Veh: Tyre Size: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM! / (Policy Condition) OIS Remark: The veh had commenced its Margas TOYOTYOKO or repair at the time of inspection. Front R/Bal. Bal, or Market Value: R/Bal. Consistent? : Yes or No UBal. IDAC Accident Rport: ∐Bal. Consistent? : Yes or No D.O.I. GIA / PR Seen: D.O.A. Res.: Yes or No days Est. Repairs: Survey held at 3 Val.: Yes or No Des. of Damages : Frt V Rear I OK I MIS I UIC I Rooftop or Lum Sum: CA | REV | REP. | 24 HRS Vehicle: IN/OUT The U/C / Chassis frame / Body Structure affected due to collision. Person Contacted: Action / Instruction Date / Time have no GIA, NO DETAILS MALAYSIA VEHICLE SUBMIT PRS REPORT JSW8531 range \$3000-4000, 6days Days Of Repair: : Prell. Report Date/Time, File Pass to? Survey Fee: Resurvey No. of Trip: : Final Roport Transportation: Date/Time, File Return to? S + RS.__SI Add Fee: : Site Insp (\$ Photos Interview (\$ Chiners : Tech. Invs (\$ Repert Formar: Weelfend (\$ Lunap Som [LBJ: Ca TENTAL