

ASS. REC. BY:

REF: CS3/CTI21004156/Gqf3

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): PAULINE THAM of CTI Date/Time: 31/3/2021 10:29 AM

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 1326L Insured: GBH 5391Y

at Workshop m/s Teamwork Garage Pte Ltd Tel: 68442475

of 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi

Policy No: DMCVSNW00051542001 Claim No: SNM21D201788C02

Sum Insured: Excess:

Make of Veh: D.O.A. 26/03/2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 31-03-21 4.32P.M

Person Contacted: DARREN

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SLS 1326L - X
	GBH 5391Y- NA/CTI21003979/Y DOA:26/03/2021