

ASS. REC. BY:

600
PRS

ASSIGNMENT

AXA

(2025)

From:

Date:

Veh No:

TBE 6204P

Yr Regn:

02 Jul 2010

Estimated Cost:

Type: M.Cdr / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

Yamaha T135 cc 135

at Workshop m/s

Colour:

red

A/C: Insured / Std / NI / NA

of

Sp. Reading

35727

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

54P302521

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In Order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In Order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F: 70/80-17

R: 70/90-17

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Bal. or Market Value:

\$5000

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Front

Rear

R/Bal.

4 mm

R/Bal.

4 mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

01-04-21

Survey held at

W/S

3:35pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rebate : 1849

\$2000 - \$3000

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Wash (\$

Survey Fee:

Transportation:

3 + RS. SI

Photos

Other:

Report Form

Lump Sum / Other

TOTAL