Our Ref:

Dear Sir/Madam

CT0321/SHA7743T/CK(st)

Date:

29.04.2021



CHINA TAIPING INSURANCE CO (S)PTE L 3 ANSON ROAD #16-00 Singapore 079909

Attn : Motor Claims Department

Without Prejudice

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

Mainline +65 6383 6280 Facsimilie +65 6280 9755

www.cdge.com.sq

Company Registration No: 199506048W

### ACCIDENT ON 25.03.2021 INVOLVING SHA7743T & XE 316D ALONG TAMPINES AVE 10 AFTER AVE 3

We are the authorised repair workshop for Comfort Transportation Pte Ltd , the owner of vehicle No SHA7743T, which was involved in the captioned accident with your insured vehicle No XE 316D.

The vehicle owner and the taxi hirer/driver concerned have requested and authorised us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage of the vehicle.

As the accident was caused by the negligent act of your insured driver, we are submitting these claims for your consideration on behalf of the claimants:

#### Workshops

205 Braddell Road Singapore 579701

> Loyang 59 Loyang Drive

Singapore 508969

Sin Ming 383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

## Taxi Owner's Claim:

1. Cost of Repairs		S\$	7,648.06
2. Loss of Rental	6 days x S\$ 125.19	S\$	751.14
3. Survey Report Fee		S\$	0.00
4. LTA Search Fee		S\$	0.00
5. GIA / Police Report Fee		S\$	2.00
6. Others		S\$	0.00

	[E&OE]	<b>Total Claims</b>	S\$	8,881.20	
<ol> <li>Loss of Income</li> <li>Others</li> </ol>	6 da	ys x \$\$ 80.00	S\$ S\$	480.00 0.00	
Hirer's Claim :					

A copy each of the following supporting documents marked [X] is enclosed:

[X]	Original Repair Bill	[X]	Letter of Authority from Owner/Hirer/Operator
[X]	GIA/Police Report(s)	[X]	Rental Rate Letter
M	LTA/GIA Search Slip(s)	[X]	Downtime/Mileage Record
[']	Survey Report / Bill	[]	Witness Statement / Accident Scene Photo(s)
[]	Driver's IC/DL/VL / Road	Tax / Log	g Card / Certificate of Insurance
[]	Tow Chit / PIR / Hirer's IF	RAS / Oth	ners:

Kindly look into the matter and let us hear from you on the settlement of our clients' claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours sincerely Catherine Koh **CDGE Claims Department** 

DID: 62148733

FAX: 62141843

Email: catherinekoh@cdge.com.sg

This is a computer-generated letter. No signature is required.



A member of

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING Hyundai Ioniq SHA7743T , XE316D

ON 25-Mar-21 13:45

**ALONG** 

**TAMPINES AVE 10 AFTER AVE 3** 

I / We

LIM CHEE HONG

(Hirer) NRIC No .:

SXXXX990A

and/or

(Relief) NRIC No.: SXXXX990A

Taxi Number

**SHA7743T** 

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of earning (Pending successful recovery), loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

25-Mar-2021

Name of Hirer

LIM CHEE HONG

Hirer NRIC

SXXXX990A

Signature:

Address

174 LORONG 1 TOA PAYOH #06-12...

310174

Contact No.

81122515



8010012

# GST REG. NO. M2-8921817-3

# ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
205 Braddell Road Singapore 579701 383 Sin Ming Drive Singapore 575717

383 Sin Ming Drive Singapore 575717 7 Sungei Kadut Way Singapore 728791

COMPANY REG. NO.: 199506048W Page: 1

TAX INVOICE

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE SG 079909

CONTACT NO: 62222366

Description: 3P 25.03.2021

VEHCLE NO SHA7743T INV. NO/DATE 91555866 27.04.2021

MAKE HYUNDAI JOB NO. 305460503

MODEL IONIQ(G3)

ODOMETER READING

**DATE OF REG** 30.09.2020

DATE/TIME IN 25.03.2021 14:10

CHASSIS CODE

KMHC851CVLU189609

S/No	Part No.		Qty	Unit Price	%Disc	Net
PART	REQUISITION					
0001	04-01-0104-2256	PANEL ASSY-TAIL GATE#	1	2,480.40	20.00	1,984.32
0002	04-01-0104-2270	EMBLEM-HYBRID	1	24.30	20.00	19.44
0003	04-01-0104-2271	EMBLEM-IONIQ	1	31.30	20.00	25.04
0004	04-01-0104-2175	SYMBOL MARK-H	1	28.00	20.00	22.40
0005	04-01-0101-0111	BUMPER COVER CLIP REAR	10	2.20	20.00	17.60
0006	28-01-9999-2025	APP LOGO REAR BONNET CTPL	1	40.00	0.00	40.00
0007	28-01-0103-0006	REAR BOOT TEL NUMBER CTPL*	1	30.00	0.00	30.00
0008	28-01-0103-0005	REAR BOOT LOGO CTPL	1	30.00	0.00	30.00
0009	04-01-0104-2282	COVER-RR BUMPER#	1	459.40	20.00	367.52
0010	04-01-0104-2533	MOULDING ASSY-RR BUMPER CTR	1	451.25	20.00	361.00

<sup>1)</sup> WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTES PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TEST OWNERS' RISK.

#### ComfortDelGro Engineering Pte Ltd

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010012	91555866	7,648.06	

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

<sup>2)</sup> CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS, OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCI IN GOOD ORDER.

<sup>3)</sup> INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND DIVIND TO COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR PERIOD OF DEFAULT.

<sup>4)</sup> PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OF DISCREPANY WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE GUSTOMER, THE COMPANY WILL TREAT THIS INVOICE CORRECT AND BINDING.



# GST REG. NO. M2-8921817-3

# TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
205 Braddell Road Singapore 579701 383 Sin Ming Drive Singapore 575717

COMPANY REG. NO.: 199506048W Page: 2

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE SG 079909

CONTACT NO: 62222366

VEHCLE NO SHA7743T

INV. NO/DATE 91555866 27.04.2021

MAKE HYUNDAI

JOB NO. 305460503

MODEL IONIQ(G3)

ODOMETER READING

DATE OF REG 30.09.2020

DATE/TIME IN 25.03.2021 14:10

CHASSIS CODE KMHC851CVLU189609

S/No	Part No.		Qty	Unit Price	%Disc	Net
0011	09-01-9999-0068	REVERSE SENSOR ASSY*	1	180.00	0.00	180.00
0012	04-01-0104-2346	PANEL ASSY-BACK	1	532.00	20.00	425.60
0013	04-01-0104-2288	BEAM-RR BUMPER	1	394.80	20.00	315.84
0014	04-01-0104-2700	LAMP ASSY-REAR COMB INSIDE RH#	1	794.40	20.00	635.52
0015	04-01-0104-2699	LAMP ASSY-REAR COMB INSIDE LH#	1	794.40	20.00	635.52
0016	04-01-0104-2257	GLASS ASSY-TAIL GATE LOWER#	1	584.90	20.00	467.92
			SUB-TOTAL	:		5,557.72
JOB N	IATURE					
0001	PB	PANEL BEATING		750.00		750.00
0002	SP	SPRAYPAINT CHARGE		750.00		750.00
0003	17-01 EASONABLE PE	CHECK ALL LIGHTING		30.00		30.00

# ComfortDelGro Engineering Pte Ltd

Head Office: 205 Braddell Road Singapore 579701

ACCOL	JNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
81	010012	91555866	7,648.06	

Kindly note that no receipt shall be issued unless requested.

**CUSTOMER'S COPY** 



# ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
45 Pandan Road Singapore 609286
383 Sin Ming Drive Singapore 575717
7 Sungei Kadut Way Singapore 728791
320 Ubi Road 3 Singapore 408649

# GST REG. NO. M2-8921817-3

# TAX INVOICE

COMPANY REG. NO.: 199506048W Page:

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE SG 079909

CONTACT NO: 62222366

VEHCLE NO SHA7743T

INV. NO/DATE 91555866 27.04.2021

MAKE HYUNDAI JOB NO. 305460503

MODEL IONIQ(G3)

ODOMETER READING

**DATE OF REG** 30.09.2020

DATE/TIME IN 25.03.2021 14:10

CHASSIS CODE KMHC851CVLU189609

S/No	Part No.		Qty	Unit Price %Disc	Net
0004	20-00	TUFF COAT ON AFFECTED PARTS.		30.00	30.00
0005	20-22	REMOVE/REFIX REVERSE SENSOR		30.00	30.00
			SUB-TOTAL	:	1,590.00
		Items t	total		7,147.72
		Add GST	r @	7.000 %	500.34
		Invoice	e amount		7,648.06

Issued by : KATHERINETAN 27.04.2021 14:35:12 Repair type : CLSO/57/57 Payment Type/Term: /Credit 30 days

#### ComfortDelGro Engineering Pte Ltd

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010012	91555866	7,648.06	

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: (

CT21030435

Date: 27 April 2021



# TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

25/03/2021 @ 13:45 hrs

ALONG

TAMPINES AVE 10 AFTER AVE 3

INVOLVING

XE316D

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHA7743T (the "Taxi"). The Taxi was hired to LIM CHEE HONG IC NO SXXXX990A a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$125.19 per day (inclusive of GST).

Please be advised that the Taxi was insured with **AXA Insurance Singapore Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Philip Chia Manager, Fleet Safety

This is a computer generated letter. No signature is required.

	T) CHENTED (TI				MILEAGE	(בויייור) שב ואיוב זט פרוטטה	(11111) DI 10
MILEAGE TRAVELLED	HOURS OF EACH	DATE	NAME OF DRIVER	MILEAGE READING 9	TRAVELLED 120 (KM)	FROM	TO
(KM)	A TILL	19/3	A. P \$ 0.9	26777	877	3.50	150
3000	1	20/2	7.7	4359	132	0845	5441
010	0071 716	20/2	4	57 × 80	127	4.00	3.05
	1	21/2	4	500 000 t	カニ	3845	1415
706 427		21/2	A. C.	22677	822	3.30	01.11
06 (40		22/2	200	00 th	951	0845	1500
622	2.1.0/1.8 ADIA 1500	2,812	N. 23/3 7 040	7-7-2	135	3.15	1015
100	(C)(1)/1			1 1 1			
2 1 5	,	272		2	97743T	1400	( *
0 0000 551	15 10 (	80/2/08	1 meister	Chai		\	1600
7	25	10/0/01			No.	X	
3997 (20	李						

**INSURER ENQUIRY** 

# Find insurer

Vehicle reg. no.

XE316D

**Date of Accident** 

25/03/2021

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance China Taiping Insurance (Sing...

Period of Insurance \_\_\_\_\_\_\_23/01/2021 - 22/01/2022

Requested By Por Moy Juan (COMFORTDELG...

Requested Date \_\_\_\_\_\_\_25/03/2021 15:11

Payment details

Request Amount: **\$\$1.87** 

GST Amount: \$\$0.13

Total Amount Due (GST Inclusive): **\$\$2** 

**General Insurance Association** 

Records Management Centre

GST Registration No: M400017735

8MA 7743 T