

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 29.03.2021

Time: 13:07:11

Page: 1

LKK -

China Taiping
CLIS

B

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305460878
 REGN NO : SHB6220L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 05.01.2017
 DATE/TIME IN : 29.03.2021 09:20
 ACCIDENT DATE : 28.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	FRT BUMPER	1	1,052.20	20.00	841.76	de	
0002 04-01-0103-2164-A	RADIATOR GRILLE	1	1,480.00	20.00	1,184.00	one	
0003 04-01-0103-2175-G	RADIATOR GRILLE EMBLEM	1	129.50	20.00	103.60	we	2661.70.
0004 FNPS	FRT NO PLATE W/TRIM COVER	1 N	55.00		55.00	one	20% - 2129.36 5N55
						SUB-TOTAL :	2,184.36

JOB NATURE

0000 PB	PANEL BEATING	300.00	280	
0001 SP	SPRAYPAINT CHARGE	300.00	250	530.
		SUB-TOTAL :	600.00	

TOTAL : 2,784.36 2714.36

MVA NAME & SIGNATURE
 DATE :

SURVEYOR NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO

CLIS 2150
 2 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Taiping 97425749
 21/3/21 @ 4pm
 02 days
 Resurvey after repair
 Taiping @ lkkauto.com