

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI21004188/Utf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	С	Date:	09/04/2021	
			C	Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJA 5752G	Veh. Inspected		SGN 7554R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10009637/JM	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		31/03/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA WISH (A)	c.c		1794	
	Engine No.	HIDDEN	Year of Reg.		2006	
	Chassis No.	ZNE100315206	Colour		BLACK	
	Odometer	187512 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	FALKEN		6 mm	
	L/H Front Tyre	205/55 R16	FALKEN		6 mm	
	R/H Rear Tyre	205/55 R16	FALKEN		6 mm	
	L/H Rear Tyre	205/55 R16	FALKEN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	31/03/2021	Inspection Date		01/04/2021	
	Survey held at	PROFI AUTOMOTIVE				
		BLK 10 KAKI BUKIT ROAD 2 #01-03 FIRST EAST CENTRE SINGAPORE 417868				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: