

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



C INCOME INSUE	PANCE CO-OPERATIVE LTD	Ref:	NS/INC21004253/0	Otcn2
INTO INCOME INCOMANCE CO-OF ENATIVE ETD THE INCOME				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			04-05-2021	
		Code:	INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKB 3685M	Veh. lı	nspected	SHB 853A
Policy No.		Cover	age (\$)	0.00
Claim No.	MT/1129808-001	Exces	s (\$)	0.00
Assign From		Assig	n Date	25/03/2021
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS 4	c.c		1798
Engine No.	HIDDEN	Year o	f Reg.	2017
Chassis No.	JTDKB3FU903572536	Colou	r	MAROON
Odometer	382793	Steeri	ng	IN ORDER
Brakes	IN ORDER	Modifi	cation	SPORTS RIM
General	FAIR			
3. Conditions of Tyres				
	Size	Make		Balance
R/H Front Tyre	195/65 R16	SAILUN	N .	6 mm
L/H Front Tyre	195/65 R16	SAILUN		6 mm
R/H Rear Tyre	195/65 R16	SAILUN		6 mm
L/H Rear Tyre	195/65 R16	SAILUN	l .	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/03/2021	Insped	tion Date	25/03/2021
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD			
60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705				
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				
	Insured Veh. Policy No. Claim No. Assign From Make & Model Engine No. Chassis No. Odometer Brakes General R/H Front Tyre L/H Front Tyre L/H Rear Tyre L/H Rear Tyre THE VEHICLE SU DAMAGES SEE D Accident Date Survey held at A)THE INSPECTICE B)IN ACCORDANG	Policy Particulars Insured Veh. SKB 3685M Policy No. Claim No. MT/1129808-001 Assign From Vehicle Particulars Make & Model TOYOTA PRIUS 4 Engine No. HIDDEN Chassis No. JTDKB3FU903572536 Odometer 382793 Brakes IN ORDER General FAIR Condition Size R/H Front Tyre 195/65 R16 L/H Front Tyre 195/65 R16 L/H Rear Tyre 195/65 R16 L/H Rear Tyre 195/65 R16 L/H Rear Tyre 195/65 R16 ACCIDENT SUSTAINED DAMAGES AT THE FROM DAMAGES SEE DETAILS. General Accident Date 23/03/2021 Survey held at SMRT AUTOMOTIVE SERVICES 60 WOODLANDS INDUSTRIAL Rear A)THE INSPECTION WAS CONDUCTED ON A"WIT B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE Estimate Inspection of the service of the	Policy Particulars: - THIRI Insured Veh. SKB 3685M Veh. In Policy No. Cover. Claim No. MT/1129808-001 Exces Assign From Assign Vehicle Particulars & Make & Model TOYOTA PRIUS 4 C.C Engine No. HIDDEN Year of Chassis No. JTDKB3FU903572536 Colour Odometer 382793 Steerin Brakes IN ORDER Modifications of Size Make R/H Front Tyre 195/65 R16 SAILUN L/H Front Tyre 195/65 R16 SAILUN L/H Rear Tyre 195/65 R16 SAILUN SECURATION OF DESCRIPTION OF DESCRIPTIO	RAS BASAH ROAD OI NTUC TRADE UNION HOUSESINGAPORE 56 Code: INC4 Policy Particulars: - THIRD PARTY CLAIM Insured Veh. SKB 3685M Veh. Inspected Policy No. Coverage (\$) Claim No. MT/1129808-001 Excess (\$) Assign From Assign Date Vehicle Particulars & Condition Make & Model TOYOTA PRIUS 4 C.C Engine No. HIDDEN Year of Reg. Chassis No. JTDKB3FU903572536 Colour Odometer 382793 Steering Brakes IN ORDER Modification General FAIR Conditions of Tyres R/H Front Tyre 195/65 R16 SAILUN L/H Front Tyre 195/65 R16 SAILUN L/H Front Tyre 195/65 R16 SAILUN L/H Rear Tyre 195/65 R16 SAILUN Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS. General Information Accident Date 23/03/2021 Inspection Date Survey held at SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 Remarks A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED R